





report date: 2024-03-29

General information

Make	HYUNDAI
Model	IX35 CRDI STYLE
Colour	White
Year of manufacture	2013
Top speed	108 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	260 Nm at 2.750 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	58.9 mpg
Consumption combined	48.7 mpg
CO2 emission	139 g/km
CO2 label	E



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-05-24

Pictures 15

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-05-31
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	10
Total items failed	5

MOT #10	2023-05-22 10:15
MOT test number	735170496941
Result	✓ Passed
Next expiry date	2024-05-31

MOT #9		2022-05-25 09:12
MOT test	number	427090555780
Result		✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Nail in tyre	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

CarCheck.co.uk page 3/12



EY63CXZ

report date: 2024-03-29

MOT #8 2022-05-25 09:12 **MOT** test number 132265040195 Result × Failed Pass with rectification Nearside Front Headlamp light intensity severely reduced (4.1.4 (a)) Pass with rectification Offside Headlamp aim too high (4.1.2 (a)) Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Pass with rectification Nearside Headlamp aim too high (4.1.2 (a)) **Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Advice Nearside Rear Nail in tyre

MOT test number

Result

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #6 2020-08-31 12:22

MOT test number 106956997493

Result ✓ Passed

MOT test number

Result

Fail Offside Front Anti-roll bar insecurely attached (5.3.3 (a) (i))

Fail Nearside Front Track rod end seriously misaligned (2.1.3 (e))

CarCheck.co.uk page 4/12



MOT #2

EY63CXZ report date: 2024-03-29

2017-08-03 09:03

MOT #4	2019-08-23 14:45
MOT test number	180769406403
Result	✓ Passed
MOT #3	2018-08-30 12:30
MOT test number	127459992804
Result	✓ Passed
Minor Nearside Front Windscreen wiper blade defective (3.4 (b) (i))	

MOT test number	360828356513
Result	✓ Passed
MOT #1	2016-08-15 14:12
MOT test number	592861693801
Result	✓ Passed

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 June
Days left	33
MOT expiry date	31 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

· ·		
For how long did the current and previous owner(s) have this HYUNDAI? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.		NDAI

	More info	>
Plate changes		
See in this check if this HYUNDAI had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	OK NEW	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courts at info	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-09-01
Last registration	2023-05-22
Complete history	See info



2013-09-01	23 mi
2016-08-15	29.588 mi
2017-08-03	36.983 mi
2018-08-30	46.471 mi
2019-08-23	60.954 mi
2020-08-31	76.156 mi
	11.777 es
	2016-08-15 2017-08-03 2018-08-30 2019-08-23

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	90%
Children	88%
Pedestrian	54%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1820 mm
Height	1660 mm
Length	4410 mm
Wheel base	2640 mm
Kerb weight	1537 kg
Max. allowed weight	1940 kg

Additional information

Fuel tank capacity	58 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 p.	age 12/12

Number of axles 2

Engine number D4FDDZ186080