




report date: 2024-03-28

## General information

Make	VOLVO
Model	V50 D5 R-DESIGN
Colour	Blue
Year of manufacture	2009
Top speed	137 mph
0 - 60 mph	7.9 seconds
Gearbox	5 speed automatic

## Engine & fuel consumption

Power	180 BHP
Max. torque	350 Nm at 1.750 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	29.1 mpg
Consumption extra urban	52.3 mpg
Consumption combined	40.4 mpg
CO2 emission	166 g/km
CO2 label	H






Internet history

Entry 1

Date	2022-04-23
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2024-05-18
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	25
Total items failed	3

MOT #14	2023-05-19 09:01
MOT test number	509082130233
Result	✓ Passed
Next expiry date	2024-05-18

MOT #13	2023-05-12 11:35
MOT test number	578668564650
Result	✗ Failed
MAJOR	Nearside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))
MAJOR	Offside Rear Anti-roll bar linkage damaged and seriously weakened (5.3.3 (b) (i))
Pass with rectification	Nearside Front Position lamp not working (4.2.1 (a) (ii))
MAJOR	Offside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))

**MOT #12**

2022-05-19 09:28

**MOT test number**

912565055835

**Result**

✓ Passed

**Advice** Rear Suspension arm pin or bush worn but not resulting in excessive movement both side trailing arm bush (5.3.4 (a) (i))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Front Lower Suspension arm pin or bush worn but not resulting in excessive movement both sides (5.3.4 (a) (i))

**Advice** Handbrake excessive travel

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #11**

2022-05-18 09:40

**MOT test number**

707753596513

**Result**

✗ Failed

**Advice** Handbrake excessive travel

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Rear Suspension arm pin or bush worn but not resulting in excessive movement both side trailing arm bush (5.3.4 (a) (i))

**Advice** Front Lower Suspension arm pin or bush worn but not resulting in excessive movement both sides (5.3.4 (a) (i))

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MAJOR** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

**MOT #10**

2021-09-17 09:38

**MOT test number**

654725447316

**Result**

✓ Passed

**Advice** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))



<b>MOT #9</b>	2019-10-12 11:49
<b>MOT test number</b>	430349896921
<b>Result</b>	✓ Passed
<b>Advice</b>	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

<b>MOT #8</b>	2019-10-12 11:49
<b>MOT test number</b>	941423159668
<b>Result</b>	✗ Failed
<b>Pass with rectification</b>	Nearside Front Position lamp not working (4.2.1 (a) (ii))
<b>Advice</b>	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
<b>Pass with rectification</b>	Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

<b>MOT #7</b>	2018-11-26 10:03
<b>MOT test number</b>	226900104525
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
<b>Advice</b>	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

<b>MOT #6</b>	2017-11-03 13:40
<b>MOT test number</b>	560169472332
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Rear Tyre worn close to the legal limit inner edge (4.1.E.1)
<b>Advice</b>	Nearside Rear Tyre worn close to the legal limit inner edge (4.1.E.1)

<b>MOT #5</b>	2016-11-01 15:08
<b>MOT test number</b>	884975438743
<b>Result</b>	✓ Passed
<b>Advice</b>	Oil leak

**MOT #4** 2015-11-04 11:12**MOT test number** 934016924073**Result** ✓ Passed**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened pitted and scored (3.5.1i)**Advice** Advise on both front tyres worn inside edge**MOT #3** 2014-07-03 16:29**MOT test number** 656864684137**Result** ✓ Passed**MOT #2** 2013-06-27 14:45**MOT test number** 855908473193**Result** ✓ Passed**MOT #1** 2012-06-25 09:04**MOT test number** 927177372102**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 May 2024

✓  
**MOT**  
**Expires:**  
18 May 2024

<b>Tax status</b>	Valid until 1 May
<b>Days left</b>	2
<b>MOT expiry date</b>	18 May 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	H
<b>Single payment (12 months)</b>	£ 290,00,-
<b>Single six month payment</b>	£ 159,50,-
<b>Total payable by 12 monthly instalments</b>	£ 304,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	<b>PK09HJD</b>
Plate since	2019-09-28
Current registration	<b>PK09HJD</b>
Plate since	2019-09-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-06-29
Last registration	2023-05-19
Complete history	<a href="#">See info</a>



Registration #1	2009-06-29	28 mi
Registration #2	2012-06-25	35.261 mi
Registration #3	2013-06-27	47.073 mi
Registration #4	2014-07-03	59.506 mi
Registration #5	2015-11-04	76.732 mi
Registration #6	2016-11-01	85.600 mi
Registration #7	2017-11-03	99.780 mi
Registration #8	2018-11-26	120.796 mi
Registration #9	2019-05-29	151.377 mi
Registration #10	2019-05-29	151.377 mi
Registration #11	2019-05-29	151.377 mi
Registration #12	2019-05-29	151.377 mi
Registration #13	2019-05-29	151.377 mi
Registration #14	2019-05-29	151.377 mi
Registration #15	2019-05-29	151.377 mi
Registration #16	2019-05-29	151.377 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1548 kg
Max. allowed weight	2020 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	739593