



report date: 2024-03-28

General information

Make	MINI
Model	FIRST
Colour	Red
Year of manufacture	2010
Top speed	109 mph
0 - 60 mph	13.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	75 BHP
Max. torque	120 Nm at 2.500 rpm
Engine capacity	1.397 cc
Cylinders	4
Fuel type	Petrol
Consumption city	41.5 mpg
Consumption extra urban	64.2 mpg
Consumption combined	53.3 mpg
CO2 emission	128 g/km
CO2 label	D






Internet history

Entry 1

Date	2022-02-04
Pictures	3
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-03-15
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	12
Total items failed	5

MOT #17	2023-03-16 15:00
MOT test number	571129166059
Result	✓ Passed
Next expiry date	2024-03-15
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #16	2023-03-13 11:42
MOT test number	809193291956
Result	✗ Failed
MAJOR	Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
MAJOR	Exhaust hydrocarbon content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))
MAJOR	Offside Rear Service brake excessively binding (1.2.1 (f))

MOT #15	2021-11-10 09:36
MOT test number	225514357473
Result	✓ Passed
Advice	Front Tyre slightly damaged/cracking or perishing both on inside edge (5.2.3 (d) (ii))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))

**MOT #14** 2020-10-26 10:22**MOT test number** 666076761144**Result** ✓ Passed**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #13** 2019-11-16 09:11**MOT test number** 146868323108**Result** ✓ Passed**MOT #12** 2018-11-10 10:20**MOT test number** 777425171070**Result** ✓ Passed**MOT #11** 2018-11-10 09:17**MOT test number** 554657249874**Result** ✗ Failed**MAJOR** Offside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))**MOT #10** 2017-11-11 13:16**MOT test number** 994455191247**Result** ✓ Passed**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #9** 2017-11-11 11:35**MOT test number** 999325605837**Result** ✗ Failed**Fail** Offside Rear rear brake recording little or no effort (3.7.B.5a)**Fail** Offside Front Lower Front suspension has excessive movement at a wishbone pin or bush rear bush (2.5.A.1c)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**MOT #8** 2016-11-12 14:48**MOT test number** 111650524353**Result** ✓ Passed**MOT #7** 2016-11-12 09:05**MOT test number** 299955454279**Result** ✗ Failed**Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)**Advice** MIL lamp illuminated**MOT #6** 2015-11-25 08:45**MOT test number** 546357704508**Result** ✓ Passed**MOT #5** 2015-11-25 08:45**MOT test number** 210912619621**Result** ✗ Failed**Pass with rectification** Nearside Headlamp not working on dipped beam (1.7.5a)**MOT #4** 2015-04-15 12:02**MOT test number** 668555105157**Result** ✓ Passed



MOT #3	2014-03-22 10:14
MOT test number	818251884027
Result	✓ Passed
MOT #2	2013-04-08 16:02
MOT test number	286718393018
Result	✓ Passed
MOT #1	2012-04-24 12:48
MOT test number	249075612435
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✗
MOT
Expired:
15 March 2024

Tax status	Valid until 1 September
Days left	125
MOT expiry date	15 March 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	BX10HKY
Plate since	2019-09-28
Current registration	BX10HKY
Plate since	2019-09-28

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-03-09
Last registration	2023-03-16
Complete history	See info



Registration #1	2010-03-09	24 mi
Registration #2	2012-04-24	3.923 mi
Registration #3	2013-04-08	14.585 mi
Registration #4	2014-03-22	29.508 mi
Registration #5	2015-04-15	39.895 mi
Registration #6	2015-11-25	41.960 mi
Registration #7	2015-11-25	41.960 mi
Registration #8	2016-11-12	55.384 mi
Registration #9	2016-11-12	55.384 mi
Registration #10	2017-11-11	67.597 mi
Registration #11	2018-03-20	75.377 mi
Registration #12	2018-03-20	75.377 mi
Registration #13	2018-03-20	75.377 mi
Registration #14	2018-03-20	75.377 mi
Registration #15	2018-03-20	75.377 mi
Registration #16	2018-03-20	75.377 mi
Registration #17	2018-03-20	75.377 mi
Registration #18	2018-03-20	75.377 mi
Registration #19	2018-03-20	75.377 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1683 mm
Height	1407 mm
Length	3699 mm
Wheel base	2467 mm
Kerb weight	1060 kg
Max. allowed weight	1510 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Engine number	A889I628
---------------	----------