



HYUNDAI




report date: 2024-03-29

General information

Make	HYUNDAI
Model	IX35 CRDI SE
Colour	Black
Year of manufacture	2015
Top speed	108 mph
0 - 60 mph	12.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	260 Nm at 1.250 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	58.9 mpg
Consumption combined	53.3 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-07-10
Pictures	40
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-04-24
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	22
Total items failed	0

MOT #9	2024-04-19 09:05
MOT test number	147453332309
Result	✓ Passed
Next expiry date	2025-04-24
Advice	Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #8	2024-04-09 10:04
MOT test number	788591030418
Result	✗ Failed
MAJOR	Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
DANGEROUS	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
MAJOR	Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
DANGEROUS	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
MAJOR	Parking brake inoperative on one side Both sides (1.4.1 (a))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge 2.00mm 215/70r16 (5.2.3 (e))
MAJOR	Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
DANGEROUS	Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))



MOT #7	2023-04-25 12:37
MOT test number	418427636137
Result	✓ Passed
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #6	2022-04-22 13:45
MOT test number	998149543411
Result	✓ Passed
Advice	Tyre slightly damaged/cracking or perishing Both rear (5.2.3 (d) (ii))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #5	2021-03-24 11:25
MOT test number	898244215010
Result	✓ Passed

MOT #4	2021-02-05 14:29
MOT test number	460443917718
Result	✗ Failed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing Cracking around the edge (5.2.3 (d) (ii))
MAJOR	Nearside Parking brake inoperative on one side (1.4.1 (a))
MAJOR	Offside Front Tyre(s) with different structures are fitted across the same axle commercial tyre fitted (5.2.3 (c))
DANGEROUS	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
DANGEROUS	Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))
MAJOR	Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))



MOT #3	2020-03-23 12:14
MOT test number	604133234433
Result	✓ Passed
MOT #2	2019-03-27 09:59
MOT test number	791477100101
Result	✓ Passed
Advice	Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))
MOT #1	2018-03-27 16:33
MOT test number	873743686725
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
24 April 2025

Tax status	Valid until 1 September
Days left	124
MOT expiry date	24 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-03-11
Last registration	2024-04-19
Complete history	See info



Registration #1	2015-03-11	9 mi
Registration #2	2018-03-27	30.558 mi
Registration #3	2019-03-27	43.616 mi
Registration #4	2020-03-23	55.370 mi
Registration #5	2021-02-05	65.400 mi
Registration #6	2021-03-24	66.933 mi
Registration #7	2022-05-20	75.277 mi
Registration #8	2023-05-20	85.277 mi
Registration #9	2023-05-20	95.277 mi
Registration #10	2023-05-20	105.277 mi
Registration #11	2024-04-19	115.277 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	88%
Pedestrian	54%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1820 mm
Height	1665 mm
Length	4410 mm
Wheel base	2640 mm
Kerb weight	1537 kg
Max. allowed weight	1940 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D4FDFZ359220