



TOYOTA



report date: 2024-03-28

General information

Make	TOYOTA
Model	CELICA VVTI
Colour	Green
Year of manufacture	-
Top speed	127 mph
0 - 60 mph	8.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	172 Nm at 4.200 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	27.4 mpg
Consumption extra urban	45.6 mpg
Consumption combined	36.7 mpg





LABEL UNKNOWN



Internet history

Entry 1

Date	2021-06-23
Pictures	13
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT #21	2021-08-03 16:23
MOT test number	757910075272
Result	✓ Passed
Next expiry date	2022-08-16
Advice	Surface rust underneath of car all over

MOT #20	2021-08-02 10:33
MOT test number	650702737081
Result	✗ Failed
Fail	Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))
Fail	Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Fail	Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))
Fail	Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT #19	2020-08-17 14:24
MOT test number	640843235104
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Front Service brake fluctuating, but not excessively (1.2.1 (e))
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Underside heavily undersealed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Brake pipe corroded, covered in grease or other material all brake pipes painted, not allowing full inspection (1.1.11 (c))

**MOT #18**

2020-08-04 16:28

MOT test number

530374029384

Result**✗ Failed**

Advice Brake pipe corroded, covered in grease or other material all brake pipes painted, not allowing full inspection (1.1.11 (c))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Offside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength (5.3.6 (a) (i))

Advice Front Service brake fluctuating, but not excessively (1.2.1 (e))

Advice Underside heavily undersealed

Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Offside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength inner sill (5.3.6 (a) (i))

MOT #17

2019-07-09 10:26

MOT test number

558606942065

Result**✓ Passed****MOT #16**

2019-07-01 16:16

MOT test number

696469254078

Result**✗ Failed**

Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Exhaust has a minor leak of exhaust gases (6.1.2 (a))

Fail Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

**MOT #15** 2018-08-07 13:32**MOT test number** 869676669351**Result** ✓ Passed**Advice** Corrosion on under side of vehicle**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #14** 2018-07-13 10:09**MOT test number** 286760993422**Result** ✗ Failed**Fail** Offside Rear Brake pipe excessively corroded (1.1.11 (c))**Fail** Nearside Rear Brake pipe excessively corroded (1.1.11 (c))**Advice** Offside Rear Parking (secondary brake) grabbing slightly (1.3.1 (c))**Fail** Nearside Front Position lamp not working (4.2.1 (a))**Advice** CORROSION HAS STARTED ON VEHICLE UNDERSIDE**MOT #13** 2017-04-11 09:25**MOT test number** 886217939005**Result** ✓ Passed**MOT #12** 2016-03-03 15:40**MOT test number** 164733893974**Result** ✓ Passed

**MOT #11** 2016-02-29 10:02**MOT test number** 239647885060**Result** ✗ Failed**Fail** Offside rear parking brake recording little or no effort (3.7.B.6a)**Fail** Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)**Fail** Rear brake application uneven (3.7.B.2)**Fail** Rear Exhaust has a major leak of exhaust gases (7.1.2)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**MOT #10** 2014-12-08 09:30**MOT test number** 665862044340**Result** ✓ Passed**MOT #9** 2013-03-28 14:55**MOT test number** 786327783096**Result** ✓ Passed**MOT #8** 2012-03-27 09:56**MOT test number** 146357582041**Result** ✓ Passed**MOT #7** 2011-04-04 10:51**MOT test number** 675994391098**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Corrossion and pitting to rear discs**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #6** 2010-04-02 09:30**MOT test number** 164532190478**Result** ✓ Passed**Notice** Front wipers worn**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #5** 2009-03-30 09:32**MOT test number** 814809889081**Result** ✓ Passed**MOT #4** 2008-03-25 17:12**MOT test number** 923195788015**Result** ✓ Passed**MOT #3** 2008-03-20 13:51**MOT test number** 834030488040**Result** ✗ Failed**Fail** Offside Front front brake binding (3.7.B.1)**Notice** Burning smell from brakes or clutch**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Slight surface rust on all brake discs**Fail** Offside Front An item not tested (Manual)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2007-03-29 10:42**MOT test number** 352908387014**Result** ✓ Passed



MOT #1	2006-03-29 16:08
MOT test number	632538686094
Result	✓ Passed



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	PK03 OYA
Plate since	2019-03-28
Current registration	PK03 OYA
Plate since	2019-03-28

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2003-03-29
Last registration	2021-08-03
Complete history	See info



Registration #1	2003-03-29	7 mi
Registration #2	2006-03-29	5.603 mi
Registration #3	2007-03-29	10.097 mi
Registration #4	2008-03-20	13.767 mi
Registration #5	2008-03-25	13.767 mi
Registration #6	2009-03-30	22.486 mi
Registration #7	2010-04-02	32.473 mi
Registration #8	2011-04-04	41.131 mi
Registration #9	2012-03-27	47.372 mi
Registration #10	2013-03-28	52.522 mi
Registration #11	2014-12-08	59.348 mi
Registration #12	2016-02-29	68.509 mi
Registration #13	2017-03-29	75.000 mi
Registration #14	2018-03-29	80.000 mi
Registration #15	2019-03-29	85.000 mi
Registration #16	2020-03-29	90.000 mi
Registration #17	2021-03-29	95.000 mi
Registration #18	2022-03-29	100.000 mi
Registration #19	2023-03-29	105.000 mi
Registration #20	2024-03-29	110.000 mi
Registration #21	2025-03-29	115.000 mi
Registration #22	2026-03-29	120.000 mi
Registration #23	2027-03-29	125.000 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1735 mm
Height	1315 mm
Length	4350 mm
Wheel base	2600 mm
Kerb weight	1145 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Engine number	1ZZ1324678