





report date: 2024-03-29

## General information

Make	BMW
Model	5 SERIES 220D XDRIVE LUXURY ACTIVE TOURER
Colour	Blue
Year of manufacture	2018
Top speed	138 mph
Gearbox	8 speed automatic

# Engine & fuel consumption

Power	188 BHP
Max. torque	400 Nm at 1.750 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	64.2 mpg
Consumption combined	60.1 mpg
CO2 emission	124 g/km
CO2 label	D



CarCheck.co.uk page 1/11



report date: 2024-03-29

## Internet history

### Entry 2

Date 2023-07-12

Pictures 30

Listing price <u>View report</u>









source: cargurus.co.uk

#### Entry 1

Date	2021-09-15	
Pictures	1	
Listing price	<u>View report</u>	



source: cargurus.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

MOT history
-------------

MOT expiry date	2024-07-24
MOT pass rate	75 %
MOT passed	3
Failed MOT tests	1
Total advice items	7
Total items failed	0

MOT #4	2023-07-10 11:06
MOT test number	904310739251
Result	✓ Passed
Next expiry date	2024-07-24

MOT #3	2022-07-25 08:19
MOT test number	153451083518
Result	<b>✓</b> Passed

MOT #2	2021-06-24 15:17
MOT test	number 708948269775
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge 3mm in central tread area (5.2.3 (e))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge 3mm in central tread area (5.2.3 (e))

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #1 2021-06-23 09:49

**MOT test number** 676807134145

**Result** X Failed

Advice Nearside Front Tyre worn close to legal limit/worn on edge advance wear to outer edges (5.2.3 (e))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge 3mm in central tread area (5.2.3 (e))

**DANGEROUS** Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure in outer side wall (5.2.3 (d) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge advance wear to outer edges (5.2.3 (e))

Advice Offside Rear Tyre worn close to legal limit/worn on edge 3mm in central tread area (5.2.3 (e))

CarCheck.co.uk page 4/11



report date: 2024-03-29

## Tax & MOT check



Tax status	Valid until 1 August
Days left	93
MOT expiry date	24 July 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	49
Band	G
First licence fee (12 months)	£ 210,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11




report date: 2024-03-29

### Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

### Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

Owner	history
-------	---------

Owner history	
For how long did the current and previous owner(s) have this BMW? How many owners declared the current and see all owner registrations. Download the full report is	
***************************************	
	More info >
Plate changes	
See in this check if this BMW had different number plates.	
Number of plates	,
Current registration	UK
Plate since	
Current registration	NK SIK
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-29

### Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2018-07-30
Last registration	2023-07-10
Complete history	See info



Registration #1	2018-07-30	24 mi
Registration #2	2021-06-23	36.320 mi
Registration #3	2021-06-24	36.320 mi
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		71.777 66
Registration #7		0.77 sc

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

## Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Adult	95%
Children	84%
Pedestrian	78%
Safety systems	86%
Overall rating	89%
Video	see crash video



# Dimensions & weight

Width	1800 mm
Height	1586 mm
Length	4342 mm
Wheel base	2670 mm
Kerb weight	1510 kg
Max. allowed weight	2050 kg

# Additional information

Fuel tank capacity	51 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11,

Number of axles 2

**Engine number** 59735276