





report date: 2024-03-29

General information

| Make | VOLVO |
|---------------------|-------------------|
| Model | S60 D4 SE LUX NAV |
| Colour | Black |
| Year of manufacture | 2015 |
| Top speed | 143 mph |
| 0 - 60 mph | 7.1 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 188 BHP |
|-------------------------|---------------------|
| Max. torque | 400 Nm at 1.750 rpm |
| Engine capacity | 1.969 сс |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 62.8 mpg |
| Consumption extra urban | 78.5 mpg |
| Consumption combined | 72.4 mpg |
| CO2 emission | 102 g/km |
| CO2 label | В |



CarCheck.co.uk page 1/10



Internet history


Entry 1

Date 2021-10-09

Pictures 28

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/10



MOT history

| MOT expiry date | 2024-02-07 |
|--------------------|------------|
| MOT pass rate | 100 % |
| MOT passed | 6 |
| Failed MOT tests | 0 |
| Total advice items | 5 |
| Total items failed | 0 |

| MOT #6 | 2023-02-06 10:20 |
|--|------------------|
| MOT test number | 580591938983 |
| Result | ✓ Passed |
| Next expiry date | 2024-02-07 |
| Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |
| Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |

| MOT #5 | 2022-01-20 16:50 |
|---|------------------|
| MOT test number | 374658403323 |
| Result | ✓ Passed |
| Advice Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |

| MOT #4 | 2021-02-03 09:59 |
|--|------------------|
| MOT test number | 217016045172 |
| Result | ✓ Passed |
| Advice Front Tyre worn close to legal limit/worn on edge Front tyres (5.2.3 (e)) | |

| MOT #3 | 2020-01-31 09:44 |
|-----------------|------------------|
| MOT test number | 443951257620 |
| Result | ✓ Passed |

CarCheck.co.uk page 3/10



 MOT #2
 2019-02-08 13:49

 MOT test number
 561337541977

 Result
 ✓ Passed

 MOT #1
 2018-04-25 11:42

 MOT test number
 801419738366

 Result
 ✓ Passed

 Advice
 Rear Brake pad(s) wearing thin (3.5.1g)

CarCheck.co.uk page 4/10



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report here for the results.

| Damage 1 | |
|----------|--|
| Date | |
| Category | |
| Туре | |
| Damage 2 | |
| Date | |
| Category | |
| Туре | |



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 6/10



Owner history

| e mier metery | |
|---|-------------|
| For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full | |
| | |
| manus . | |
| | |
| *************************************** | |
| ********* | |
| *************************************** | |
| *************************************** | |
| | More info > |
| Plate changes | |
| See in this check if this VOLVO had different number plates. | |
| Number of plates | , |
| Current registration | NK SIZ |
| Plate since | |
| Current registration | NK SIX |
| Plate since | |
| | More info > |
| | |

CarCheck.co.uk page 7/10



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

Contact info

More info >

CarCheck.co.uk page 8/10



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 8 |
| First mileage registration | 2015-05-22 |
| Last registration | 2023-02-06 |
| Complete history | See info |



| Registration #1 | 2015-05-22 | 23 mi |
|-----------------|------------|------------|
| Registration #2 | 2018-04-25 | 90.043 mi |
| Registration #3 | 2019-02-08 | 98.062 mi |
| Registration #4 | 2020-01-31 | 115.013 mi |
| Registration #5 | | 9.777 es |
| Registration #6 | | 11.777 es |
| Registration #7 | | 11.777 es |
| Registration #8 | | 11.777 es |

More info >

CarCheck.co.uk page 9/10



Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| 50482 | |
| 50501 | |
| S0566 | |
| S0567 | |
| 50569 | |

Safety ratings

| NCAP rating | **** |
|-------------|-----------------|
| Video | see crash video |



Dimensions & weight

| Width | 2097 mm |
|---------------------|---------|
| Height | 1484 mm |
| Length | 4635 mm |
| Wheel base | 2776 mm |
| Kerb weight | 1589 kg |
| Max. allowed weight | 2090 kg |

Additional information

| · | | |
|-----------------------------------|------------------|------------|
| Fuel tank capacity | 67 I | |
| Fuel delivery | Direct Injection | |
| Number of doors | 4 | |
| Number of seats CarCheck.co.uk | 5 | page 10/10 |

Number of axles2Engine number1357405