



report date: 2024-03-28

General information

Make	MINI
Model	COOPER CLUBMAN
Colour	Black
Year of manufacture	2014
Top speed	125 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	118 BHP
Max. torque	160 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.8 mpg
Consumption extra urban	62.8 mpg
Consumption combined	51.4 mpg
CO2 emission	129 g/km
CO2 label	D






Internet history

Entry 1

Date	2021-09-02
Pictures	32
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-09-25
MOT pass rate	100 %
MOT passed	8
Failed MOT tests	0
Total advice items	11
Total items failed	0

MOT #8	2023-09-20 07:19
MOT test number	730422930673
Result	✓ Passed
Next expiry date	2024-09-25
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))

MOT #7	2022-09-26 12:24
MOT test number	853689606360
Result	✓ Passed
Advice	Nearside Rear Service brake binding but not excessively (1.2.1 (f))
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Brake pad(s) wearing thin inner pad (1.1.13 (a) (ii))
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #6	2021-09-15 11:39
MOT test number	852416376688
Result	✓ Passed

**MOT #5** 2020-08-12 09:45**MOT test number** 968806514887**Result** ✓ Passed**MOT #4** 2019-08-19 11:49**MOT test number** 376057070270**Result** ✓ Passed**MOT #3** 2018-08-23 08:48**MOT test number** 825602684380**Result** ✓ Passed**Advice** Nearside Front Inner Road wheel slightly distorted (5.2.2 (c) (i))**Advice** Front Service brake requirements only just met. It would appear that the braking system requires adjustment or repair. slight binding (1.2.1 (c))**MOT #2** 2017-08-18 16:09**MOT test number** 642089865617**Result** ✓ Passed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened inner face (3.5.1i)**Advice** Offside Front Tyre worn close to the legal limit 2.8mm (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit 2.6mm (4.1.E.1)**MOT #1** 2016-08-26 11:47**MOT test number** 751879319765**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
25 September 2024

Tax status	Valid until 1 October
Days left	154
MOT expiry date	25 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

SE14OLN	2014-01-01
SE14OLN	2014-01-01
SE14OLN	2014-01-01
SE14OLN	2014-01-01
SE14OLN	2014-01-01
SE14OLN	2014-01-01
SE14OLN	2014-01-01

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	 SE14OLN
Plate since	2014-01-01
Current registration	 SE14OLN
Plate since	2014-01-01

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.


Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2014-07-18
Last registration	2023-09-20
Complete history	See info



Registration #1	2014-07-18	23 mi
Registration #2	2016-08-26	12.944 mi
Registration #3	2017-08-18	21.972 mi
Registration #4	2018-08-23	29.687 mi
Registration #5	2019-08-19	41.119 mi
Registration #6	2020-08-20	55.277 mi
Registration #7	2021-08-20	65.277 mi
Registration #8	2022-08-20	75.277 mi
Registration #9	2023-08-20	85.277 mi
Registration #10	2023-09-20	95.277 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1683 mm
Height	1426 mm
Length	3937 mm
Wheel base	2547 mm
Kerb weight	1145 kg
Max. allowed weight	1645 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number	A442J668
---------------	----------