



report date: 2024-03-28

General information

Make	FORD
Model	TRANSIT 350 MWB DRW C/C
Colour	White
Year of manufacture	-
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 BHP
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN

**MOT history**

MOT #18	2019-02-19 14:13
MOT test number	323871776930
Result	✓ Passed
Next expiry date	2020-02-18

MOT #17	2019-02-07 16:34
MOT test number	101155384626
Result	✗ Failed
Fail Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))	
Fail Parking brake efficiency below requirements (1.4.2 (a) (i))	
Fail Leaf spring fractured (5.3.1 (b) (i))	

MOT #16	2018-01-29 11:41
MOT test number	588446686232
Result	✓ Passed
Advice Nearside Rear Vehicle structure has slight corrosion (6.1.B.2)	

MOT #15	2018-01-25 15:06
MOT test number	900852500199
Result	✗ Failed
Fail Offside Rear Stop lamp not working (1.2.1b)	
Fail Service brake: efficiency below requirements (3.7.B.7)	
Fail Offside Front Brake pipe excessively corroded (3.6.B.2c)	
Advice Nearside Rear Vehicle structure has slight corrosion (6.1.B.2)	
Fail Front Brake pad(s) less than 1.5 mm thick (3.5.1g)	

**MOT #14**

2017-01-12 09:48

MOT test number

902464622368

Result

✓ Passed

- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Brake pipe slightly corroded and offside front (3.6.B.2c)
- Advice** Nearside and offside front brake discs corroded but not severely weakened.
- Advice** Nearside Rear Brake pipe slightly corroded and offside rear (3.6.B.2c)

MOT #13

2017-01-12 09:48

MOT test number

976415214001

Result

✗ Failed

- Pass with rectification** Offside Stop lamp not working (1.2.1b)
- Advice** Nearside Rear Brake pipe slightly corroded and offside rear (3.6.B.2c)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Brake pipe slightly corroded and offside front (3.6.B.2c)
- Advice** Nearside and offside front brake discs corroded but not severely weakened.

MOT #12

2016-01-22 11:37

MOT test number

857217239354

Result

✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Steering system has slight free play detected at steering wheel (2.2.A.1b)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Front Brake pipe slightly corroded both sides (3.6.B.2c)

**MOT #11**

2016-01-22 09:16

MOT test number

185869655380

Result

✗ Failed

Fail Offside Front Brake pad(s) less than 1.5 mm thick inner (3.5.1g)**Advice** Steering system has slight free play detected at steering wheel (2.2.A.1b)**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Brake pipe slightly corroded both sides (3.6.B.2c)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #10**

2015-01-29 09:46

MOT test number

817449125003

Result

✓ Passed

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #9**

2014-01-23 12:23

MOT test number

616803024084

Result

✓ Passed

Advice Offside Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)**Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)

**MOT #8** 2013-01-25 12:11**MOT test number** 385295523039**Result** ✓ Passed**Notice** Nail in offside rear tyre**Advice** Front Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2012-01-18 15:42**MOT test number** 119188412069**Result** ✓ Passed**Advice** Offside Front Track rod end ball joint has slight play (2.2.B.1f)**Advice** Rear Brake pipe slightly corroded (3.6.B.2c)**MOT #6** 2012-01-18 10:04**MOT test number** 816278112084**Result** ✗ Failed**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Advice** Rear Brake pipe slightly corroded (3.6.B.2c)**Fail** Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Front Track rod end ball joint has slight play (2.2.B.1f)**Fail** Nearside Front wheel bearing rough when rotated (2.5.A.2)**MOT #5** 2011-01-31 17:19**MOT test number** 527641331062**Result** ✓ Passed**Notice** Nearside and offside front brake discs wearing thin.

**MOT #4** 2011-01-31 11:59**MOT test number** 339891231049**Result** ✗ Failed**Notice** Nearside and offside front brake discs wearing thin.**Fail** Nearside rear brake binding (3.7.B.1)**Fail** Nearside rear parking brake recording little or no effort (3.7.B.6a)**MOT #3** 2010-02-01 16:10**MOT test number** 534862330088**Result** ✓ Passed**MOT #2** 2010-02-01 14:21**MOT test number** 730512530015**Result** ✗ Failed**Fail** Nearside Track rod end ball joint has excessive play (2.2.B.1f)**MOT #1** 2009-02-02 12:24**MOT test number** 561993639010**Result** ✓ Passed



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	AD05VJU
Plate since	2019-03-28
Current registration	AD05VJU
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2005-07-29
Last registration	2019-02-19
Complete history	See info



Registration #1	2005-07-29	26 mi
Registration #2	2009-02-02	66.735 mi
Registration #3	2010-02-01	73.905 mi
Registration #4	2010-02-01	73.905 mi
Registration #5	2011-01-31	81.103 mi
Registration #6	2011-01-31	81.103 mi
Registration #7	2012-01-18	96.637 mi
Registration #8	2012-01-18	96.637 mi
Registration #9	2013-01-25	102.979 mi
Registration #10	2014-01-23	110.531 mi
Registration #11	2015-01-23	110.531 mi
Registration #12	2015-01-23	110.531 mi
Registration #13	2015-01-23	110.531 mi
Registration #14	2015-01-23	110.531 mi
Registration #15	2015-01-23	110.531 mi
Registration #16	2015-01-23	110.531 mi
Registration #17	2015-01-23	110.531 mi
Registration #18	2015-01-23	110.531 mi
Registration #19	2019-02-19	110.531 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	3
Engine number	5C67224