



report date: 2024-03-29

General information

Make	JAGUAR
Model	XJ TDVI EXECUTIVE
Colour	Blue
Year of manufacture	2006
Top speed	141 mph
0 - 60 mph	7.8 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	205 BHP
Max. torque	435 Nm at 1.900 rpm
Engine capacity	2.720 cc
Cylinders	6
Fuel type	Diesel
Consumption city	25.9 mpg
Consumption extra urban	43.5 mpg
Consumption combined	34.9 mpg
CO2 emission	214 g/km
CO2 label	K





MOT history

MOT expiry date 2021-06-29**MOT pass rate** 71 %**MOT passed** 12**Failed MOT tests** 5**Total advice items** 44**Total items failed** 12**MOT #17** 2020-06-30 13:05**MOT test number** 208530748740**Result** ✓ Passed**Next expiry date** 2021-06-29**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Under tray fitted**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #16** 2020-06-26 08:28**MOT test number** 446769346157**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Rear Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Under tray fitted

**MOT #15**

2019-05-07 14:57

MOT test number

166616147468

Result

✓ Passed

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Brake pipe corroded, covered in grease or other material to nearside rear (1.1.11 (c))
- Advice** Under tray fitted not allowing a full inspection
- Advice** Front Brake pipe corroded, covered in grease or other material to offside rear (1.1.11 (c))
- Advice** Front Service brake fluctuating, but not excessively (1.2.1 (e))

MOT #14

2019-04-29 14:43

MOT test number

940593674496

Result

✗ Failed

- Advice** Front Brake pipe corroded, covered in grease or other material to offside rear (1.1.11 (c))
- Fail** Offside Rear Lower Suspension arm pin or bush excessively worn inner front bush (5.3.4 (a) (i))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Fail** Rear Registration plate inscription illegible (0.1 (b))
- Fail** Offside Front Brake pipe excessively corroded (1.1.11 (c))
- Advice** Front Brake pipe corroded, covered in grease or other material to nearside rear (1.1.11 (c))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Rear Lower Suspension arm pin or bush excessively worn inner front bush (5.3.4 (a) (i))
- Fail** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))
- Advice** Under tray fitted not allowing a full inspection
- Fail** Exhaust has a major leak of exhaust gases (6.1.2 (a))

**MOT #13**

2018-04-23 08:26

MOT test number

749521480668

Result

✓ Passed

- Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)
- Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)
- Advice** Covers fitted under vehicle not allowing a full inspection
- Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)
- Advice** Front Brake pipe slightly corroded to rear (3.6.B.2c)
- Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)

MOT #12

2017-04-28 10:53

MOT test number

634885991966

Result

✓ Passed

- Advice** Rear Direction indicator slightly discoloured (1.4.A.2f)
- Advice** Offside Rear Inner Suspension arm has slight play in a pin/bush (2.4.G.2)
- Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice** Under car covers fitted not allowing full inspection
- Advice** Offside Front Exhaust has a minor leak of exhaust gases joint (7.1.2)

MOT #11

2016-05-03 08:29

MOT test number

706289197395

Result

✓ Passed

MOT #10

2015-04-24 09:29

MOT test number

149174915124

Result

✓ Passed

**MOT #9** 2014-05-09 09:38**MOT test number** 996529824112**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #8** 2013-05-09 14:54**MOT test number** 657109723147**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**MOT #7** 2013-05-07 09:32**MOT test number** 969877023171**Result** ✗ Failed**Fail** Offside Rear passenger door cannot be opened from outside the vehicle (6.2.B.1c)**Notice** Under-trays fitted obscuring some underside components**MOT #6** 2012-05-14 14:53**MOT test number** 675055232100**Result** ✓ Passed**MOT #5** 2011-07-25 17:38**MOT test number** 106496901202**Result** ✓ Passed**Advice** Offside Rear Lower Suspension arm has slight play in a pin/bush (2.4.G.2)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #4** 2011-07-25 12:02**MOT test number** 387596901473**Result** ✗ Failed**Advice** Offside Rear Lower Suspension arm has slight play in a pin/bush (2.4.G.2)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Registration plate lamp not working (1.1.C.1d)**MOT #3** 2010-02-05 15:26**MOT test number** 174616530052**Result** ✓ Passed**Notice** Both front tyres bald on inner edges**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Notice** Nail in offside front tyre**MOT #2** 2010-02-03 14:27**MOT test number** 241934730043**Result** ✗ Failed**Notice** Both front tyres bald on inner edges**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Notice** Nail in offside front tyre**Fail** Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)



MOT #1	2009-02-11 14:46
MOT test number	394752749079
Result	✓ Passed



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	VX55UOH
Plate since	2024-03-29
Current registration	VX55UOH
Plate since	2024-03-29

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled. If not, and you buy this JAGUAR then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2006-02-01
Last registration	2020-06-30
Complete history	See info



Registration #1	2006-02-01	28 mi
Registration #2	2009-02-11	30.267 mi
Registration #3	2010-02-03	38.884 mi
Registration #4	2010-02-05	38.886 mi
Registration #5	2011-07-25	70.033 mi
Registration #6	2011-07-25	70.033 mi
Registration #7	2012-05-14	79.229 mi
Registration #8	2013-05-07	83.500 mi
Registration #9	2013-05-09	83.557 mi
Registration #10	2013-05-09	83.557 mi
Registration #11	2013-05-09	83.557 mi
Registration #12	2013-05-09	83.557 mi
Registration #13	2013-05-09	83.557 mi
Registration #14	2013-05-09	83.557 mi
Registration #15	2013-05-09	83.557 mi
Registration #16	2013-05-09	83.557 mi
Registration #17	2013-05-09	83.557 mi
Registration #18	2013-05-09	83.557 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2108 mm
Height	1448 mm
Length	5090 mm
Wheel base	3034 mm
Kerb weight	1659 kg
Max. allowed weight	2283 kg

Additional information

Fuel tank capacity	85 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	00766447G