



report date: 2024-03-28

General information

Make	NISSAN
Model	PIXO VISIA
Colour	Silver
Year of manufacture	2011
Top speed	96 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	90 Nm at 3.400 rpm
Engine capacity	996 cc
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	64.2 mpg
CO2 emission	103 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-02-03
Pictures	1
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)

**MOT history**

MOT expiry date	2024-09-21
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	15
Total items failed	6

MOT #13 2023-09-06 14:50**MOT test number** 156218552070**Result** Passed**Next expiry date** 2024-09-21**Advice** Nearside Rear Shock absorbers has slight external damage to the casing corroded (5.3.2 (b))**Advice** Boot struts dangerously weak , replace asap**Advice** Offside Rear Shock absorbers has slight external damage to the casing corroded (5.3.2 (b))**Advice** Brake hydraulic reservoir close to minimum mark (1.1.10 (d) (i))**MOT #12** 2023-08-31 14:45**MOT test number** 246496295142**Result** Failed**Advice** Nearside Rear Shock absorbers has slight external damage to the casing corroded (5.3.2 (b))**Advice** Brake hydraulic reservoir close to minimum mark (1.1.10 (d) (i))**Fail** Offside Rear Direction indicator incorrect colour (4.4.3 (a))**Fail** Nearside Rear Parking brake inoperative on one side (1.4.1 (a))**Advice** Offside Rear Shock absorbers has slight external damage to the casing corroded (5.3.2 (b))**Advice** Boot struts dangerously weak , replace asap**Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**MOT #11** 2022-08-31 15:47**MOT test number** 224729990413**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #10** 2021-09-15 11:46**MOT test number** 442920894510**Result** ✓ Passed**Advice** Front Tyre worn close to legal limit/worn on edge Both front (5.2.3 (e))**Advice** Both rear shocks corroded**MOT #9** 2020-09-22 12:36**MOT test number** 359180443663**Result** ✓ Passed**MOT #8** 2020-09-22 10:02**MOT test number** 377095452440**Result** ✗ Failed**Fail** Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Fail** Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MOT #7** 2020-02-17 11:33**MOT test number** 834111951702**Result** ✓ Passed**Advice** Brake pad(s) wearing thin offside & nearside front (1.1.13 (a) (ii))

**MOT #6** 2019-02-19 11:57**MOT test number** 404731972166**Result** ✓ Passed**MOT #5** 2019-02-19 10:21**MOT test number** 682265968875**Result** ✗ Failed**Fail** Tyre tread depth below requirements of 1.6mm offside & nearside front (5.2.3 (e))**MOT #4** 2018-01-31 10:05**MOT test number** 136514177485**Result** ✓ Passed**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #3** 2017-02-10 09:56**MOT test number** 127941722353**Result** ✓ Passed**MOT #2** 2016-02-11 11:43**MOT test number** 435213033914**Result** ✓ Passed**MOT #1** 2015-02-25 10:32**MOT test number** 715426255098**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
21 September 2024

Tax status	Valid until 1 April
Days left	336
MOT expiry date	21 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	PX61OKA
Plate since	2024-03-28
Current registration	PX61OKA
Plate since	2024-03-28

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-09-01
Last registration	2023-09-06
Complete history	See info



Registration #1	2011-09-01	8 mi
Registration #2	2015-02-25	31.334 mi
Registration #3	2016-02-11	35.453 mi
Registration #4	2017-02-10	40.823 mi
Registration #5	2018-01-31	46.154 mi
Registration #6	2019-02-19	62.269 mi
Registration #7	2019-02-19	62.269 mi
Registration #8	2020-02-17	78.621 mi
Registration #9	2023-09-06	150.000 mi
Registration #10	2023-09-06	150.000 mi
Registration #11	2023-09-06	150.000 mi
Registration #12	2023-09-06	150.000 mi
Registration #13	2023-09-06	150.000 mi
Registration #14	2023-09-06	150.000 mi
Registration #15	2023-09-06	150.000 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1630 mm
Height	1470 mm
Length	3565 mm
Wheel base	2360 mm
Kerb weight	855 kg
Max. allowed weight	1250 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	140325