



report date: 2024-03-29

General information

Make	CITROEN
Model	BERLINGO VTR PLUS HDI
Colour	Beige
Year of manufacture	2009
Top speed	138 mph
0 - 60 mph	11.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	38.7 mpg
Consumption extra urban	60.1 mpg
Consumption combined	50.4 mpg
CO2 emission	149 g/km
CO2 label	F






Internet history

Entry 1

Date	2021-02-11
Pictures	1
Listing price	View report



source: yesauto.com



MOT history

MOT expiry date	2025-02-16
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	33
Total items failed	0

MOT #15	2024-02-15 15:55
MOT test number	166794279368
Result	✓ Passed
Next expiry date	2025-02-16

MOT #14	2024-02-15 09:56
MOT test number	200547930004
Result	✗ Failed
DANGEROUS Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
MAJOR Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))	

MOT #13	2023-02-17 12:47
MOT test number	983211112790
Result	✓ Passed
Advice Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))	
Advice Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	

**MOT #12** 2023-02-14 13:01**MOT test number** 170611930165**Result** ✗ Failed**Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**MAJOR** Horn not working (7.7 (a))**Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**MOT #11** 2022-02-01 13:04**MOT test number** 661621843801**Result** ✓ Passed**Advice** Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**Advice** Rear Suspension component mounting prescribed area is corroded but not considered excessive axle mounts (5.3.6 (a) (i))**MOT #10** 2021-02-16 12:45**MOT test number** 279236339394**Result** ✓ Passed**MOT #9** 2021-02-15 14:45**MOT test number** 738202049816**Result** ✗ Failed**MAJOR** Offside Obligatory mirror seriously damaged, affecting the rear view (3.3 (b) (ii))**Advice** Front Anti-roll bar ball joint has slight play both (5.3.4 (a) (i))**MAJOR** Offside Front Position lamp not working (4.2.1 (a) (ii))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #8** 2019-07-16 08:18**MOT test number** 847689372668**Result** ✓ Passed**Minor** Driver's view to the front outside the swept area of the windscreen wipers restricted by an obstruction (3.1 (a) (i))**Advice** Nearside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Minor** Offside Obligatory mirror slightly damaged (3.3 (b) (i))**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Offside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #7** 2018-07-17 08:30**MOT test number** 372336023605**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Fog lamp damaged**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Windscreen damaged lower section**MOT #6** 2017-07-10 08:40**MOT test number** 152895403434**Result** ✓ Passed**Advice** Windscreen damaged lower section**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #5** 2016-07-08 11:30**MOT test number** 838263286556**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #4** 2015-07-03 17:04**MOT test number** 555464485196**Result** ✓ Passed**Notice** Windscreen cracked**Notice** Near side front fog light not working**MOT #3** 2014-07-04 15:12**MOT test number** 288375984431**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #2** 2013-07-20 08:42**MOT test number** 858711003238**Result** ✓ Passed**MOT #1** 2012-08-10 12:41**MOT test number** 699083922268**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Engine covers fitted obscuring some components in the engine bay



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
16 February 2025

Tax status	Valid until 1 March
Days left	306
MOT expiry date	16 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	0
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-09-25
Last registration	2024-02-15
Complete history	See info



Registration #1	2009-09-25	6 mi
Registration #2	2012-08-10	8.600 mi
Registration #3	2013-07-20	21.740 mi
Registration #4	2014-07-04	36.621 mi
Registration #5	2015-07-03	47.337 mi
Registration #6	2016-07-08	59.825 mi
Registration #7	2017-07-10	75.354 mi
Registration #8	2018-07-17	90.625 mi
Registration #9	2019-07-16	107.197 mi
Registration #10	2020-07-22	125.277 mi
Registration #11	2021-07-22	145.277 mi
Registration #12	2022-07-22	165.277 mi
Registration #13	2023-07-22	185.277 mi
Registration #14	2024-02-15	205.277 mi
Registration #15	2024-02-15	225.277 mi
Registration #16	2024-02-15	245.277 mi
Registration #17	2024-02-15	265.277 mi

More info >



Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)

Dimensions & weight

Width	1853 mm
Height	1456 mm
Length	4779 mm
Wheel base	2815 mm
Max. allowed weight	2040 kg

Additional information

Fuel tank capacity	66 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	JBAJ3204064