



report date: 2024-03-29

General information

Make	HONDA
Model	ACCORD VTEC SE
Colour	Silver
Year of manufacture	2004
Top speed	137 mph
0 - 60 mph	8.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	153 BHP
Max. torque	190 Nm at 4.500 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.0 mpg
Consumption extra urban	47.9 mpg
Consumption combined	38.2 mpg
CO2 emission	176 g/km
CO2 label	I






Internet history

Entry 1

Date	2021-09-06
Pictures	10
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-06-26
MOT pass rate	85 %
MOT passed	17
Failed MOT tests	3
Total advice items	35
Total items failed	9

MOT #20	2023-06-27 10:52
MOT test number	750992482758
Result	✓ Passed
Next expiry date	2024-06-26

MOT #19	2023-06-20 13:21
MOT test number	644478574973
Result	✗ Failed
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))
Fail	Nearside Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))
Fail	Offside Front Driver's view of the road through the swept area of the windscreen significantly affected by an obstruction sun visor (3.1 (a) (ii))

MOT #18	2022-06-10 10:25
MOT test number	827160638997
Result	✓ Passed

**MOT #17**

2021-06-03 15:48

MOT test number

267367622562

Result

✓ Passed

Advice

Offside Rear Coil spring corroded (5.3.1 (b) (i))

Minor

Nearside Front Upper Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice

Nearside Rear Coil spring corroded (5.3.1 (b) (i))

Advice

Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

Minor

Offside Front Upper Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #16

2020-06-16 11:06

MOT test number

607087886482

Result

✓ Passed

Minor

Nearside Front Upper Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Minor

Offside Front Upper Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice

Nearside Rear brake disc corroded

**MOT #15**

2020-05-29 11:39

MOT test number

124634202895

Result**✗ Failed**

Fail Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Minor Nearside Front Upper Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Fail Offside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

Fail Offside Front Position lamp not working (4.2.1 (a) (ii))

Advice Offside rear tyre has tread separation

Fail Nearside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

Minor Offside Front Upper Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice Rear discs heavily corroded

MOT #14

2019-05-24 15:03

MOT test number

275959883282

Result**✓ Passed**

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Minor Nearside Front Upper Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Minor Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Minor Offside Front Upper Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #13**

2018-05-31 11:19

MOT test number

375510793969

Result

✓ Passed

Minor

Nearside Front Upper Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice

Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice

Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Minor

Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice

Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Minor

Offside Front Upper Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #12

2017-05-26 14:50

MOT test number

569647663725

Result

✓ Passed

Advice

All discs slightly worn and pitted

Advice

Front lower arm bushes slightly deteriorated

MOT #11

2016-06-08 11:01

MOT test number

842081229121

Result

✓ Passed

Advice

Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

MOT #10

2015-06-03 11:31

MOT test number

295364155475

Result

✓ Passed

Notice

Offside rear tyre bald inner edge

Notice

Front brake pads appear slightly worn, closer inspection recommended.

Notice

Nearside front wiper blade split



MOT #9	2014-06-05 16:30
---------------	------------------

MOT test number	365756954132
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
---------------	---

Notice	Offside rear tyre has deep cuts in tread
---------------	--

MOT #8	2013-06-06 13:23
---------------	------------------

MOT test number	545297753104
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #7	2012-05-31 12:41
---------------	------------------

MOT test number	127942652158
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #6	2011-05-18 15:51
---------------	------------------

MOT test number	256838131487
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #5	2010-05-26 16:55
---------------	------------------

MOT test number	532026040136
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2009-05-27 15:54
---------------	------------------

MOT test number	342637949104
------------------------	--------------

Result	✓ Passed
---------------	----------



MOT #3	2009-05-27 15:54
MOT test number	513947549106
Result	✗ Failed
Pass with rectification	Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
Pass with rectification	Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

MOT #2	2008-05-30 15:59
MOT test number	234441058454
Result	✓ Passed
Notice	Brake pedal rubber begining to wear slightly

MOT #1	2007-06-13 10:43
MOT test number	453944667154
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
26 June 2024

Tax status		Valid until 1 December
Days left		216
MOT expiry date		26 June 2024
Full MOT history		See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2004-06-07
Last registration	2023-06-27
Complete history	See info



Registration #1	2004-06-07	9 mi
Registration #2	2007-06-13	33.061 mi
Registration #3	2008-05-30	42.288 mi
Registration #4	2009-05-27	51.448 mi
Registration #5	2010-05-26	59.202 mi
Registration #6	2011-05-18	66.199 mi
Registration #7	2012-05-31	72.675 mi
Registration #8	2013-06-06	79.779 mi
Registration #9	2014-06-05	85.391 mi
Registration #10	2015-06-03	90.729 mi
Registration #11	2016-06-08	96.112 mi
Registration #12	2017-06-08	101.500 mi
Registration #13	2018-06-08	106.888 mi
Registration #14	2019-06-08	112.276 mi
Registration #15	2020-06-08	117.664 mi
Registration #16	2021-06-08	123.052 mi
Registration #17	2022-06-08	128.440 mi
Registration #18	2023-06-27	133.828 mi
Registration #19	2024-03-29	139.216 mi
Registration #20	2024-03-29	144.604 mi
Registration #21	2024-03-29	150.000 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1760 mm
Height	1445 mm
Length	4665 mm
Wheel base	2670 mm
Kerb weight	1379 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Engine number	K20A62004284