



GN60KWJ

report date: 2024-03-29

General information

Make	FIAT
Model	GRANDE PUNTO SOUND
Colour	White
Year of manufacture	-
Top speed	103 mph
0 - 60 mph	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	77 BHP
Max. torque	115 Nm at 3.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.9 mpg






Internet history

Entry 1

Date	2021-05-26
Pictures	10
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT #10	2020-07-10 09:44
MOT test number	467643304478
Result	✓ Passed
Next expiry date	2021-07-09
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front strut top bearing noisy

MOT #9	2019-04-17 13:31
MOT test number	414475438875
Result	✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #8	2018-05-03 10:35
MOT test number	238067050924
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit Worn on the inner edge (4.1.E.1)
Advice	Exhaust is in poor condition
Advice	Nearside Front Tyre worn close to the legal limit inner and outer edges worn (4.1.E.1)

**MOT #7** 2018-05-02 11:47**MOT test number** 539470839288**Result** ✗ Failed

- Advice** Offside Rear Tyre is perished and cracked advise change tyre
- Advice** Offside Front Tyre worn close to the legal limit Worn on the inner edge (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit inner and outer edges worn (4.1.E.1)
- Advice** Exhaust is in poor condition
- Fail** Nearside Rear Shock absorber has a serious fluid leak (2.7.3)

MOT #6 2017-04-11 07:18**MOT test number** 578925968030**Result** ✓ Passed**MOT #5** 2017-04-10 14:55**MOT test number** 459409218891**Result** ✗ Failed

- Fail** Nearside Front Headlamp not working on main beam (1.7.5a)
- Pass with rectification** Front Windscreen washer provides insufficient washer liquid (8.2.3)
- Fail** Offside Front Headlamp not working on main beam (1.7.5a)

MOT #4 2016-10-25 10:49**MOT test number** 704764023670**Result** ✓ Passed

- Advice** Exhaust rear box slightly rusty
- Advice** Offside Rear tyre slightly cracked



MOT #3	2015-10-22 15:44
MOT test number	708576262191
Result	✓ Passed
Advice	Rear exhaust box corroded slightly
Advice	Nearside Rear Shock absorber has a light misting of oil (2.7.3)

MOT #2	2014-10-07 09:27
MOT test number	658120784209
Result	✓ Passed
Notice	O/s wiper blade split but clearing the screen

MOT #1	2013-10-25 11:23
MOT test number	598878693201
Result	✓ Passed



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2010-09-28
Last registration	2020-07-10
Complete history	See info



Registration #1	2010-09-28	7 mi
Registration #2	2013-10-25	20.405 mi
Registration #3	2014-10-07	36.915 mi
Registration #4	2015-10-22	43.080 mi
Registration #5	2016-10-25	53.244 mi
Registration #6	2017-04-10	56.979 mi
Registration #7	2019-05-20	59.277 mi
Registration #8	2019-05-20	59.277 mi
Registration #9	2019-05-20	59.277 mi
Registration #10	2019-05-20	59.277 mi
Registration #11	2019-05-20	59.277 mi
Registration #12	2019-05-20	59.277 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4030 mm
Wheel base	2510 mm
Kerb weight	1040 kg
Max. allowed weight	1600 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number	9632561
---------------	---------