




report date: 2024-03-29

General information

Make	VAUXHALL
Model	MOVANO F3500 L3H1 C/C CDTI
Colour	White
Year of manufacture	2015
Top speed	80 mph
0 - 60 mph	14.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	123 BHP
Max. torque	310 Nm at 2.500 rpm
Engine capacity	2.299 cc
Cylinders	4
Fuel type	Diesel
Consumption city	28.0 mpg
Consumption extra urban	35.0 mpg
Consumption combined	32.0 mpg
CO2 emission	226 g/km
CO2 label	L








Internet history

Entry 1

Date	2021-06-28
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-07-14
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	18
Total items failed	0

MOT #8	2023-07-06 14:30
MOT test number	899053774574
Result	✓ Passed
Next expiry date	2024-07-14

MOT #7	2023-06-21 09:59
MOT test number	183708671164
Result	✗ Failed
MAJOR	Engine MIL inoperative or indicates a malfunction LIGHT ON (8.2.2.2 (g))
MAJOR	Offside Front Driver's door cannot be opened from outside the vehicle (6.2.3 (a))
Advice	Nearside Front Nail in tyre

MOT #6	2022-06-21 10:20
MOT test number	648697026392
Result	✓ Passed

MOT #5	2021-07-15 10:21
MOT test number	745230622647
Result	✓ Passed

**MOT #4** 2020-10-16 13:50**MOT test number** 213862406509**Result** ✓ Passed**Advice** Offside Rear Nail in tyre**Advice** Damage to n/s/f**MOT #3** 2020-10-02 10:26**MOT test number** 965167189277**Result** ✗ Failed**MAJOR** Offside Front Side repeater not working (4.4.1 (a) (ii))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**DANGEROUS** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Offside Rear Nail in tyre**Advice** Damage to n/s/f**MAJOR** Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #2** 2019-09-17 10:30**MOT test number** 963670552281**Result** ✓ Passed**Minor** Nearside Windscreen wiper blade defective (3.4 (b) (i))



MOT #12018-09-12 07:21

MOT test number389447915077

Result

✓ Passed

- Advice

Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice

Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
14 July 2024

Tax status	Valid until 1 August
Days left	93
MOT expiry date	14 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 FN65PLZ
Plate since	2019-03-29
Current registration	 FN65PLZ
Plate since	2019-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-09-21
Last registration	2023-07-06
Complete history	See info



Registration #1	2015-09-21	25 mi
Registration #2	2018-09-12	25.028 mi
Registration #3	2019-09-17	36.067 mi
Registration #4	2020-10-02	49.333 mi
Registration #5	2020-10-16	49.333 mi
Registration #6	2020-10-16	49.333 mi
Registration #7	2020-10-16	49.333 mi
Registration #8	2020-10-16	49.333 mi
Registration #9	2020-10-16	49.333 mi
Registration #10	2020-10-16	49.333 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	96%
Children	90%
Pedestrian	67%
Safety systems	100%
Overall rating	89%
Video	see crash video



Dimensions & weight

Width	2470 mm
Height	2350 mm
Length	6418 mm
Kerb weight	1686 kg
Max. allowed weight	3500 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	3
Engine number	M9T -C156231 LWL