





report date: 2024-03-29

General information

Make	VAUXHALL
Model	MERIVA EXCLUSIV AC CDTI ECOFLEX S/S
Colour	Brown
Year of manufacture	2014
Top speed	122 mph
0 - 60 mph	9.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	58.9 mpg
Consumption extra urban	67.3 mpg
Consumption combined	64.2 mpg
CO2 emission	116 g/km
CO2 label	С



CarCheck.co.uk page 1/11



BF14MXT report date: 2024-03-29

Internet history

-		-		1
п	L	ΓV	,	т.

Entry 1	
Date	2021-10-08
Pictures	0
Listing price	View report

source: cargurus.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

MOT history

MOT expiry date	2024-11-02
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	5
Total items failed	2

MOT #10	2023-10-16 14:42
MOT test number	342228735864
Result	✓ Passed
Next expiry date	2024-11-02
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #9	2022-10-28 15:51
MOT test number	829119123534
Result	✓ Passed
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #8	2022-10-28 15:51		
MOT test number	687499012747		
Result	▼ Failed		
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))			
Pass with rectification	Offside Front Inner Tyre has a tear, caused by separation or partial failure of its		
structure (5.2.3 (d) (ii))			

MOT #7	2021-11-03 15:55
MOT test number	296228348372
Result	✓ Passed
Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))	

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #6	2021-11-02 09:00
MOT test number	811464754138
Result	× Failed
Fail Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g)) Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))	

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))		
MOT #5	2021-02-23 09:34	
MOT test number	778368559325	
Result	✓ Passed	
MOT #4	2020-02-24 11:04	
MOT test number	125549403452	
Result	✓ Passed	
MOT #3	2019-02-26 10:49	
MOT test number	556951611432	
Result	✓ Passed	
MOT #2	2018-02-21 09:40	
MOT test number	984777878162	
Result	✓ Passed	
MOT #1	2017-02-22 15:50	
MOT test number	941072551033	
Result	✓ Passed	

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 November
Days left	186
MOT expiry date	2 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	

Damage 2	
Date	
Category	



Extra VAUXHALL salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

BF14MXT

report date: 2024-03-29

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report here.


More info >

Plate changes

mber of plates

-

See in this check if this VAUXHALL had different number plates.





More info >

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-03-01
Last registration	2023-10-16
Complete history	See info



Registration #1	2014-03-01	28 mi
Registration #2	2017-02-22	20.778 mi
Registration #3	2018-02-21	30.175 mi
Registration #4	2019-02-26	38.808 mi
Registration #5	2020-02-24	45.499 mi
Registration #6	2021-02-23	49.728 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es

More info >

CarCheck.co.uk page 10/11



BF14MXT report date: 2024-03-29

Safety ratings

NCAP rating	****
Adult	89%
Children	77%
Pedestrian	55%
Safety systems	86%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1994 mm
Height	1615 mm
Length	4300 mm
Wheel base	2644 mm
Kerb weight	1518 kg
Max. allowed weight	2040 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	A1141184FWXX0075LVL

CarCheck.co.uk page 11/11