



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	EOS GTI EDITION30 T 230
Colour	Blue
Year of manufacture	2007
Top speed	150 mph
0 - 60 mph	6.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	227 BHP
Max. torque	300 Nm at 2.200 rpm
Engine capacity	1.984 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.0 mpg
Consumption extra urban	44.1 mpg
Consumption combined	34.4 mpg
CO2 emission	194 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-12-14
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-01-14
MOT pass rate	71 %
MOT passed	15
Failed MOT tests	6
Total advice items	40
Total items failed	3

MOT #21	2024-01-15 15:01
MOT test number	646624438454
Result	✓ Passed
Next expiry date	2025-01-14

MOT #20	2023-01-07 16:11
MOT test number	161904707676
Result	✓ Passed
Minor	Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge nearside rear strong advise (5.2.3 (e))

**MOT #19**

2023-01-04 10:01

MOT test number

933465621591

Result**✗ Failed****Advice** Offside Rear Tyre worn close to legal limit/worn on edge nearside rear strong advise (5.2.3 (e))**MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))**MAJOR** Offside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))**MAJOR** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MAJOR** Windscreen washer provides insufficient washer liquid (3.5 (a))**DANGEROUS** Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**MAJOR** Offside Front Inner Brake disc significantly and obviously worn (1.1.14 (a) (i))**MAJOR** Offside Front Service brake excessively binding nearside front (1.2.1 (f))**MAJOR** Offside Front Side repeater not working (4.4.1 (a) (ii))**DANGEROUS** Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #18**

2021-12-16 13:31

MOT test number

234165804629

Result**✓ Passed****MOT #17**

2021-12-16 13:31

MOT test number

118606809173

Result**✗ Failed****Pass with rectification** Position lamp not working (4.2.1 (a) (ii))

**MOT #16** 2020-12-18 16:49**MOT test number** 128745155590**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge worn heavily on inner edge (5.2.3 (e))**Advice** Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))**MOT #15** 2020-12-18 12:19**MOT test number** 761113529348**Result** ✗ Failed**MAJOR** Offside Windscreen washer provides insufficient washer liquid feed pipe split (3.5 (a))**Advice** Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))**MAJOR** Nearside Windscreen washer provides insufficient washer liquid feed pipe split (3.5 (a))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge worn heavily on inner edge (5.2.3 (e))**MAJOR** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt insecure (6.1.7 (g) (ii))**MOT #14** 2020-01-03 15:08**MOT test number** 295625643796**Result** ✓ Passed

**MOT #13**

2020-01-02 12:45

MOT test number

588113120984

Result**✗ Failed**

- MAJOR** Bonnet primary retaining device ineffective (3.1 (c))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- MAJOR** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Nearside Side repeater light intensity significantly reduced (4.4.3 (a))
- MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #12

2019-01-05 12:25

MOT test number

162933589949

Result**✓ Passed**

- Advice** Under trays and engine covers fitted

**MOT #11** 2019-01-02 13:51**MOT test number** 989854298952**Result** ✗ Failed

DANGEROUS Offside Rear Tyre has a bulge, caused by separation or partial failure of its structure inner edge (5.2.3 (d) (ii))

MAJOR Windscreen washer not working (3.5 (a))

Advice Under trays and engine covers fitted

MAJOR Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge outer edge (5.2.3 (e))

MAJOR Bonnet cannot be secured in the closed position (3.1 (b) (i))

DANGEROUS Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #10 2017-10-31 14:15**MOT test number** 273290963612**Result** ✓ Passed**MOT #9** 2016-11-07 13:11**MOT test number** 117595342867**Result** ✓ Passed**MOT #8** 2015-10-31 10:55**MOT test number** 556051824905**Result** ✓ Passed**MOT #7** 2014-11-05 14:46**MOT test number** 736459804381**Result** ✓ Passed

**MOT #6** 2014-11-04 13:24**MOT test number** 186448704396**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2013-11-08 16:50**MOT test number** 257102013357**Result** ✓ Passed**MOT #4** 2013-02-05 12:48**MOT test number** 246406633097**Result** ✓ Passed**MOT #3** 2012-02-14 16:37**MOT test number** 169645242069**Result** ✓ Passed**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #2** 2011-02-16 16:10**MOT test number** 137647641025**Result** ✓ Passed**MOT #1** 2010-02-15 10:21**MOT test number** 861176240089**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
14 January 2025

Tax status	Valid until 1 October
Days left	155
MOT expiry date	14 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 PK07BFX
Plate since	2024-03-29
Current registration	 PK07BFX
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2007-03-01
Last registration	2024-01-15
Complete history	See info



Registration #1	2007-03-01	7 mi
Registration #2	2010-02-15	28.837 mi
Registration #3	2011-02-16	35.666 mi
Registration #4	2012-02-14	44.017 mi
Registration #5	2013-02-05	49.896 mi
Registration #6	2013-11-08	54.006 mi
Registration #7	2014-11-04	61.282 mi
Registration #8	2014-11-05	61.282 mi
Registration #9	2015-10-31	67.857 mi
Registration #10	2016-11-07	74.495 mi
Registration #11	2017-10-31	82.256 mi
Registration #12	2019-01-02	88.627 mi
Registration #13	2019-01-02	88.627 mi
Registration #14	2019-01-02	88.627 mi
Registration #15	2019-01-02	88.627 mi
Registration #16	2019-01-02	88.627 mi
Registration #17	2019-01-02	88.627 mi
Registration #18	2019-01-02	88.627 mi
Registration #19	2019-01-02	88.627 mi
Registration #20	2019-01-02	88.627 mi
Registration #21	2019-01-02	88.627 mi
Registration #22	2019-01-02	88.627 mi
Registration #23	2019-01-02	88.627 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1759 mm
Height	1469 mm
Length	4216 mm
Wheel base	2578 mm
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles

2

Engine number

NOT KNOWN