





#### General information

Make	ΤΟΥΟΤΑ
Model	VERSO VALVEMATIC ICON
Colour	Silver
Year of manufacture	2013
Top speed	115 mph
0 - 60 mph	11.1 seconds
Gearbox	7 speed CVT

## Engine & fuel consumption

Power	147 BHP
Max. torque	180 Nm at 4.000 rpm
Engine capacity	1.798 cc
Cylinders	4
Fuel type	Petrol
Consumption city	33.2 mpg
Consumption extra urban	48.7 mpg
Consumption combined	41.5 mpg
CO2 emission	159 g/km
CO2 label	G








## Internet history

Entry 1	
Date	2021-02-05
Pictures	10
Listing price	View report









source: autoonline.co.uk



## MOT history

MOT expiry date	2025-03-25
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	11
Total items failed	3

MOT #10	2024-03-26 11:55
MOT test number	296125432891
Result	✓ Passed
Next expiry date	2025-03-25
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #9		2024-03-26 11:55
MOT test number		456903453898
Result		🗙 Failed
Pass with rectification	Nearside Rear Direction indicator incorrect colour (4.4.3 (a))	
Pass with rectification	Offside Rear Direction indicator incorrect colour (4.4.3 (a))	
Advice Offside Rear Tyr	e slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #8		2023-02-24 12:43
MOT test	number	127984561151
Result		✓ Passed
<b>Advice</b> (a) (ii))	Front Brake disc worn, pitted or scored, but not seriously weakened brake p	ads 50% worn (1.1.14
Advice	Rear brake pads 50% worn	





MOT #7		2022-03-21 10:46
MOT test	number	230162336916
Result		✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

МОТ #6	2022-03-21 09:43
MOT test number	409650151739
Result	🗙 Failed
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Fail Nearside Front Tyre has a bulge, caused by separation or partial failure of its	structure (5.2.3 (d) (ii))
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #5	2021-03-04 15:11
MOT test number	990069525641
Result	✓ Passed
MOT #1	2020-03-24 12:47

MOT #4	2020-03-24 12:47
MOT test number	294929847536
Result	✓ Passed

MOT #3	2018-10-05 08:40
MOT test number	774736762713
Result	Passed
Advice Offside Front Tyre slightly damaged (5.2.3 (d) (ii))	





MOT #2	2017-10-17 08:20
MOT test number	606505818423
Result	✓ Passed
MOT #1	2016-10-27 15:35
MOT test number	331855461794
Result	✓ Passed



Tax & MOT check

	✓ Taxed		√ мот
Tax due: 1 March 2025		Expires: 25 March 2025	
Tax status			Valid until 1 March
Days left			306
MOT expiry date			25 March 2025
Full MOT history			<u>See MOT history</u>

## Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-





#### Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	K K
Damage 2	AMPL
Date	NE
Category	AMP
Туре	

#### Extra TOYOTA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 11.111
Auction value	4 10.000
Average private trade value	4 10.200





## Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

and the second sec	
************	
*******	
*******	
************	
********	
	More info >
Plate changes	
See in this check if this TOYOTA had different number plat	es.
Number of plates	
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





#### Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





## Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-11-22
Last registration	2024-03-26
Complete history	See info



Registration #1	2013-11-22	8 mi
Registration #2	2016-10-27	81.892 mi
Registration #3	2017-10-17	85.417 mi
Registration #4	2018-10-05	89.831 mi
Registration #5	2020-03-24	92.909 mi
Registration #6		11.777 est
Registration #7		11.777 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.117 esi





## Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Adult	89%
Children	75%
Pedestrian	69%
Safety systems	86%
Overall rating	82%
Video	see crash video



Dimensions & weight	
Width	1790 mm
Height	1620 mm
Length	4460 mm
Wheel base	2780 mm
Kerb weight	1540 kg
Max. allowed weight	2125 kg
Additional information	
Fuel tank capacity	60 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 12/12