



report date: 2024-03-29

General information

Make	CITROEN
Model	BERLINGO 625 LX L1 HDI
Colour	White
Year of manufacture	2014
Top speed	92 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 BHP
Max. torque	185 Nm at 1.500 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.9 mpg
Consumption extra urban	60.1 mpg
Consumption combined	55.4 mpg
CO2 emission	133 g/km
CO2 label	E





## MOT history

MOT expiry date	2024-04-25
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	11
Total items failed	5

MOT #8 2023-04-26 16:13

MOT test number 424628938794

Result ✓ Passed

Next expiry date 2024-04-25

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Minor** Nearside Front Upper Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))

**Minor** Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #7 2021-09-29 14:37

MOT test number 945915430934

Result ✓ Passed

**Advice** Oil leak, but not excessive engine (8.4.1 (a) (i))

**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #6** 2021-09-28 14:31**MOT test number** 526218090427**Result** ✗ Failed

- Fail** Offside Front Lower Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))
- Minor** Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Fail** Horn not working (7.7 (a))
- Advice** Oil leak, but not excessive engine (8.4.1 (a) (i))
- Fail** Nearside Front Lower Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Fail** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

**MOT #5** 2020-07-27 14:44**MOT test number** 602229092705**Result** ✓ Passed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #4** 2020-07-27 14:44**MOT test number** 446245613407**Result** ✗ Failed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Pass with rectification** Front Position lamp not working (4.2.1 (a) (ii))

**MOT #3** 2019-07-24 12:58**MOT test number** 516132339623**Result** ✓ Passed



MOT #2	2018-07-12 12:02
MOT test number	255075559391
Result	✓ Passed
MOT #1	2017-08-08 14:52
MOT test number	764974341984
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✗  
**MOT**  
**Expired:**  
25 April 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	124
<b>MOT expiry date</b>	25 April 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	39
<b>Standard rate (12 months)</b>	£ 275,00,-
<b>Standard rate (6 months)</b>	£ 151,25,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	<b>CN64XKF</b>
Plate since	2024-03-29
Current registration	<b>CN64XKF</b>
Plate since	2024-03-29

More info >





Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2014-09-17
Last registration	2023-04-26
Complete history	<a href="#">See info</a>



Registration #1	2014-09-17	26 mi
Registration #2	2017-08-08	56.202 mi
Registration #3	2018-07-12	70.730 mi
Registration #4	2019-07-24	96.072 mi
Registration #5	2020-07-27	115.247 mi
Registration #6	2021-05-20	135.277 mi
Registration #7	2022-05-20	155.277 mi
Registration #8	2023-05-20	175.277 mi
Registration #9	2024-05-20	195.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1810 mm
Height	1801 mm
Length	4380 mm
Wheel base	2728 mm
Kerb weight	1304 kg
Max. allowed weight	1945 kg

Additional information

Fuel delivery	Direct Injection
Number of seats	3
Number of axles	2
Engine number	JBEM3044262