




report date: 2024-03-28

General information

Make	KIA
Model	PROCEED PRO CEED STRIKE
Colour	White
Year of manufacture	2010
Top speed	112 mph
0 - 60 mph	11.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	137 Nm at 5.000 rpm
Engine capacity	1.396 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	48.7 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-07-20
Pictures	6
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-07-22
MOT pass rate	65 %
MOT passed	11
Failed MOT tests	6
Total advice items	16
Total items failed	18

MOT #17 2023-07-21 06:56

MOT test number 957711035116

Result ✔ Passed

Next expiry date 2024-07-22

Advice Nearside Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. low (1.2.1 (b) (i))

MOT #16 2023-07-18 16:26

MOT test number 873099331153

Result ✘ Failed

- Fail** Nearside Headlamp aim unable to be tested (4.1.2 (b))
- Fail** Offside Rear Suspension arm corroded and seriously weakened spring holder (5.3.3 (b) (i))
- Fail** Nearside Rear Brakes imbalanced across an axle low (1.2.1 (b) (i))
- Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Fail** Nearside Rear Suspension arm corroded and seriously weakened spring holder (5.3.3 (b) (i))
- Advice** Nearside Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. low (1.2.1 (b) (i))
- Fail** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))

MOT #15 2022-07-07 13:22

MOT test number 764675380095

Result ✔ Passed



MOT #14	2022-07-06 12:23
MOT test number	845418820998
Result	✗ Failed
Fail	Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
Fail	Front Windscreen washer provides insufficient washer liquid both (3.5 (a))
Fail	Offside Front Headlamp aim not tested (4.1.2 (b))
Fail	Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
Fail	Front Windscreen wiper does not clear the windscreen effectively both (3.4 (b) (ii))
Fail	Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

MOT #13	2021-07-23 10:23
MOT test number	341351296109
Result	✓ Passed

MOT #12	2021-07-22 16:05
MOT test number	420008726832
Result	✗ Failed
Fail	Windscreen washer not working (3.5 (a))

MOT #11	2020-10-09 12:48
MOT test number	738763450825
Result	✓ Passed

MOT #10	2020-10-08 08:13
MOT test number	442314983826
Result	✗ Failed
Fail	Nearside Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))



MOT #9	2019-10-17 15:08
MOT test number	988865692876
Result	✓ Passed
Advice	Offside Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Nearside Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #8	2019-10-17 09:17
MOT test number	877296464801
Result	✗ Failed
Fail	Nearside Service brake excessively binding (1.2.1 (f))
Fail	Offside Headlamp aim too high (4.1.2 (a))
Advice	Offside Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Fail	Offside Service brake excessively binding (1.2.1 (f))
Advice	Nearside Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #7	2018-10-29 16:00
MOT test number	541536723767
Result	✓ Passed

MOT #6	2017-10-05 09:22
MOT test number	751596840131
Result	✓ Passed
Advice	Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
Advice	Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)



MOT #5 2017-10-05 09:22

MOT test number 819260257770

Result ✗ Failed

Pass with rectification Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)

Advice Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #4 2016-09-23 08:54

MOT test number 486518364179

Result ✓ Passed

Advice Nearside Front Anti-roll bar linkage ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

Advice Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Offside Front Anti-roll bar linkage ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

Advice Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Nearside rear tyre tread cracked

MOT #3 2015-09-22 11:30

MOT test number 725329678315

Result ✓ Passed

MOT #2 2014-09-23 12:19

MOT test number 548086964204

Result ✓ Passed

MOT #1 2013-10-28 11:57

MOT test number 988871103317

Result ✓ Passed

Notice Nail in offside rear tyre



Tax & MOT check

✓
Taxed

Tax due:
1 March 2025

✓
MOT

Expires:
22 July 2024

Tax status Valid until 1 March

Days left 307

MOT expiry date 22 July 2024

Full MOT history [See MOT history](#)

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-




Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	SP60ZPN
Plate since	2024-03-28
Current registration	SP60ZPN
Plate since	2024-03-28

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.


Finance company	REDACTED
Date of agreement	REDACTED
Agreement type	REDACTED
Agreement term	REDACTED
Agreement number	REDACTED
Contact info	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-09-30
Last registration	2023-07-21
Complete history	See info



Registration #1	2010-09-30	17 mi
Registration #2	2013-10-28	27.008 mi
Registration #3	2014-09-23	36.581 mi
Registration #4	2015-09-22	45.547 mi
Registration #5	2016-09-23	53.699 mi
Registration #6	2017-10-05	63.630 mi
Registration #7	2017-10-05	63.630 mi
Registration #8	2018-10-29	67.108 mi
Registration #9	2019-10-17	69.309 mi
Registration #10	2019-10-17	69.316 mi
Registration #11	2019-10-17	69.316 mi
Registration #12	2019-10-17	69.316 mi
Registration #13	2019-10-17	69.316 mi
Registration #14	2019-10-17	69.316 mi
Registration #15	2019-10-17	69.316 mi
Registration #16	2019-10-17	69.316 mi
Registration #17	2019-10-17	69.316 mi
Registration #18	2019-10-17	69.316 mi
Registration #19	2019-10-17	69.316 mi

[More info >](#)



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1790 mm
Height	1450 mm
Length	4250 mm
Wheel base	2650 mm
Kerb weight	1257 kg
Max. allowed weight	1750 kg

Additional information

Fuel tank capacity	53 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

Number of axles

2

Engine number

G4FAAZ240284