




report date: 2024-03-28

General information

Make	VOLVO
Model	XC60 D3 SE AWD
Colour	Gold
Year of manufacture	2012
Top speed	118 mph
0 - 60 mph	10.4 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	161 BHP
Max. torque	420 Nm at 1.500 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	31.7 mpg
Consumption extra urban	50.4 mpg
Consumption combined	41.5 mpg
CO2 emission	179 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-05-26
Pictures	32
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-03-28
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	26
Total items failed	6

MOT #12	2024-03-22 16:32
MOT test number	344270771052
Result	✓ Passed
Next expiry date	2025-03-28
Advice	Power steering close to minimum mark (2.1.5 (b) (i))
Advice	Offside Front Power steering pipe/hose has slight seepage (2.1.5 (a))
Advice	Rear Exhaust heatshield loose

MOT #11	2023-03-11 12:05
MOT test number	456878462514
Result	✓ Passed
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Play in steering rack inner joint(s)
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #10**

2022-03-19 10:59

MOT test number

592947650887

Result

✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge Wearing inner edge (5.2.3 (e))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing Cracking (5.2.3 (d) (ii))
- Advice** Offside Front Inner Rearmost bush cracking
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge Wearing outer edges (5.2.3 (e))
- Advice** Nearside Front Inner Rearmost bush cracking
- Advice** Offside Front Tyre slightly damaged/cracking or perishing Cracking (5.2.3 (d) (ii))
- Advice** Offside Front Play in steering rack inner joint(s)

MOT #9

2022-03-16 15:14

MOT test number

614373836119

Result

✗ Failed

- Advice** Offside Front Inner Rearmost bush cracking
- Fail** Offside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))
- Advice** Offside Front Play in steering rack inner joint(s)
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge Wearing outer edges (5.2.3 (e))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing Cracking (5.2.3 (d) (ii))
- Advice** Nearside Front Inner Rearmost bush cracking
- Fail** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge Wearing inner edge (5.2.3 (e))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing Cracking (5.2.3 (d) (ii))
- Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

**MOT #8** 2021-03-02 09:46**MOT test number** 254312437586**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #7** 2020-03-23 15:00**MOT test number** 517491604179**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Track rod end ball joint has slight play (2.1.3 (b) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #6** 2019-03-22 17:06**MOT test number** 760956284214**Result** ✓ Passed**MOT #5** 2019-03-22 11:51**MOT test number** 174989553157**Result** ✗ Failed**Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #4** 2018-03-29 15:23**MOT test number** 674078165314**Result** ✓ Passed



MOT #3 2018-03-27 07:57

MOT test number 499004485232

Result ✗ Failed

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #2 2016-09-27 13:11

MOT test number 156225534801

Result ✓ Passed

MOT #1 2015-10-08 13:53

MOT test number 450914480067

Result ✓ Passed

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
28 March 2025

Tax status	Valid until 1 September
Days left	126
MOT expiry date	28 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-28
Current registration	
Plate since	2019-09-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-10-20
Last registration	2024-03-22
Complete history	See info



Registration #1	2012-10-20	13 mi
Registration #2	2015-10-08	52.594 mi
Registration #3	2016-09-27	67.060 mi
Registration #4	2018-03-27	80.670 mi
Registration #5	2018-03-29	80.670 mi
Registration #6	2019-03-22	87.087 mi
Registration #7	2019-03-22	87.087 mi
Registration #8	2019-03-22	87.087 mi
Registration #9	2019-03-22	87.087 mi
Registration #10	2019-03-22	87.087 mi
Registration #11	2019-03-22	87.087 mi
Registration #12	2019-03-22	87.087 mi
Registration #13	2019-03-22	87.087 mi
Registration #14	2019-03-22	87.087 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	79%
Pedestrian	48%
Safety systems	86%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1891 mm
Height	1713 mm
Length	4627 mm
Wheel base	2774 mm
Kerb weight	1863 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1138183