



report date: 2024-03-29

General information

Make	VAUXHALL
Model	ANTARA SE NAV CDTI S/S
Colour	White
Year of manufacture	2015
Top speed	117 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.5 mpg
Consumption extra urban	48.7 mpg
Consumption combined	42.2 mpg
CO2 emission	177 g/km
CO2 label	I






Internet history

Entry 1

Date 2021-08-01

Pictures 7

Listing price [View report](#)



source: autotrader.co.uk



MOT history

MOT expiry date	2024-09-21
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	29
Total items failed	0

MOT #9	2023-09-21 12:07
MOT test number	783768080766
Result	✓ Passed
Next expiry date	2024-09-21

MOT #8	2022-09-22 13:14
MOT test number	699766781452
Result	✓ Passed

- Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material Main (1.1.11 (c))
- Advice** Engine bay and under body covers fitted as standard obscuring various testable comonents
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Back bush (5.3.4 (a) (i))
- Advice** TPMS light on
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material Main (1.1.11 (c))

**MOT #7** 2022-09-22 09:57**MOT test number** 626656064469**Result** ✗ Failed**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Back bush (5.3.4 (a) (i))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material Main (1.1.11 (c))**MAJOR** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**MAJOR** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Engine bay and under body covers fitted as standard obscuring various testable comonents**Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material Main (1.1.11 (c))**MAJOR** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))**MAJOR** Nearside Headlamp not working on main beam (4.1.1 (a) (ii))**Advice** TPMS light on**MAJOR** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #6** 2021-08-16 13:54**MOT test number** 469359265195**Result** ✓ Passed



MOT #5

2021-08-13 15:17

MOT test number

590027497124

Result

✗ Failed

MAJOR Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

DANGEROUS Nearside Front Anti-roll bar attachment bracket/mounting insecure and impairing directional stability Lower ball joint. (5.3.3 (a) (ii))

MAJOR Offside Front Windscreen washer provides insufficient washer liquid (3.5 (a))

MAJOR Nearside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

MAJOR Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt Lower ball joint. (5.3.4 (b) (ii))

MAJOR Windscreen wiper does not clear the windscreen effectively Blade is insecure. (Clip is missing). (3.4 (b) (ii))

MOT #4

2021-01-22 13:48

MOT test number

739114707098

Result

✓ Passed

Advice Front Suspension arm pin or bush worn but not resulting in excessive movement both nearside and offside rear bushes (5.3.4 (a) (i))

MOT #3

2020-01-17 09:03

MOT test number

482288503701

Result

✓ Passed

MOT #2

2019-01-26 11:35

MOT test number

708927557486

Result

✓ Passed

Advice Slight misting of oil on engine



MOT #1	2018-01-29 12:35
MOT test number	184896253123
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (3.5.1g)
Advice	Front brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)
Advice	Rear Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

X

Untaxed

Tax expired:
18 January 2024

✓

MOT

Expires:
21 September 2024

Tax status	Expired at 18 January 2024
Days left	102 days too late
MOT expiry date	21 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	SE64RZW
Plate since	2019-03-29
Current registration	SE64RZW
Plate since	2019-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-01-29
Last registration	2023-09-21
Complete history	See info



Registration #1	2015-01-29	23 mi
Registration #2	2018-01-29	44.947 mi
Registration #3	2019-01-26	55.193 mi
Registration #4	2020-01-17	66.205 mi
Registration #5	2021-01-22	75.365 mi
Registration #6	2022-01-29	85.377 mi
Registration #7	2022-01-29	85.377 mi
Registration #8	2022-01-29	85.377 mi
Registration #9	2022-01-29	85.377 mi
Registration #10	2022-01-29	85.377 mi
Registration #11	2023-09-21	85.377 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	2085 mm
Height	1761 mm
Length	4596 mm
Wheel base	2707 mm
Kerb weight	1911 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	Z22D1 345365K LNQ