





report date: 2024-03-28

General information

Make	RENAULT
Model	MEGANE DYNAMIQUE TOMTOM ENERGY DCI S/S
Colour	Black
Year of manufacture	2014
Top speed	118 mph
0 - 100 km/h	12.1 seconds
0 - 60 mph	12.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	81 kW / 110 HP / 110 BHP
Max. torque	260 Nm at 1.750 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	72.4 mpg
Consumption extra urban	88.3 mpg
Consumption combined	80.7 mpg
CO2 emission	90 g/km
CO2 label	A



CarCheck.co.uk page 1/13



report date: 2024-03-28

Internet history

Entry 1

Date 2021-06-23

Pictures 34

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

MOT history

MOT expiry date	2025-03-30
MOT pass rate	50 %
MOT passed	6
Failed MOT tests	6
Total advice items	10
Total items failed	17

MOT #12	2024-03-27 13:16
MOT test number	836367885310
Result	✓ Passed
Next expiry date	2025-03-30
Advice Nearside Front Tyre worn close to legal limit/worn on edge on limit 1.6mm	(5.2.3 (e))

MOT #11	2024-03-27 10:04
MOT test number	766945723571
Result	X Failed
Advice Nearside Front Tyre worn close to legal limit/worn on edge on limit 1.6mn	n (5.2.3 (e))
Fail Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))	
Fail Offside Front Outer Drive shaft joint constant velocity boot split or insecure, ingress of dirt (6.1.7 (g) (ii))	no longer prevents the

MOT #10		2023-03-28 07:52
MOT test	number	358316233538
Result		✓ Passed
Advice	Offside door mirror glass cracked	
Advice	Nearside dip beam output weak	

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT test number

Result

Pass with rectification

Offside Headlamp aim too low (4.1.2 (a))

Advice

Nearside dip beam output weak

Pass with rectification

Nearside Headlamp aim too low (4.1.2 (a))

Advice

Offside door mirror glass cracked

MOT #8

MOT test number

Result

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT test number

Result

Pass with rectification

Stop lamp(s) all not working (4.3.1 (a) (iii))

Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

 MOT #6
 2021-03-31 19:00

 MOT test number
 837758791131

 Result
 ✓ Passed

 Advice
 Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT #5 2021-03-31 19:00

MOT test number 404957734566

Result X Failed

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Pass with rectification

Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

MOT #4 2019-06-01 12:47

MOT test number 608498166833

Result
✓ Passed

MOT #3 2019-05-17 08:42

MOT test number 227648483558

Result X Failed

Fail Offside Headlamp aim too low (4.1.2 (a))

Fail Nearside Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Fail Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

Fail Nearside Rear Tyre has ply or cords exposed outer wall, cut. (5.2.3 (d) (ii))

Fail Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

Fail Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

MOT #2 2017-09-26 15:19

MOT test number 281032440334

Result ✓ Passed

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT #1 2017-09-26 08:59 **MOT test number** 414445696850 Result × Failed Fail Electronic stability system warning lamp indicates a fault (3.4.1c) Offside Windscreen wiper does not clear the windscreen effectively (8.2.2) Fail Fail Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c) Fail Tyre pressure monitoring system warning lamp indicates a fault (4.1.D.4) Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords Fail (4.1.D.1a)

CarCheck.co.uk page 6/13



YH64WLU report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 July
Days left	64
MOT expiry date	30 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



YH64WLU report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

More info >

Owner history For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this RENAULT had different number plates. about of pliates faste since

CarCheck.co.uk page 10/13



report date: 2024-03-28

Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Pinance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2014-10-17
Last registration	2024-03-27
Complete history	See info



Registration #1	2014-10-17	11 mi
Registration #2	2017-09-26	56.266 mi
Registration #3	2017-09-26	56.267 mi
Registration #4	2019-05-17	75.752 mi
Registration #5	2019-06-01	72.868 mi
Registration #6	2021-03-31	88.097 mi
Registration #7	2021-03-31	88.097 mi
Registration #8		71.777 es
Registration #9		11.777 es
Registration #10		71.777 es
Registration #11		11.777 es
Registration #12		71.777 es
Registration #13		11.777 es

mn.n.n

More info >

77.777 86

CarCheck.co.uk page 12/13



report date: 2024-03-28

Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	83%
Children	78%
Pedestrian	60%
Safety systems	56%
Overall rating	72%
Video	see crash video



Dimensions & weight

Width	1804 mm
Height	1423 mm
Length	4299 mm
Wheel base	2641 mm
Kerb weight	1215 kg
Max. allowed weight	1813 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 13/3

Number of axles 2

Engine number D292824