



report date: 2024-03-28

General information

Make	VOLVO
Model	V70 D5 SE LUX
Colour	Blue
Year of manufacture	2012
Top speed	137 mph
0 - 60 mph	8.1 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	205 BHP
Max. torque	420 Nm at 1.500 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	29.7 mpg
Consumption extra urban	52.3 mpg
Consumption combined	40.9 mpg
CO2 emission	164 g/km
CO2 label	G





Internet history

Entry 1

Date	2022-01-08
Pictures	9
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-01-27
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	16
Total items failed	3

MOT #13	2024-01-23 10:34
MOT test number	838333303994
Result	✓ Passed
Next expiry date	2025-01-27
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge Worn on inner edge (5.2.3 (e))

MOT #12	2023-01-23 12:36
MOT test number	239446957230
Result	✓ Passed

MOT #11	2022-01-15 15:03
MOT test number	497380341296
Result	✓ Passed

MOT #10	2022-01-15 15:03
MOT test number	450554950339
Result	✗ Failed
Pass with rectification	Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

MOT #9	2021-01-22 09:03
MOT test number	190118318257
Result	✓ Passed

**MOT #8** 2020-01-21 10:45**MOT test number** 977195507556**Result** ✓ Passed**MOT #7** 2019-01-14 10:09**MOT test number** 859995024410**Result** ✓ Passed**MOT #6** 2018-01-09 15:40**MOT test number** 168755871075**Result** ✓ Passed**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**MOT #5** 2018-01-09 10:02**MOT test number** 813967775232**Result** ✗ Failed**Advice** Rear brake discs worn**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Front brake discs worn**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #4** 2017-01-18 10:22**MOT test number** 357683110585**Result** ✓ Passed

**MOT #3** 2016-01-14 11:57**MOT test number** 230462071706**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear tyre wall cut**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2016-01-13 10:11**MOT test number** 175574235542**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear tyre wall cut**Fail** Nearside Side repeater not working and damage (1.4.A.2c)**MOT #1** 2015-01-05 16:52**MOT test number** 685335505064**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Cuts on offside front tyre wall**Advice** Nearside Side repeater damaged, but still visible from a reasonable distance (1.4.A.2e)**Notice** Engine covers fitted obscuring some components in the engine bay



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
27 January 2025

Tax status	Valid until 1 February
Days left	278
MOT expiry date	27 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	LP61LSK
Plate since	2019-09-28
Current registration	LP61LSK
Plate since	2019-09-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-01-27
Last registration	2024-01-23
Complete history	See info



Registration #1	2012-01-27	27 mi
Registration #2	2015-01-05	28.167 mi
Registration #3	2016-01-13	37.403 mi
Registration #4	2016-01-14	37.404 mi
Registration #5	2017-01-18	44.972 mi
Registration #6	2018-01-09	50.382 mi
Registration #7	2018-01-09	50.383 mi
Registration #8	2019-01-14	57.527 mi
Registration #9	2019-01-20	58.337 mi
Registration #10	2019-01-20	58.337 mi
Registration #11	2019-01-20	58.337 mi
Registration #12	2019-01-20	58.337 mi
Registration #13	2019-01-20	58.337 mi
Registration #14	2019-01-20	58.337 mi
Registration #15	2019-01-20	58.337 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	88%
Children	84%
Pedestrian	43%
Safety systems	71%
Overall rating	77%
Video	see crash video



Dimensions & weight

Width	1861 mm
Height	1547 mm
Length	4823 mm
Wheel base	2816 mm
Kerb weight	1773 kg
Max. allowed weight	2310 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1109863