



report date: 2024-03-29

General information

Make	VOLVO
Model	S60 D5 SE EU4
Colour	Blue
Year of manufacture	-
Top speed	140 mph
0 - 60 mph	8.1 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	185 BHP
Max. torque	400 Nm at 2.000 rpm
Cylinders	5
Fuel type	Diesel
Consumption city	27.7 mpg
Consumption extra urban	47.1 mpg
Consumption combined	37.7 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-09-30
Pictures	17
Listing price	<a href="#">View report</a>



source: autotrader.co.uk

**MOT history**

<b>MOT #23</b>	2022-04-21 08:25
<b>MOT test number</b>	829168919650
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2023-04-20
<b>Advice</b>	Rear Shock absorbers has slight external damage to the casing (5.3.2 (b))

<b>MOT #22</b>	2022-04-14 08:02
<b>MOT test number</b>	255241596689
<b>Result</b>	✗ Failed
<b>Advice</b>	Offside Front Coil spring corroded (5.3.1 (b) (i))
<b>Fail</b>	Nearside Rear Lower Shock absorbers has an excessively worn bush (5.3.2 (c))
<b>Advice</b>	Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
<b>Advice</b>	Offside Rear Service brake requirements only just met. It would appear that the braking system requires adjustment or repair (1.2.1 (c))
<b>Advice</b>	Anti-roll bar pin or bush worn but not resulting in excessive movement both rears (5.3.4 (a) (i))
<b>Advice</b>	Nearside Front Coil spring corroded (5.3.1 (b) (i))
<b>Advice</b>	Rear Exhaust has a minor leak of exhaust gases back box (6.1.2 (a))
<b>Advice</b>	Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
<b>Fail</b>	Nearside Rear Suspension arm insecurely attached (5.3.3 (a) (i))
<b>Advice</b>	Anti-roll bar pin or bush worn but not resulting in excessive movement both fronts (5.3.4 (a) (i))
<b>Advice</b>	Nearside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #21**

2022-04-08 15:13

**MOT test number**

514302989869

**Result****✗ Failed**

- Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Advice** Anti-roll bar pin or bush worn but not resulting in excessive movement both rears (5.3.4 (a) (i))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Fail** Brake lever has insufficient reserve travel (1.1.2 (a))
- Advice** Anti-roll bar pin or bush worn but not resulting in excessive movement both fronts (5.3.4 (a) (i))
- Fail** Offside Rear Lower Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Rear Exhaust has a minor leak of exhaust gases back box (6.1.2 (a))

**MOT #20**

2021-04-14 10:15

**MOT test number**

669886392106

**Result****✓ Passed**

- Advice** Top/Bottom covers fitted
- Advice** Offside Front Inner Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Inner Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Top/Bottom covers fitted
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #19** 2020-08-10 09:56**MOT test number** 294353785792**Result** ✓ Passed**MOT #18** 2019-07-24 14:45**MOT test number** 561236268049**Result** ✓ Passed**MOT #17** 2019-07-24 11:09**MOT test number** 252834750040**Result** ✗ Failed**Fail** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #16** 2018-08-20 14:01**MOT test number** 636196111086**Result** ✓ Passed**MOT #15** 2018-08-13 09:22**MOT test number** 857974900249**Result** ✗ Failed**Fail** Front Brakes imbalanced across an axle (1.2.1 (b) (i))**Fail** Hydraulic fluid leaking excessively (8.4.1 (a) (i))**MOT #14** 2017-08-16 14:39**MOT test number** 661070557443**Result** ✓ Passed

**MOT #13** 2016-08-15 10:52**MOT test number** 701085540974**Result** ✓ Passed**MOT #12** 2016-08-13 09:07**MOT test number** 198004997065**Result** ✗ Failed**Fail** Front brake application uneven (3.7.B.2)**MOT #11** 2015-08-18 09:41**MOT test number** 966537200831**Result** ✓ Passed**MOT #10** 2015-08-17 00:00**MOT test number** 868940976632**Result** ✗ Failed**Fail** Rear Exhaust system not adequately supported (7.1.1)**Fail** Nearside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**MOT #9** 2014-08-18 14:09**MOT test number** 415780434217**Result** ✓ Passed**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #8**

2014-03-26 16:02

**MOT test number**

525975384033

**Result**

✓ Passed

- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #7**

2014-03-26 16:02

**MOT test number**

759235884021

**Result**

✗ Failed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Pass with rectification** Nearside Rear Lower Rear position lamp(s) not working (1.1.A.3b)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #6**

2013-03-25 09:55

**MOT test number**

399824683060

**Result**

✓ Passed

- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)





**MOT #5** 2012-03-27 10:43**MOT test number** 366817882029**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Centre exhaust bracket deteriorated but still supporting exhaust**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2011-03-21 10:50**MOT test number** 649090281096**Result** ✓ Passed**MOT #3** 2010-03-03 11:26**MOT test number** 644972260019**Result** ✓ Passed**MOT #2** 2009-03-13 15:24**MOT test number** 971452479040**Result** ✓ Passed**MOT #1** 2009-03-13 11:23**MOT test number** 600572679015**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2006-03-27
Last registration	2022-04-21
Complete history	<a href="#">See info</a>



Registration #1	2006-03-27	23 mi
Registration #2	2009-03-13	22.885 mi
Registration #3	2009-03-13	22.886 mi
Registration #4	2010-03-03	28.892 mi
Registration #5	2011-03-21	34.158 mi
Registration #6	2012-03-27	44.177 mi
Registration #7	2013-03-25	54.642 mi
Registration #8	2014-03-26	64.588 mi
Registration #9	2014-08-18	67.593 mi
Registration #10	2015-08-17	72.973 mi
Registration #11	2015-08-18	72.973 mi
Registration #12	2016-08-13	80.643 mi
Registration #13	2016-08-13	80.643 mi
Registration #14	2016-08-13	80.643 mi
Registration #15	2016-08-13	80.643 mi
Registration #16	2016-08-13	80.643 mi
Registration #17	2016-08-13	80.643 mi
Registration #18	2016-08-13	80.643 mi
Registration #19	2016-08-13	80.643 mi
Registration #20	2016-08-13	80.643 mi
Registration #21	2016-08-13	80.643 mi
Registration #22	2016-08-13	80.643 mi
Registration #23	2016-08-13	80.643 mi
Registration #24	2016-08-13	80.643 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2050 mm
Height	1428 mm
Length	4603 mm
Wheel base	2715 mm
Kerb weight	1519 kg
Max. allowed weight	2050 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	417262