





General information

| Make | HONDA |
|---------------------|----------------|
| Model | JAZZ I-VTEC EX |
| Colour | Orange |
| Year of manufacture | 2017 |
| Top speed | 113 mph |
| 0 - 60 mph | 12.3 seconds |
| • | |
| Gearbox | 1 speed CVT |

Engine & fuel consumption

| Power | 101 BHP |
|-------------------------|---------------------|
| Max. torque | 123 Nm at 5.000 rpm |
| Engine capacity | 1.318 сс |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 51.4 mpg |
| Consumption extra urban | 62.8 mpg |
| Consumption combined | 57.7 mpg |
| CO2 emission | 114 g/km |
| CO2 label | С |







Internet history

| Entry 1 | |
|---------------|-------------|
| Date | 2021-01-31 |
| Pictures | 10 |
| Listing price | View report |



source: autoonline.co.uk



MOT history

| MOT expiry date | 2025-02-13 |
|--------------------|------------|
| MOT pass rate | 63 % |
| MOT passed | 5 |
| Failed MOT tests | 3 |
| Total advice items | 12 |
| Total items failed | 4 |

| MOT #8 | 2024-02-14 04:28 |
|------------------|------------------|
| MOT test number | 671938569770 |
| Result | ✓ Passed |
| Next expiry date | 2025-02-13 |

| MOT #7 | 2024-02-09 04:22 |
|---|------------------|
| MOT test number | 422038773712 |
| Result | 🗙 Failed |
| Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Fail Nearside Front Headlamp aim too high (4.1.2 (a)) | |

| MOT #6 | | 2023-07-18 16:26 |
|----------|--|------------------|
| MOT test | number | 910653837675 |
| Result | | ✓ Passed |
| Advice | Brake disc worn, but not excessively all round (lipped) (1.1.14 (a) (i)) | |
| Advice | Tyre worn close to legal limit/worn on edge both front worn on edges (5.2.3 (e)) | |
| Advice | Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |



| MOT #5 | 2023-07-11 15:11 | |
|---|------------------|--|
| MOT test number | 998409947386 | |
| Result | 🗙 Failed | |
| Fail Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) | | |
| Advice Tyre worn close to legal limit/worn on edge both front worn on edges (5.2.3 (e)) | | |
| Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) | | |
| Advice Brake disc worn, but not excessively all round (lipped) (1.1.14 (a) (i)) | | |
| Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | | |

| MOT #4 | 2022-07-27 15:05 |
|---|------------------|
| MOT test number | 832792480153 |
| Result | ✓ Passed |
| Advice Front Brake pad(s) wearing thin visual (1.1.13 (a) (ii)) | |

| MOT #3 | 2022-07-26 13:21 |
|--|------------------|
| MOT test number | 795118817481 |
| Result | 🗙 Failed |
| FailParking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))AdviceFront Brake pad(s) wearing thin visual (1.1.13 (a) (ii)) | |

| MOT #2 | | 2021-07-21 13:39 |
|------------------------|---|------------------|
| MOT test number | | 546502259714 |
| Result | | ✓ Passed |
| Minor Offside Windscre | een wiper blade defective (3.4 (b) (i)) | |
| Minor Nearside Windso | creen wiper blade defective (3.4 (b) (i)) | |





| MOT #1 | 2020-08-07 15:40 |
|-----------------|------------------|
| MOT test number | 809784121657 |
| Result | ✓ Passed |



Tax & MOT check

| Taxed Tax due: 1 August 2024 | ✓ MOT Expires: 13 February 2025 |
|------------------------------------|--|
| Tax status | Valid until 1 August |
| Days left | 93 |
| MOT expiry date | 13 February 2025 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|-------------------------------|------------|
| Band | G |
| First licence fee (12 months) | £ 210,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |





Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|--------|
| Date | |
| Category | Lamp |
| Туре | |
| Damage 2 | AMPL |
| Date | |
| Date | OLE |
| Category | L'ESN' |
| Туре | |

Extra HONDA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 10.200 |

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| and the second sec | |
|--|-------------|
| ************ | |
| ******** | |
| ****** | |
| *********** | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this HONDA had different number plat | es. |
| Number of plates | , |
| Current registration | |
| Plate since | |
| Current registration | |
| Plate since | |
| | More info > |





Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HONDA is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |


More info \rightarrow





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 10 |
| First mileage registration | 2017-09-15 |
| Last registration | 2024-02-14 |
| Complete history | See info |



| Registration #1 | 2017-09-15 | 20 mi |
|------------------------------------|------------|--------------------------|
| Registration #2 | 2020-08-07 | 14.606 mi |
| Registration #3 | | 11.177 esi |
| Registration #4 | 2021-07-21 | 18.098 mi |
| Registration #5 | 2022-07-26 | 24.849 mi |
| Registration #6 | | 11.117 esi |
| Registration #7 | | |
| | | |
| Registration #8 | | 10.000 mi |
| Registration #8 Registration #9 | | 11.117 est 11.117 est |

More info >





Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 93% |
| Children | 85% |
| Pedestrian | 73% |
| Safety systems | 71% |
| Overall rating | 83% |
| Video | see crash video |



| Dimensions & weight | |
|--|-------------------------------|
| Width | 1694 mm |
| Height | 1550 mm |
| Length | 3995 mm |
| Wheel base | 2530 mm |
| Kerb weight | 1132 kg |
| Max. allowed weight | 1605 kg |
| | |
| Additional information | |
| Additional information Fuel tank capacity | 40 |
| | 40 l Multi-Point Injection |
| Fuel tank capacity | |
| Fuel tank capacity Fuel delivery | Multi-Point Injection |
| Fuel tank capacity Fuel delivery Number of doors | Multi-Point Injection 5 |