



report date: 2024-03-29

General information

Make	NISSAN
Model	NAVARA DCI ACENTA 4X4 DCB
Colour	White
Year of manufacture	2011
Top speed	112 mph
0 - 60 mph	10.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	188 BHP
Max. torque	450 Nm at 2.000 rpm
Engine capacity	2.488 cc
Cylinders	4
Fuel type	Diesel
Consumption city	26.4 mpg
Consumption extra urban	39.2 mpg
Consumption combined	33.2 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-05-25
Pictures	24
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-06-29
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	41
Total items failed	6

MOT #16	2023-05-31 15:01
---------	------------------

MOT test number	350906119228
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-06-29
------------------	------------

- Advice** Nearside Front Lower Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Exhaust has a minor leak of exhaust gases middle on the flange (6.1.2 (a))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Chassi very rusty
- Advice** Central Front Oil leak, but not excessive engine area (8.4.1 (a) (i))
- Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Engine cover and belly pan fitted

**MOT #15**

2022-06-29 09:27

MOT test number

735837836246

Result

✓ Passed

Minor Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Upper Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #14**

2021-06-30 11:14

MOT test number

727417518738

Result

✓ Passed

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #13**

2021-06-23 10:37

MOT test number

118605690859

Result

✗ Failed

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MAJOR** Nearside Rear Integral body structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting (6.2.2 (d) (i))**MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MAJOR** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

**MOT #12** 2020-06-04 08:08**MOT test number** 283306847201**Result** ✓ Passed**Advice** Rear exhaust box corroded but not leaking exhaust gasses**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #11** 2019-06-08 07:39**MOT test number** 402351213234**Result** ✓ Passed**MOT #10** 2019-05-29 13:41**MOT test number** 220760064142**Result** ✗ Failed**MAJOR** Offside Rear Brake pipe excessively corroded (1.1.11 (c))**MAJOR** Nearside Exhaust system insecure centre (6.1.2 (a))**MAJOR** Nearside Rear Brake pipe excessively corroded (1.1.11 (c))**MAJOR** Nearside Rear Exhaust system insecure (6.1.2 (a))**MAJOR** Oil leaking excessively from engine (8.4.1 (a) (i))**MOT #9** 2019-03-25 15:49**MOT test number** 731428577930**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #8** 2019-03-20 14:21**MOT test number** 925032016448**Result** ✗ Failed

MAJOR Exhaust emissions test aborted because smoke levels are significantly in excess of the specified limit values (8.2.2.2 (f))

MAJOR Offside Rear Leaf spring fractured (5.3.1 (b) (i))

DANGEROUS Offside Rear Inner Tyre has ply or cords exposed full side wall, broken spring rubbing on tyre (5.2.3 (d) (ii))

MAJOR Rear Brakes imbalanced across an axle 90% nearside poor. (1.2.1 (b) (i))

MAJOR Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))

MAJOR Nearside Rear Leaf spring fractured (5.3.1 (b) (i))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))

MOT #7 2018-03-02 15:08**MOT test number** 733001430692**Result** ✓ Passed**MOT #6** 2018-03-02 13:25**MOT test number** 891015444783**Result** ✓ Passed**MOT #5** 2018-03-02 12:20**MOT test number** 274970761827**Result** ✗ Failed

Fail Rear Brakes imbalanced across an axle (3.7.B.5b)

Fail Rear brake application uneven near-side low (3.7.B.2)



MOT #4	2016-12-15 14:06
MOT test number	639098259638
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit inner edge (4.1.E.1)

MOT #3	2016-12-15 11:52
MOT test number	400374709763
Result	✗ Failed
Fail	Rear Brakes imbalanced across an axle Axle 2 (3.7.B.5b)
Fail	Rear Brakes imbalanced across an axle 73% nearside very low, adjustment maybe run off (3.7.B.5b)
Fail	Parking brake: efficiency below requirements (3.7.B.7)
Advice	Nearside Front Tyre worn close to the legal limit inner edge (4.1.E.1)
Fail	Nearside Rear rear brake recording little or no effort (3.7.B.5a)

MOT #2	2015-10-14 11:24
MOT test number	163943708191
Result	✓ Passed

MOT #1	2014-11-11 13:48
MOT test number	617315514320
Result	✓ Passed



Tax & MOT check

✗
Untaxed

Tax expired:
24 March 2024

✓
MOT

Expires:
29 June 2024

Tax status

Expired at 24 March 2024

Days left

36 days too late

MOT expiry date

29 June 2024

Full MOT history

[See MOT history](#)



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2011-03-04
Last registration	2023-05-31
Complete history	See info



Registration #1	2011-03-04	27 mi
Registration #2	2014-11-11	37.153 mi
Registration #3	2015-10-14	40.988 mi
Registration #4	2016-12-15	54.824 mi
Registration #5	2016-12-15	54.825 mi
Registration #6	2018-03-02	68.489 mi
Registration #7	2018-03-02	68.490 mi
Registration #8	2018-03-02	68.491 mi
Registration #9	2019-03-20	80.372 mi
Registration #10	2019-03-20	80.372 mi
Registration #11	2019-03-20	80.372 mi
Registration #12	2019-03-20	80.372 mi
Registration #13	2019-03-20	80.372 mi
Registration #14	2019-03-20	80.372 mi
Registration #15	2019-03-20	80.372 mi
Registration #16	2019-03-20	80.372 mi
Registration #17	2019-03-20	80.372 mi
Registration #18	2019-03-20	80.372 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1848 mm
Height	1905 mm
Length	5296 mm
Kerb weight	2085 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Engine number	81893B