




report date: 2024-03-29

General information

Make	VOLVO
Model	C30 D DRIVE SE LUX
Colour	White
Year of manufacture	2011
Top speed	118 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	57.7 mpg
Consumption extra urban	83.1 mpg
Consumption combined	72.4 mpg
CO2 emission	99 g/km
CO2 label	A





Internet history

Entry 1

Date	2021-12-09
Pictures	55
Listing price	View report



AA This dealer has signed up to our **Dealer Promise.**

- Free history check
- 6 months (minimum) MOT
- Free 12 months Breakdown cover

aacars.com 



source: autotrader.co.uk



MOT history

MOT expiry date	2024-05-09
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	27
Total items failed	7

MOT #12 2023-05-10 12:19

MOT test number 589027689194

Result ✓ Passed

Next expiry date 2024-05-09

Advice Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))

MOT #11 2021-12-16 14:18

MOT test number 101102999767

Result ✓ Passed

Advice Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))

MOT #10 2021-01-14 10:28

MOT test number 637301027573

Result ✓ Passed

MOT #9 2021-01-13 19:45

MOT test number 943556478335

Result ✗ Failed

MAJOR Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MAJOR Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))



MOT #8 2019-07-24 11:49

MOT test number 818771541084

Result ✓ Passed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Exhaust corroding

MOT #7 2018-07-25 14:01

MOT test number 642943223726

Result ✓ Passed

- Advice** Exhaust corroding
- Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #6 2017-07-26 09:47

MOT test number 134309078773

Result ✓ Passed

- Advice** Rear tyres perishing
- Advice** Exhaust corroding
- Advice** Offside front tyre bald on inner edge

MOT #5 2016-07-14 09:27

MOT test number 692332783210

Result ✓ Passed

- Advice** Exhaust corroding
- Advice** Offside Front tyre low on inner edge



MOT #4 2015-07-07 14:06

MOT test number 905868985183

Result ✔ Passed

- Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)
- Notice** Engine covers fitted obscuring some components in the engine bay
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Notice** Under-trays fitted obscuring some underside components

MOT #3 2015-07-07 10:50

MOT test number 218768385110

Result ✘ Failed

- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Notice** Engine covers fitted obscuring some components in the engine bay
- Fail** Nearside Front position lamp(s) not working (1.1.A.3b)
- Notice** Under-trays fitted obscuring some underside components
- Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)
- Notice** 5/5/4 - 4/4/4 - 5/5/5 - 5/4/4 - Spr S/saver

MOT #2 2014-07-29 12:45

MOT test number 375850614476

Result ✔ Passed

- Notice** Engine covers fitted obscuring some components in the engine bay
- Notice** Under-trays fitted obscuring some underside components



MOT #1 2014-07-29 12:17

MOT test number 237340614206

Result ✗ Failed

Fail Nearside Front position lamp(s) not working (1.1.A.3b)

Notice Under-trays fitted obscuring some underside components

Fail Offside Headlamp aim too high (1.8)

Notice 6/6/6 - 6/6/6 - 6/6/5 - 5/4/5 - Spr s/saver

Fail Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

Fail Nearside Registration plate lamp not working (1.1.C.1d)

Fail Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)

Notice Engine covers fitted obscuring some components in the engine bay

Fail Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)



Tax & MOT check

✓
Taxed

Tax due:
1 January 2025

✓
MOT

Expires:
9 May 2024

Tax status Valid until 1 January

Days left 246

MOT expiry date 9 May 2024

Full MOT history [See MOT history](#)

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable




Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled. If not, and you buy this VOLVO then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this VOLVO is financed.


Finance company	REDACTED
Date of agreement	REDACTED
Agreement type	REDACTED
Agreement term	REDACTED
Agreement number	REDACTED
Contact info	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-07-27
Last registration	2023-05-10
Complete history	See info



Registration #1	2011-07-27	26 mi
Registration #2	2014-07-29	49.196 mi
Registration #3	2014-07-29	49.196 mi
Registration #4	2015-07-07	60.540 mi
Registration #5	2015-07-07	60.540 mi
Registration #6	2016-07-14	67.991 mi
Registration #7	2017-07-26	75.811 mi
Registration #8	2019-05-10	95.277 mi
Registration #9	2019-05-10	95.277 mi
Registration #10	2019-05-10	95.277 mi
Registration #11	2019-05-10	95.277 mi
Registration #12	2019-05-10	95.277 mi
Registration #13	2019-05-10	95.277 mi
Registration #14	2019-05-10	95.277 mi

[More info >](#)



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1437 kg
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1760212