





report date: 2024-03-28

General information

Make	CITROEN
Model	DS3 E-HDI FLAIR ETG6
Colour	Silver
Year of manufacture	2015
Top speed	114 mph
0 - 60 mph	10.7 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	91 BHP
Max. torque	230 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	72.4 mpg
Consumption extra urban	80.7 mpg
Consumption combined	78.5 mpg
CO2 emission	94 g/km
CO2 label	A



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history


Entry 1

Date 2021-06-13

Pictures 14

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

NAC	\Т	بہا: حا	L
MC	ノレ	nis	tory

MOT expiry date	2024-06-16
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	13
Total items failed	2

MOT #10	2023-06-13 09:17	
MOT test number	510114660705	
Result	✓ Passed	
Next expiry date	2024-06-16	
Advice Nearside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))		
Advice Rear Brake disc worn, but not excessively (1.1.14 (a) (i))		

MOT #9	2022-06-10 08:33
MOT test number	418025014933
Result	✓ Passed
MOT #8	2021-06-17 15:43
MOT test number	256742028365
Result	✓ Passed
Advice Nearside Drive shaft joint worn, but not excessively (6.1.7 (c) (i))	

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #7 2021-06-16 16:32 529461632512 **MOT** test number Result **★** Failed **Advice** Rear Exhaust mounting defective (6.1.2 (a)) Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Advice Offside Front Service brake fluctuating, but not excessively (1.2.1 (e)) Offside Front Coil spring fractured or broken (5.3.1 (b) (i)) **MAJOR** Advice Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i)) Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) **MAJOR** Nearside Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #6		2020-10-30 13:34
MOT test number		162491548167
Result		✓ Passed
MOT #5		2020-10-30 13:34
MOT test number		767885723357
Result		X Failed
Pass with rectification	Central Rear Exhaust system insecure (6.1.2 (a))	

MOT #4	2019-11-05 11:01
MOT test number	677792840165
Result	✓ Passed
Advice Nearside Rear No free movement on brake callaper	

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #3 2019-11-05 11:01

MOT test number 520366452199

Result X Failed

Advice Nearside Rear No free movement on brake callaper

Pass with rectification Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #2 2018-11-13 09:46

MOT test number 799884683866

Result ✓ Passed

MOT #1 2017-11-28 17:52

MOT test number 520013058606

Result \rightarrow Passed

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 June
Days left	34
MOT expiry date	16 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



SG15XZE report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	
HARMAN CO. C.	

	More info >
Plate changes	
See in this check if this CITROEN had different number plates.	
Number of plates	,
Current registration	NIE UK
Plate since	
Current registration	UK ZIZ
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-03-22
Last registration	2023-06-13
Complete history	See info



Registration #1	2015-03-22	12 mi
Registration #2	2017-11-28	19.333 mi
Registration #3	2018-11-13	30.548 mi
Registration #4	2019-11-05	44.730 mi
Registration #5	2019-11-05	44.730 mi
Registration #6	2020-10-30	57.272 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		n

More info >

CarCheck.co.uk page 11/12



SG15XZE report date: 2024-03-28

Safety ratings

NCAP rating	****
Adult	90%
Children	85%
Pedestrian	43%
Safety systems	97%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1946 mm
Height	1540 mm
Length	4157 mm
Wheel base	2595 mm
Kerb weight	1055 kg
Max. allowed weight	1605 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	JBFN0073270

CarCheck.co.uk page 12/12