



report date: 2024-03-29

General information

Make	FIAT
Model	PUNTO EVO ACTIVE
Colour	Red
Year of manufacture	2010
Top speed	103 mph
0 - 60 mph	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	77 BHP
Max. torque	115 Nm at 3.250 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	49.6 mpg
CO2 emission	132 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-01-29
Pictures	10
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2025-04-17
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	22
Total items failed	8

MOT #16 2024-04-16 07:53

MOT test number 573677218121

Result ✓ Passed

Next expiry date 2025-04-17

Advice Nearside Front Tyre worn close to legal limit/worn on edge worn on the outer edge (5.2.3 (e))

Advice Nearside Front Play in steering rack inner joint(s)

Advice Oil leak, but not excessive Oil Filter (8.4.1 (a) (i))

Advice Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))

MOT #15 2023-04-18 11:15

MOT test number 206829452864

Result ✓ Passed

Advice Offside plastic cover worn + loose

Advice Rear Exhaust mounting defective (6.1.2 (a))

MOT #14 2022-04-14 11:17

MOT test number 162068175356

Result ✓ Passed

Minor Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice All 4 road springs corroded

**MOT #13** 2021-04-15 15:42**MOT test number** 586858960643**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Nearside Rear shock absorber corroded

MOT #12 2020-03-04 16:15**MOT test number** 490605335658**Result** ✓ Passed**MOT #11** 2020-02-27 10:09**MOT test number** 289294511432**Result** ✗ Failed

- MAJOR** Offside Rear Shock absorbers has an excessively worn bush (5.3.2 (c))
- MAJOR** Offside Front Position lamp not working (4.2.1 (a) (ii))
- MAJOR** Nearside Headlamp aim too low (4.1.2 (a))
- MAJOR** Nearside Front Service brake excessively fluctuating (1.2.1 (e))
- MAJOR** Exhaust has a major leak of exhaust gases (6.1.2 (a))
- MAJOR** Offside Headlamp aim too high (4.1.2 (a))

MOT #10 2019-02-12 16:01**MOT test number** 292889121783**Result** ✓ Passed

**MOT #9** 2019-02-12 14:49**MOT test number** 147638083378**Result** ✗ Failed**MAJOR** Offside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))**MAJOR** Nearside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))**MAJOR** Nearside Rear Shock absorbers damaged to the extent that it does not function Outer casing (5.3.2 (b))**MOT #8** 2018-03-01 08:44**MOT test number** 602139891379**Result** ✓ Passed**MOT #7** 2018-02-19 16:38**MOT test number** 154794366050**Result** ✗ Failed**Fail** Registration plate lamp not working (1.1.C.1d)**Fail** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)**Fail** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Fail** Nearside Headlamp aim too low (1.8)**MOT #6** 2017-02-02 16:43**MOT test number** 549885126910**Result** ✓ Passed

**MOT #5** 2017-02-01 08:10**MOT test number** 381407873047**Result** ✗ Failed**Fail** Nearside Stop lamp not working (1.2.1b)**Fail** Offside Stop lamp not working (1.2.1b)**MOT #4** 2016-02-27 11:08**MOT test number** 674380405601**Result** ✓ Passed**MOT #3** 2015-03-02 12:14**MOT test number** 897601065080**Result** ✓ Passed**MOT #2** 2015-03-02 12:14**MOT test number** 345111165067**Result** ✗ Failed**Pass with rectification** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #1** 2013-07-24 16:24**MOT test number** 339725803406**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
17 April 2025

Tax status	Valid until 1 April
Days left	336
MOT expiry date	17 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-07-27
Last registration	2024-04-16
Complete history	See info



Registration #1	2010-07-27	15 mi
Registration #2	2013-07-24	24.342 mi
Registration #3	2015-03-02	27.915 mi
Registration #4	2016-02-27	38.994 mi
Registration #5	2017-02-01	48.927 mi
Registration #6	2017-02-02	48.927 mi
Registration #7	2018-02-19	50.113 mi
Registration #8	2018-03-01	50.131 mi
Registration #9	2019-02-12	52.747 mi
Registration #10	2019-05-29	55.377 mi
Registration #11	2019-05-29	55.377 mi
Registration #12	2019-05-29	55.377 mi
Registration #13	2019-05-29	55.377 mi
Registration #14	2019-05-29	55.377 mi
Registration #15	2019-05-29	55.377 mi
Registration #16	2019-05-29	55.377 mi
Registration #17	2019-05-29	55.377 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4065 mm
Wheel base	2510 mm
Kerb weight	1040 kg
Max. allowed weight	1600 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	5839116