



HY03NEJ

report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	BEETLE
Colour	Blue
Year of manufacture	-
Gearbox	-

Engine & fuel consumption

Fuel type	Diesel
-----------	--------



LABEL UNKNOWN



Internet history

Entry 2

Date	2021-10-24
Pictures	12
Listing price	View report



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 1

Date	2021-10-24
Pictures	23
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT #25	2022-09-12 10:23
MOT test number	110821948547
Result	✓ Passed
Next expiry date	2023-09-11
Advice	Nearside Front Lower Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
Advice	N/s outer cv gator worn
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

MOT #24	2020-11-19 16:39
MOT test number	765114418520
Result	✓ Passed
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Offside Front Suspension component mounting prescribed area is corroded but not considered excessive sill end (5.3.6 (a) (i))
Advice	Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))

MOT #23	2020-11-19 08:44
MOT test number	250229054483
Result	✗ Failed
Fail	Nearside Rear Outer Suspension component mounting prescribed area excessively corroded significantly reducing structural strength sill (5.3.6 (a) (i))
Advice	Offside Front Suspension component mounting prescribed area is corroded but not considered excessive sill end (5.3.6 (a) (i))
Advice	Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Fail	Nearside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength sill end (5.3.6 (a) (i))



MOT #22	2019-12-13 11:33
MOT test number	543246860644
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #21	2019-12-11 10:06
MOT test number	215109609388
Result	✗ Failed
Fail	Battery insecure and likely to fall from carrier (4.13 (a) (ii))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Nearside Front Front passenger door cannot be opened from outside the vehicle (6.2.3 (a))
Fail	Rear Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))
Fail	Offside Rear Inner Suspension component mounting prescribed area excessively corroded significantly reducing structural strength sill (5.3.6 (a) (i))
Fail	Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

MOT #20	2018-11-13 16:54
MOT test number	873448005269
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #19**

2018-11-13 10:17

MOT test number

775779765505

Result**✗ Failed**

- Fail** Nearside Front Suspension arm pin or bush likely to become detached (5.3.4 (a) (ii))
- Fail** Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Minor** Brake fluid warning lamp defective (1.1.10 (f))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Front Exhaust system insecure (6.1.2 (a))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Nearside Front Position lamp not working (4.2.1 (a))
- Fail** Offside Front Suspension arm pin or bush likely to become detached (5.3.4 (a) (ii))
- Fail** Offside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Front Exhaust has a major leak of exhaust gases (6.1.2 (a))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #18

2017-11-08 09:26

MOT test number

194502024216

Result**✓ Passed****MOT #17**

2016-11-15 13:05

MOT test number

148770088168

Result**✓ Passed**

**MOT #16** 2016-11-14 13:36**MOT test number** 538423466610**Result** ✗ Failed**Fail** Front Tyre tread depth below requirements of 1.6mm both (4.1.E.1)**MOT #15** 2016-04-29 08:46**MOT test number** 546523684496**Result** ✓ Passed**MOT #14** 2015-04-11 14:49**MOT test number** 348881405144**Result** ✓ Passed**MOT #13** 2015-04-09 14:01**MOT test number** 468929995052**Result** ✗ Failed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Fail** Nearside Rear Vehicle structure has excessive corrosion, seriously affecting its strength within 30cm of the body mountings (6.1.B.2)**Notice** Oil leak**Pass with rectification** Offside Front Headlamp aim too low (1.8)**MOT #12** 2014-02-14 11:44**MOT test number** 495385044051**Result** ✓ Passed

**MOT #11** 2013-01-28 16:27**MOT test number** 178338123495**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #10** 2013-01-28 12:26**MOT test number** 385708823060**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front coil spring fractured (2.4.C.1a)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #9** 2012-02-08 14:33**MOT test number** 766149832095**Result** ✓ Passed**MOT #8** 2011-02-21 15:57**MOT test number** 918002751027**Result** ✓ Passed**MOT #7** 2010-04-10 10:53**MOT test number** 622280400116**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #6** 2009-04-02 11:45**MOT test number** 973552099047**Result** ✓ Passed**MOT #5** 2009-04-01 12:03**MOT test number** 403951099064**Result** ✗ Failed**Fail** Nearside Rear coil spring incomplete (2.4.C.1a)**MOT #4** 2008-03-14 12:40**MOT test number** 461564778015**Result** ✓ Passed**MOT #3** 2007-04-02 11:56**MOT test number** 663882097096**Result** ✓ Passed**MOT #2** 2006-03-06 11:45**MOT test number** 151085766076**Result** ✓ Passed**MOT #1** 2006-03-06 11:22**MOT test number** 163275966034**Result** ✗ Failed**Notice** Advise plastic engine under tray fitted**Fail** Rear registration plate deteriorated (6.3.1d)**Notice** Advise plastic engine cover fitted**Fail** Front Windscreen washer provides insufficient washer liquid (8.2.3)



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	7
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	27
First mileage registration	2003-03-04
Last registration	2022-09-12
Complete history	See info



Registration #1	2003-03-04	16 mi
Registration #2	2006-03-06	28.858 mi
Registration #3	2006-03-06	28.858 mi
Registration #4	2007-04-02	36.769 mi
Registration #5	2008-03-14	41.726 mi
Registration #6	2009-04-01	45.769 mi
Registration #7	2009-04-02	45.769 mi
Registration #8	2010-04-10	59.400 mi
Registration #9	2011-02-21	66.511 mi
Registration #10	2012-02-08	77.559 mi
Registration #11	2013-01-28	87.622 mi
Registration #12	2013-01-28	87.622 mi
Registration #13	2014-02-14	99.517 mi
Registration #14	2015-04-09	109.170 mi
Registration #15	2016-05-20	121.377 mi
Registration #16	2016-05-20	121.377 mi
Registration #17	2016-05-20	121.377 mi
Registration #18	2016-05-20	121.377 mi
Registration #19	2016-05-20	121.377 mi
Registration #20	2016-05-20	121.377 mi
Registration #21	2016-05-20	121.377 mi
Registration #22	2016-05-20	121.377 mi
Registration #23	2016-05-20	121.377 mi
Registration #24	2016-05-20	121.377 mi
Registration #25	2016-05-20	121.377 mi
Registration #26	2016-05-20	121.377 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Additional information

Engine number NOT KNOWN