





report date: 2024-03-28

### General information

Make	RENAULT
Model	MEGANE SCENIC FIDJI 16V SCENIC
Colour	Silver
Year of manufacture	-
Top speed	115 mph
0 - 60 mph	11.2 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	110 BHP
Max. torque	148 Nm at 3.750 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	28.5 mpg
Consumption extra urban	47.9 mpg
Consumption combined	38.7 mpg



CarCheck.co.uk page 1/13



EGO3ENL report date: 2024-03-28

Internet history

Entry 1

Date 2021-06-24


Pictures 6

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

## MOT history

MOT #21		2021-06-05 14:24
MOT test	number	710825070936
Result		✓ Passed
Next expi	ry date	2022-06-07
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))		
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened bot	h (1.1.14 (a) (ii))

MOT #20		2020-06-08 09:57
MOT test	number	839981711656
Result		<b>✓</b> Passed
Advice	Offside Front Coil spring corroded (5.3.1 (b) (i))	
Advice	Front brake pads under 1/2 worn ?	
Advice	Nearside Front Coil spring corroded (5.3.1 (b) (i))	

MOT #19		2019-06-12 16:22
MOT test	number	687296150815
Result		<b>✓</b> Passed
Advice	Clutch pedal rubber worn	
Advice	Nearside Front Coil spring corroded (5.3.1 (b) (i))	
Advice	Front brake pads 1/2 worn ?	
Advice	Offside Front Coil spring corroded (5.3.1 (b) (i))	

CarCheck.co.uk page 3/13



Advice

EG03ENL

report date: 2024-03-28

MOT #18 2019-06-12 10:28 828205298125 **MOT** test number Result **★** Failed **MAJOR** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) Advice Front brake pads 1/2 worn? Advice Nearside Front Coil spring corroded (5.3.1 (b) (i)) Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Clutch pedal rubber worn Advice **MAJOR** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii)) Advice Offside Front tyre close to marker bars

MOT #17		2018-06-07 09:52
MOT test	number	198760166596
Result		✓ Passed
Advice	Nearside Front tyre close to marker bars	
Advice	Nearside wiper blade smearing	
Advice	Offside Front Coil spring corroded (5.3.1 (b) (i))	
Advice	Nearside Front Coil spring corroded (5.3.1 (b) (i))	

Offside Front Coil spring corroded (5.3.1 (b) (i))

MOT #16	2017-06-13 10:29
MOT test number	649844248825
Result	<b>✓</b> Passed
Advice Nearside Front coil spring corroded (2.4.C.1b)	
Advice Offside Front coil spring corroded (2.4.C.1b)	

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT test number

Result

Advice Offside Front coil spring corroded (2.4.C.1b)

Advice Nearside Front coil spring corroded (2.4.C.1b)

Fail Rear Tie bar/rod corroded and seriously weakened cross brace (2.4.G.1)

 MOT #14
 2016-05-31 11:19

 MOT test number
 340193226275

**Result** ✓ Passed

MOT #13 2016-05-24 15:10

**MOT test number** 786283271178

Result X Failed

**Fail** Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)

Fail Nearside Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)

**Fail** Offside Rear Tyre has ply or cords exposed (4.1.D.1b)

MOT #12 2015-06-08 13:55

**MOT test number** 757909455111

**Notice** Clutch pedal rubber worn on edge

**Notice** Both rear tyres worn on edges and spliting due to age

**MOT #11** 2014-06-10 15:55

MOT test number 655141864107

Result 

Passed

**Notice** Both rear tyres worn on edges and spliting due to age

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT #10	2014-06-10 11:13
MOT test number	878011064140
Result	<b>×</b> Failed
Fail Offside Outer Front constant velocity joint is insecure (2.5.C.1b)	
Notice Both front tyres worn on edges and spliting due to age	
Notice Center stop light inop	
Notice O/s rear tyre spliting due to age	

MOT #9	2013-05-28 12:45
MOT test number	557268643114
Result	✓ Passed
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #8	2012-05-16 14:17
MOT test number	236047032151
Result	✓ Passed
MOT #7	2012-05-16 11:40
MOT test number	229617832480
Result	<b>×</b> Failed
Fail Nearside Rear Registration plate lamp not working (1.1.C.1d)	

MOT #6	2011-06-07 10:09
MOT test number	196308251151
Result	<b>✓</b> Passed
MOT #5	2010-06-11 09:48
MOT test number	473882360113
Result	<b>✓</b> Passed

CarCheck.co.uk page 6/13



report date: 2024-03-28

MOT #4	2009-06-09 10:20
MOT test number	210660669129
Result	<b>✓</b> Passed
MOT #3	2008-06-04 11:10
MOT test number	182036158150
Result	<b>✓</b> Passed
MOT #2	2007-05-29 10:34
MOT test number	192139947126
Result	<b>✓</b> Passed
MOT #1	2006-05-15 15:39
MOT test number	821955936185
Result	✓ Passed

CarCheck.co.uk page 7/13



report date: 2024-03-28

### Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

### Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

# Owner history

e when motory	
For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full is	
*******	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this RENAULT had different number plates.	
Number of plates	
Current registration	NK NK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-28

### Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

**Contact info** 

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

## Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2003-07-12
Last registration	2021-06-05
Complete history	See info



Registration #1	2003-07-12	29 mi
Registration #2	2006-05-15	23.740 mi
Registration #3	2007-05-29	28.262 mi
Registration #4	2008-06-04	32.581 mi
Registration #5	2009-06-09	36.314 mi
Registration #6	2010-06-11	40.328 mi
Registration #7	2011-06-07	43.688 mi
Registration #8	2012-05-16	46.457 mi
Registration #9	2012-05-16	46.457 mi
Registration #10	2013-05-28	50.408 mi
Registration #11	2014-06-10	54.292 mi
		F 4 202:
Registration #12	2014-06-10	54.292 mi
Registration #12 Registration #13	2014-06-10	54.292 MI
-		54.292 MI
Registration #13		54.292 MI
Registration #13 Registration #14		54.292 MI
Registration #13 Registration #14 Registration #15		54.292 MI
Registration #13 Registration #14 Registration #15 Registration #16		54.292 MI
Registration #13 Registration #14 Registration #15 Registration #16 Registration #17		54.292 mi
Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18		54.292 MI
Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19		54.292 MI
Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20		54.292 MI
Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21		54.292 MI

More info >

CarCheck.co.uk page 12/13



EGO3ENL report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
50567	
50569	

## Safety ratings

NCAP rating	****
Video	see crash video



## Dimensions & weight

Width	1698 mm
Height	1675 mm
Length	4169 mm
Wheel base	2580 mm
Kerb weight	1250 kg

## Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Engine number	D773098

CarCheck.co.uk page 13/13