



Mercedes-Benz



report date: 2024-03-29

General information

Make	MERCEDES
Model	SLK 350
Colour	Black
Year of manufacture	2006
Top speed	155 mph
0 - 60 mph	5.5 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	268 BHP
Max. torque	350 Nm at 5.000 rpm
Engine capacity	3.498 cc
Cylinders	6
Fuel type	Petrol
Consumption city	19.9 mpg
Consumption extra urban	36.2 mpg
Consumption combined	28.0 mpg
CO2 emission	242 g/km
CO2 label	L





Internet history

Entry 1

Date	2021-08-27
Pictures	7
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2022-09-03
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	16
Total items failed	10

MOT #18	2021-08-20 15:02
MOT test number	841579611936
Result	✓ Passed
Next expiry date	2022-09-03
Advice	Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
Advice	Brake pipe corroded, covered in grease or other material both front to rears (1.1.11 (c))

MOT #17	2020-09-04 08:20
MOT test number	945064191441
Result	✓ Passed
Advice	Front Brake pipe corroded, covered in grease or other material To rears at rear x2 (1.1.11 (c))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #16	2019-06-21 10:27
MOT test number	500610726775
Result	✓ Passed

MOT #15	2018-07-05 10:29
MOT test number	777919023267
Result	✓ Passed

**MOT #14** 2018-03-06 17:28**MOT test number** 179975368133**Result** ✓ Passed**Advice** Offside Front Inner brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front Inner brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #13** 2018-03-06 11:27**MOT test number** 882350223746**Result** ✗ Failed**Advice** Offside Front Inner brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Nearside Rear Lower Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front Lower Suspension arm has excessive play in a pin/bush front lower arm bushes spilt (2.4.G.2)**Advice** Nearside Front Inner brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Offside Rear Lower Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Front Lower Suspension arm has excessive play in a pin/bush front lower arm bushes spilt (2.4.G.2)**MOT #12** 2017-03-01 12:04**MOT test number** 286240481719**Result** ✓ Passed**MOT #11** 2016-03-02 15:18**MOT test number** 191671703377**Result** ✓ Passed**Advice** Engine light on

**MOT #10** 2016-03-02 14:07**MOT test number** 395728796934**Result** ✗ Failed**Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)**Fail** Offside Rear Exhaust system not adequately supported mounting broken (7.1.1)**Advice** Engine light on**MOT #9** 2015-01-29 15:20**MOT test number** 355069425010**Result** ✓ Passed**MOT #8** 2014-10-10 11:38**MOT test number** 515213184228**Result** ✓ Passed**MOT #7** 2013-10-21 16:22**MOT test number** 367994993249**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Exhaust support brackets corroded

**MOT #6** 2013-10-21 12:15**MOT test number** 617254393226**Result** ✗ Failed**Fail** Offside Rear Direction indicator incorrect colour (1.4.A.2f)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)**Notice** Exhaust support brackets corroded**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #5** 2012-10-18 11:39**MOT test number** 798702092224**Result** ✓ Passed**MOT #4** 2012-10-18 11:39**MOT test number** 125812992289**Result** ✗ Failed**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**MOT #3** 2011-10-26 12:38**MOT test number** 329129491415**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2010-10-29 12:49**MOT test number** 972492500312**Result** ✓ Passed



MOT #1	2009-06-29 09:35
MOT test number	290740789473
Result	✓ Passed



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	 KU06OUB
Plate since	2019-06-29
Current registration	 KU06OUB
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2006-03-24
Last registration	2021-08-20
Complete history	See info



Registration #1	2006-03-24	14 mi
Registration #2	2009-06-29	20.386 mi
Registration #3	2010-10-29	36.533 mi
Registration #4	2011-10-26	44.849 mi
Registration #5	2012-10-18	51.988 mi
Registration #6	2013-10-21	57.746 mi
Registration #7	2013-10-21	57.746 mi
Registration #8	2014-10-10	65.599 mi
Registration #9	2015-01-29	66.966 mi
Registration #10	2016-03-02	77.095 mi
Registration #11	2016-03-02	77.095 mi
Registration #12	2016-03-02	77.095 mi
Registration #13	2016-03-02	77.095 mi
Registration #14	2016-03-02	77.095 mi
Registration #15	2016-03-02	77.095 mi
Registration #16	2016-03-02	77.095 mi
Registration #17	2016-03-02	77.095 mi
Registration #18	2016-03-02	77.095 mi
Registration #19	2016-03-02	77.095 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1969 mm
Height	1296 mm
Length	4089 mm
Wheel base	2430 mm
Kerb weight	1485 kg
Max. allowed weight	1780 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	27296330351207