





report date: 2022-08-13

General information

Make	MASERATI
Model	GRANSPORT V8
Colour	Blue
Year of manufacture	2007
Top speed	180 mph
0 - 60 mph	4.8 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	395 BHP
Max. torque	452 Nm at 4.500 rpm
Engine capacity	4.244 cc
Cylinders	8
Fuel type	Petrol
Consumption city	10.8 mpg
Consumption extra urban	22.6 mpg
Consumption combined	16.1 mpg
CO2 emission	400 g/km
CO2 label	М



CarCheck.co.uk page 1/13



Internet history

Entry 3

Date 2023-03-15

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 2

Date 2022-02-19

Pictures 12

Listing price <u>View report</u>










source: cargurus.co.uk

Entry 1

Date 2022-01-26

Pictures 58

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2025-01-07
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	16
Total items failed	8

MOT #16	2024-01-08 14:19
MOT test number	517053055175
Result	✓ Passed
Next expiry date	2025-01-07

MOT #15	2021-11-19 14:24
MOT test number	934954089490
Result	✓ Passed

MOT #14	2018-08-12 12:22
MOT test number	401698359115
Result	✓ Passed
Advice Engine cover and under trays fitted	

MOT #13		2017-06-02 13:14
MOT test	number	758834615513
Result		✓ Passed
Advice	Engine cover and under trays fitted	
Advice	Parking brake lever has little reserve travel (3.1.6b)	

CarCheck.co.uk page 3/13



MOT #12 2017-06-02 11:34

MOT test number 803846882708

Result X Failed

Advice Engine cover and under trays fitted

Fail Nearside Front Tyre has ply or cords exposed (4.1.D.1b)

Advice Parking brake lever has little reserve travel (3.1.6b)

Fail Offside Front Tyre has ply or cords exposed (4.1.D.1b)

MOT #11 2016-05-09 15:07

MOT test number 851397226780

Result

Passed

Advice Offside and nearside front tyres wearing on inner edges

MOT #10 2016-04-11 09:32

MOT test number 571809035945

Result × Failed

Advice Offside and nearside front tyres wearing on inner edges and close to limit

Fail Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)

Fail Exhaust emissions carbon monoxide content at idle excessive (7.3.D.4)

Fail Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)

MOT #9 2015-05-11 18:18

MOT test number 329061335107

Result ✓ Passed

Advice Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 4/13



MOT #8 2014-04-28 16:27

MOT test number 959728614164

Notice Engine covers fitted obscuring some components in the engine bay

Notice Nearsisde & Offside Front Upper & Lower Balljoints Have A Covering Over Dust Cover So Unable

To Check Condition

Notice Under-trays fitted obscuring some underside components

Notice Front And Rear Tyres Are Of Diffrent Sizes But Are The Same Across The Axles

MOT #7 2013-04-25 10:45

MOT test number 277845913402

Result ✓ Passed

MOT #6 2012-04-27 11:23

MOT test number 377878912167

Result \(\sqrt{Passed} \)

MOT #5 2012-04-27 11:23

MOT test number 689588912149

Result X Failed

Pass with rectification Offside Inner Rear position lamp(s) not working (1.1.A.3b)

MOT #4 2011-02-28 14:33

MOT test number 927829751015

Result
✓ Passed

MOT #3 2010-12-22 14:25

MOT test number 691166550357

CarCheck.co.uk page 5/13



MOT test number

Result

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT test number

473906480252

Result

Fail Nearside Front Tyre has ply or cords exposed (4.1.D.1b)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Fail Offside Front Tyre has ply or cords exposed (4.1.D.1b)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 January
Days left	278
MOT expiry date	7 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	M
Single payment (12 months)	£ 695,00,-
Single six month payment	£ 382,25,-
Total payable by 12 monthly instalments	£ 729,75,-

CarCheck.co.uk page 7/13



Damage history


Check the damage history for this MASERATI. See if, where and when this MASERATI had damage and the car repair costs. We also check if this MASERATI was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	

Category

Type



Extra MASERATI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this MASERATI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history	
For how long did the current and previous owner(s) have this MASERATI? How many own MASERATI have? Check it in the premium report and see all owner registrations. Download here.	

	More info >
Plate changes	
See in this check if this MASERATI had different number plates.	
Number of plates	,
Current registration	OK SAR
Plate since	
Current registration	OR SIE
Plate since	
	More info >

CarCheck.co.uk page 10/13



Finance check

Check if this MASERATI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MASERATI has been settled.

If not, and you buy this MASERATI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MASERATI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-10-17
Last registration	2024-01-08
Complete history	See info



Registration #1	2007-10-17	14 mi
Registration #2	2010-10-13	18.893 mi
Registration #3	2010-10-14	18.906 mi
Registration #4	2010-12-22	19.575 mi
Registration #5	2011-02-28	19.640 mi
Registration #6	2012-04-27	21.500 mi
Registration #7	2013-04-25	22.555 mi
Registration #8	2014-04-28	23.611 mi
Registration #9	2015-05-11	25.021 mi
Registration #10	2016-04-11	27.000 mi
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		

More info >

CarCheck.co.uk page 12/13



Dimensions & weight

Width	1822 mm
Height	1295 mm
Length	4523 mm
Wheel base	2660 mm
Kerb weight	1680 kg

Additional information

Fuel tank capacity	88 I
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Engine number	113391

CarCheck.co.uk page 13/13