




General information

Make	CITROEN
Model	GRAND C4 PICASSO HDI VTR PLUS GRAND PICASSO
Colour	White
Year of manufacture	2012
Top speed	112 mph
0 - 60 mph	13.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	285 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	43.5 mpg
Consumption extra urban	61.4 mpg
Consumption combined	53.3 mpg
CO2 emission	135 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-01-29
Pictures	1
Listing price	<a href="#">View report</a>



source: autoonline.co.uk

**MOT history**

<b>MOT expiry date</b>	2024-01-08
<b>MOT pass rate</b>	50 %
<b>MOT passed</b>	3
<b>Failed MOT tests</b>	3
<b>Total advice items</b>	26
<b>Total items failed</b>	14

**MOT #6** 2017-02-23 12:29**MOT test number** 861312835416**Result** ✓ Passed**Next expiry date** 2018-02-22

- Advice** Offside Front Track rod end ball joint has slight play borderline (2.2.B.1f)
- Advice** Front bumper slight damage nearside
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement front bush (2.4.G.2)
- Advice** Rear wiper blade rubber split

**MOT #5** 2017-02-23 10:08**MOT test number** 587722959127**Result** ✗ Failed

- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement front bush (2.4.G.2)
- Advice** Front bumper slight damage nearside
- Advice** Offside Front Track rod end ball joint has slight play borderline (2.2.B.1f)
- Fail** Offside Rear Tyre has ply or cords exposed (4.1.D.1b)
- Advice** Rear wiper blade rubber split

**MOT #4**

2017-01-12 11:05

**MOT test number**

440041469633

**Result****✗ Failed****Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)**Pass with rectification** Offside Headlamp not working on dipped beam (1.7.5a)**Fail** Nearside Track rod end ball joint has excessive play (2.2.B.1f)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Rear wiper blade rubber split**Fail** Electronic stability system warning lamp indicates a fault (3.4.1c)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement front bush (2.4.G.2)**Fail** Nearside Rear Road wheel bead rim badly distorted x2 (4.2.A.1a)**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Track rod end ball joint has slight play borderline (2.2.B.1f)**Advice** Front bumper nearside slight damage**Fail** Front brake excessively fluctuating (3.7.B.3)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Rear Brake pipe inadequately clipped (3.6.B.1)**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)

**MOT #3**

2016-01-28 17:08

**MOT test number**

560908267256

**Result**

✓ Passed

- Advice** Nearside Rear tyre has a nail in tread
- Advice** Nearside Front Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)
- Advice** Both front tyres worn on inner edges
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #2**

2016-01-28 12:18

**MOT test number**

724954006360

**Result**

✗ Failed

- Advice** Nearside Rear tyre has a nail in tread
- Fail** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)
- Fail** Rear registration plate faded (6.3.1d)
- Advice** Nearside Front Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)
- Advice** Both front tyres worn on inner edges
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #1**

2015-03-20 16:12

**MOT test number**

128519975023

**Result**

✓ Passed

- Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)



Tax & MOT check

✓  
**Taxed**  
  
Tax due:  
1 February 2025

✗  
**MOT**  
  
Expired:  
8 January 2024

Tax status	Valid until 1 February
Days left	279
MOT expiry date	8 January 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >





Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2012-05-09
Last registration	2017-02-23
Complete history	<a href="#">See info</a>



Registration #1	2012-05-09	20 mi
Registration #2	2015-03-20	29.172 mi
Registration #3	2016-01-28	37.713 mi
Registration #4	2016-01-28	37.713 mi
Registration #5	2016-01-28	37.713 mi
Registration #6	2016-01-28	37.713 mi
Registration #7	2016-01-28	37.713 mi
Registration #8	2016-01-28	37.713 mi

More info >



Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)

Dimensions & weight

Width	1830 mm
Height	1710 mm
Length	4590 mm
Wheel base	2728 mm
Kerb weight	1490 kg
Max. allowed weight	2250 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	JBER3113544