





report date: 2024-03-28

## General information

| Make                | VOLKSWAGEN     |
|---------------------|----------------|
| Model               | POLO SE TSI    |
| Colour              | White          |
| Year of manufacture | 2019           |
| Top speed           | 116 mph        |
| 0 - 100 km/h        | 10.8 seconds   |
| Gearbox             | 5 speed Manual |

# Engine & fuel consumption

| Power                   | 70 kW / 95 HP / 94 BHP |
|-------------------------|------------------------|
| Max. torque             | 175 Nm at 2.000 rpm    |
| Engine capacity         | 999 сс                 |
| Cylinders               | 3                      |
| Fuel type               | Petrol                 |
| Consumption city        | 53.3 mpg               |
| Consumption extra urban | 68.9 mpg               |
| Consumption combined    | 52.3 mpg               |
| CO2 emission            | 104 g/km               |
| CO2 label               | В                      |



CarCheck.co.uk page 1/11



# Internet history

## Entry 1

| Date          | 2022-03-06  |
|---------------|-------------|
| Pictures      | 1           |
| Listing price | View report |



source: cargurus.co.uk

CarCheck.co.uk page 2/11



MOT history

| MOT expiry date    | 2025-03-10 |
|--------------------|------------|
| MOT pass rate      | 75 %       |
| MOT passed         | 3          |
| Failed MOT tests   | 1          |
| Total advice items | 6          |
| Total items failed | 1          |

| MOT #4    |                                                                            | 2024-03-09 11:49 |
|-----------|----------------------------------------------------------------------------|------------------|
| MOT test  | number                                                                     | 556568132177     |
| Result    |                                                                            | ✓ Passed         |
| Next expi | ry date                                                                    | 2025-03-10       |
| Advice    | Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))  |                  |
| Advice    | Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) |                  |

| MOT #3                                                                                                                                      | 2024-03-09 10:41           |
|---------------------------------------------------------------------------------------------------------------------------------------------|----------------------------|
| MOT test number                                                                                                                             | 797971625144               |
| Result                                                                                                                                      | <b>X</b> Failed            |
| Minor Offside Front Track rod end ball joint dust cover damaged or deteriorated ingress of dirt (2.1.3 (g) (i))                             | I, but preventing the      |
| Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)                                                            | )                          |
| <b>Fail</b> Nearside Front Track rod end ball joint dust cover excessively damaged or olonger prevents the ingress of dirt (2.1.3 (g) (ii)) | deteriorated so that it no |
| Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))                                                            |                            |

| MOT #2                                                                            | 2023-03-07 16:14 |
|-----------------------------------------------------------------------------------|------------------|
| MOT test number                                                                   | 160575746531     |
| Result                                                                            | ✓ Passed         |
| Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt |                  |

CarCheck.co.uk page 3/11



MOT #1 2022-03-02 14:04

**MOT test number** 667423144713

**Result** ✓ Passed

CarCheck.co.uk page 4/11



# Tax & MOT check



| Tax status       | Valid until 1 March |
|------------------|---------------------|
| Days left        | 305                 |
| MOT expiry date  | 10 March 2025       |
| Full MOT history | See MOT history     |

## Tax calculation

| Vehicle class                 | 48         |
|-------------------------------|------------|
| Band                          | F          |
| First licence fee (12 months) | £ 185,00,- |
| Standard rate (12 months)     | £ 180,00,- |
| Standard rate (6 months)      | £ 99,00,-  |
| Premium rate (12 months)      | £ 570,00,- |
| Premium rate (6 months)       | £ 313,50,- |
|                               |            |

CarCheck.co.uk page 5/11



## Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <a href="here">here</a> for the results.


#### Damage 1

| Date     |  |
|----------|--|
| Category |  |
| Туре     |  |
|          |  |

#### Damage 2

| Date     |  |  |
|----------|--|--|
| Category |  |  |

**Type** 



#### Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



## Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



# Owner history

| For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dov <a href="https://example.com/here">here</a> . |             |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------|
| ********                                                                                                                                                                                                             |             |
| ***************************************                                                                                                                                                                              |             |
| ***************************************                                                                                                                                                                              |             |
| 2000000                                                                                                                                                                                                              |             |
|                                                                                                                                                                                                                      |             |
| ***************************************                                                                                                                                                                              |             |
| Plate changes                                                                                                                                                                                                        | More info > |
| See in this check if this VOLKSWAGEN had different number plates.                                                                                                                                                    |             |
| Number of plates                                                                                                                                                                                                     | ,           |
| Current registration                                                                                                                                                                                                 | UK UK       |
| Plate since                                                                                                                                                                                                          |             |
| Current registration                                                                                                                                                                                                 | UK ZIN      |
| Plate since                                                                                                                                                                                                          |             |
|                                                                                                                                                                                                                      | More info > |

CarCheck.co.uk page 8/11



## Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| Contact info      |  |

Contact info

More info >

CarCheck.co.uk page 9/11



# Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 6          |
| First mileage registration | 2019-03-11 |
| Last registration          | 2024-03-09 |
| Complete history           | See info   |



| Registration #1 | 2019-03-11 | 13 mi     |
|-----------------|------------|-----------|
| Registration #1 | 2019-03-11 | 13 1111   |
| Registration #2 | 2022-03-02 | 29.330 mi |
| Registration #3 |            | 11.777 mi |
| Registration #4 |            | 11.777 es |
| Registration #5 |            | 11.777 es |
| Registration #6 |            | 11.777 es |

More info >

CarCheck.co.uk page 10/11



## Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 |                  |
| 50482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

# Safety ratings

| NCAP rating    | ***             |
|----------------|-----------------|
| Adult          | 96%             |
| Children       | 85%             |
| Pedestrian     | 76%             |
| Safety systems | 59%             |
| Overall rating | 82%             |
| Video          | see crash video |



# Dimensions & weight

| Width               | 1751 mm |
|---------------------|---------|
| Height              | 1461 mm |
| Length              | 4053 mm |
| Wheel base          | 2551 mm |
| Kerb weight         | 1070 kg |
| Max. allowed weight | 1610 kg |

# Additional information

| Fuel tank capacity | 40 I             |
|--------------------|------------------|
| Fuel delivery      | Direct Injection |
| Number of doors    | 5                |
| CarChack co.uk     | page 11/11       |

CarCheck.co.uk page 11/11

| Number of seats | 5          |
|-----------------|------------|
| Number of axles | 2          |
| Engine number   | DKLA062185 |