



PF53YJY

report date: 2024-03-28

General information

Make	AUDI
Model	A6 RS6 QUATTRO AVANT
Colour	Black
Year of manufacture	2004
Top speed	155 mph
0 - 60 mph	4.7 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	450 BHP
Max. torque	560 Nm at 5.600 rpm
Engine capacity	4.172 cc
Cylinders	8
Fuel type	Petrol
Consumption city	13.0 mpg
Consumption extra urban	27.1 mpg
Consumption combined	19.3 mpg
CO2 emission	350 g/km
CO2 label	M






Internet history

Entry 2

Date	2022-03-13
Pictures	44
Listing price	View report



source: [cargurus.co.uk](#)

Entry 1

Date	2021-06-09
Pictures	13
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-03-09
MOT pass rate	81 %
MOT passed	17
Failed MOT tests	4
Total advice items	33
Total items failed	2

MOT #21	2024-03-07 12:41
MOT test number	153743218066
Result	✓ Passed
Next expiry date	2025-03-09
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #20	2024-03-05 11:23
MOT test number	435480890056
Result	✗ Failed
MAJOR	Offside Rear Hydraulic brake calliper leaking (1.1.16 (b) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
MAJOR	Offside Front Track rod end modification unsafe Lock nut loose (2.1.3 (f) (i))

MOT #19	2023-03-10 11:40
MOT test number	904558126011
Result	✓ Passed

MOT #18	2022-03-09 11:04
MOT test number	963941429706
Result	✓ Passed

**MOT #17** 2022-03-08 13:25**MOT test number** 439394724593**Result** ✗ Failed**MAJOR** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #16** 2020-11-07 12:43**MOT test number** 259466404297**Result** ✓ Passed**MOT #15** 2019-10-07 09:58**MOT test number** 249452021593**Result** ✓ Passed**Advice** Offside Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Damage to offside rear tyre outer wall**MOT #14** 2018-10-11 16:29**MOT test number** 507915518867**Result** ✓ Passed**MOT #13** 2018-09-26 10:07**MOT test number** 874939277299**Result** ✗ Failed**MAJOR** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MAJOR** Offside Front Exhaust has a major leak of exhaust gases (6.1.2 (a))**MAJOR** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MAJOR** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))

**MOT #12** 2017-10-03 08:37**MOT test number** 347005279689**Result** ✓ Passed**Advice** Engine covers and under trays fitted**MOT #11** 2016-06-01 14:57**MOT test number** 539397830719**Result** ✓ Passed**MOT #10** 2015-05-22 15:00**MOT test number** 989502045123**Result** ✓ Passed**MOT #9** 2014-05-21 12:57**MOT test number** 967091944131**Result** ✓ Passed**Advice** Offside Rear coil spring corroded (2.4.C.1b)**Advice** Nearside Front coil spring corroded (2.4.C.1b)**Advice** Nearside Rear coil spring corroded (2.4.C.1b)**Advice** Rear Anti-roll bar corroded but not seriously weakened (2.4.G.1)**Notice** Oil leak from auto gear box**Advice** Offside Front coil spring corroded (2.4.C.1b)**MOT #8** 2013-05-17 10:50**MOT test number** 416637433144**Result** ✓ Passed**Advice** Nearside Front Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)**Notice** Near side front brake slight binding

**MOT #7** 2012-01-16 09:52**MOT test number** 127676312021**Result** ✓ Passed**MOT #6** 2011-01-19 10:50**MOT test number** 159159911025**Result** ✓ Passed**Notice** Rear number plate slightly delaminated**Notice** N/s mirror cracked but still servicable**MOT #5** 2010-01-29 09:53**MOT test number** 792239220042**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2009-01-23 15:24**MOT test number** 454233229099**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



MOT #3	2009-01-21 11:20
MOT test number	202041929052
Result	✗ Failed
Fail	Offside Front Mechanical brake component has restricted free movement (3.5.1k)
Advice	Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Fail	Nearside Front Valve stem seriously damaged (4.1.D.1e)
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Front Brake pad(s) wearing thin (3.5.1g)

MOT #2	2008-01-15 11:27
MOT test number	524955318000
Result	✓ Passed
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #1	2007-01-12 15:26
MOT test number	914352317083
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
9 March 2025

Tax status	Valid until 1 April
Days left	338
MOT expiry date	9 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this AUDI had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this AUDI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2004-01-30
Last registration	2024-03-07
Complete history	See info



Registration #1	2004-01-30	14 mi
Registration #2	2007-01-12	15.876 mi
Registration #3	2008-01-15	20.308 mi
Registration #4	2009-01-21	23.486 mi
Registration #5	2009-01-23	23.486 mi
Registration #6	2010-01-29	26.925 mi
Registration #7	2011-01-19	29.958 mi
Registration #8	2012-01-16	32.068 mi
Registration #9	2013-05-17	34.862 mi
Registration #10	2014-05-21	35.577 mi
Registration #11	2015-05-22	36.090 mi
Registration #12	2016-06-01	36.584 mi
Registration #13	2016-06-01	36.584 mi
Registration #14	2016-06-01	36.584 mi
Registration #15	2016-06-01	36.584 mi
Registration #16	2016-06-01	36.584 mi
Registration #17	2016-06-01	36.584 mi
Registration #18	2016-06-01	36.584 mi
Registration #19	2016-06-01	36.584 mi
Registration #20	2016-06-01	36.584 mi
Registration #21	2016-06-01	36.584 mi
Registration #22	2016-06-01	36.584 mi
Registration #23	2016-06-01	36.584 mi
Registration #24	2016-06-01	36.584 mi

More info >



Car features

The AUDI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete AUDI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1850 mm
Height	1475 mm
Length	4852 mm
Wheel base	2759 mm
Max. allowed weight	2420 kg

Additional information

Fuel tank capacity	82 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2

