






report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	E-GOLF
Colour	White
Year of manufacture	2018
Top speed	93 mph
0 - 60 mph	9.3 seconds
Gearbox	1 speed CVT

Engine & fuel consumption

Power	134 BHP
Max. torque	290 Nm at 3.000 rpm
Cylinders	1
Fuel type	Electricity
Consumption combined	235.2 mpg



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 3

Date 2022-02-27

Pictures 20

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 2

Date	2021-12-19

Pictures 20

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

MOT history

MOT expiry date	2024-11-30
MOT pass rate	75 %
MOT passed	3
Failed MOT tests	1
Total advice items	11
Total items failed	1

MOT #4		2023-11-29 09:34
MOT test r	number	840805269703
Result		✓ Passed
Next expir	y date	2024-11-30
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))	

MOT #3	2022-11-27 11:57
MOT test number	895218195637
Result	✓ Passed
Minor Nearside Front Daytime running lamp incorrect colour (4.2.3 (a) (i))	

MOT #2		2021-12-01 14:00
MOT test	number	127554191809
Result		✓ Passed
Advice	Nearside Front Tyre slightly damaged to sidewall (5.2.3 (d) (ii))	
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT test number

602676536230

Result

Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Nearside Front Tyre slightly damaged to sidewall (5.2.3 (d) (ii))

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check



Full MOT history See MOT history

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	
Category	



Extra VOLKSWAGEN salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

More info >

Owner history

o which initially	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here.	

	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	OK SIES
Plate since	
Current registration	AIR SIE
Plate since	

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 9/11



GF68XDR report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2018-11-30
Last registration	2023-11-29
Complete history	See info



Registration #1	2018-11-30	17 mi
Registration #2	2021-12-01	21.419 mi
Registration #3	2021-12-01	21.434 mi
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

Car features

50225	Air conditionir
50295	
60482	
60501	
60566	
0567	
60569	

Safety ratings

NCAP rating	****
Adult	94%
Children	89%
Pedestrian	65%
Safety systems	71%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	2027 mm
Height	1482 mm
Length	4349 mm
Wheel base	2629 mm
Kerb weight	1615 kg
Max. allowed weight	2020 kg

Additional information

Fuel delivery	Not Applicable
Number of doors	5
Number of seats	5
CarChack co.uk	nago 11/1:

CarCheck.co.uk page 11/11

Number of axles	2
Engine number	EAZA039196