



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	HILUX INVINCIBLE 4X4 D-4D DCB
Colour	White
Year of manufacture	2012
Top speed	106 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	169 BHP
Max. torque	343 Nm at 3.400 rpm
Engine capacity	2.982 cc
Cylinders	4
Fuel type	Diesel
Consumption city	29.7 mpg
Consumption extra urban	42.2 mpg
Consumption combined	36.7 mpg
CO2 emission	203 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-07-19
Pictures	0
Listing price	View report

source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-26
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	28
Total items failed	7

MOT #12	2023-10-27 14:40
MOT test number	488699701293
Result	✓ Passed
Next expiry date	2024-10-26
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front front fog light missing
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #11**

2023-10-25 12:44

MOT test number

614552913020

Result**✗ Failed****Fail** Exhaust has a major leak of exhaust gases tail pipe missing (6.1.2 (a))**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Front Windscreen washer not working (3.5 (a))**Fail** Rear Rear fog lamp not working (4.5.1 (a) (ii))**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Emissions unable to be completed exhaust (8.2.2.2 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Rear Registration plate lamp likely to become detached (4.7.1 (c) (ii))**Advice** Nearside Front front fog light missing**MOT #10**

2022-07-28 12:49

MOT test number

187985380520

Result**✓ Passed****Minor** Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Minor** Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**MOT #9**

2021-08-02 13:39

MOT test number

918079196545

Result**✓ Passed**

**MOT #8** 2021-06-23 10:33**MOT test number** 693597092428**Result** ✓ Passed**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Brake disc worn, pitted or scored, but not seriously weakened both front (1.1.14 (a) (ii))**Advice** Front Service brake grabbing slightly (1.2.1 (c))**MOT #7** 2019-11-15 10:02**MOT test number** 428451379959**Result** ✓ Passed**MOT #6** 2019-11-12 09:08**MOT test number** 526795409012**Result** ✗ Failed**Fail** Tyre tread depth below requirements of 1.6mm All four (5.2.3 (e))**MOT #5** 2018-11-16 14:30**MOT test number** 546270925323**Result** ✓ Passed**Advice** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Offside Rear Service brake fluctuating, but not excessively (1.2.1 (e))**Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))**Advice** Front Service brake fluctuating, but not excessively both (1.2.1 (e))**Advice** Nearside Front Inner Drive shaft joint worn, but not excessively input shaft loose in diff (6.1.7 (c) (i))

**MOT #4** 2017-10-10 07:44**MOT test number** 101858094730**Result** ✓ Passed**MOT #3** 2016-10-25 07:43**MOT test number** 350837151830**Result** ✓ Passed**MOT #2** 2015-10-13 09:53**MOT test number** 342939064015**Result** ✓ Passed

- Advice** Under tray
- Advice** Nearside Front Tyre worn close to the legal limit 2mm (4.1.E.1)
- Advice** Engine cover
- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)

MOT #1 2015-10-12 09:57**MOT test number** 690967465316**Result** ✗ Failed

- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice** Nearside Front Tyre worn close to the legal limit 2mm (4.1.E.1)
- Advice** Under tray
- Fail** Offside Rear Tyre(s) incorrect because different size tyres are fitted on the same axle. 265/70/R17 112/109R m+s load range C (4.1.A.1a)
- Advice** Engine cover
- Advice** Nearside rear tyre slightly perished.



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
26 October 2024

Tax status	Valid until 1 February
Days left	279
MOT expiry date	26 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-29
Current registration	*****
Plate since	2023-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-10-30
Last registration	2023-10-27
Complete history	See info



Registration #1	2012-10-30	10 mi
Registration #2	2015-10-12	24.826 mi
Registration #3	2015-10-13	24.839 mi
Registration #4	2016-10-25	36.643 mi
Registration #5	2017-10-10	45.785 mi
Registration #6	2018-11-16	68.242 mi
Registration #7	2019-11-12	92.708 mi
Registration #8	2020-10-27	115.277 mi
Registration #9	2021-10-27	135.277 mi
Registration #10	2022-10-27	155.277 mi
Registration #11	2023-10-27	175.277 mi
Registration #12	2024-03-29	195.277 mi
Registration #13	2024-03-29	215.277 mi
Registration #14	2024-03-29	235.277 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1835 mm
Height	1860 mm
Length	5260 mm
Kerb weight	1975 kg
Max. allowed weight	3080 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	1KD5718327