



report date: 2024-03-29

General information

Make	KIA
Model	SORENTO CRDI XE
Colour	Black
Year of manufacture	2006
Top speed	106 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	343 Nm at 1.850 rpm
Engine capacity	2.497 cc
Cylinders	4
Fuel type	Diesel
Consumption city	28.5 mpg
Consumption extra urban	43.5 mpg
Consumption combined	36.7 mpg
CO2 emission	204 g/km
CO2 label	K





MOT history

MOT expiry date	2021-11-01
MOT pass rate	61 %
MOT passed	11
Failed MOT tests	7
Total advice items	34
Total items failed	27

MOT #18	2020-10-23 15:45
MOT test number	557760080992
Result	✓ Passed
Next expiry date	2021-11-01
Advice	Nearside Rear Inner sill has slight corrosion

MOT #17	2020-10-23 10:05
MOT test number	546784969460
Result	✗ Failed
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))
Fail	Offside Headlamp not working on main beam (4.1.1 (a) (ii))
Fail	Nearside Rear Position lamp missing (4.2.1 (a) (ii))
Fail	Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
Advice	Nearside Rear Inner sill has slight corrosion
Fail	Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
Fail	Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**MOT #16**

2019-04-30 15:47

MOT test number

749468997908

Result

✓ Passed

Advice

Nearside Front Power steering component has slight seepage from a component from boot (2.1.5 (a))

Advice

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Offside Front Power steering component has slight seepage from a component from boot (2.1.5 (a))

MOT #15

2019-04-29 08:43

MOT test number

366736093210

Result

✗ Failed

Fail

Nearside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

Advice

Nearside Front Power steering component has slight seepage from a component from boot (2.1.5 (a))

Advice

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail

Offside Rear Parking brake inoperative on one side (1.4.1 (a))

Fail

Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

Fail

Offside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

Advice

Offside Front Power steering component has slight seepage from a component from boot (2.1.5 (a))

Fail

Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

MOT #14

2018-04-27 14:11

MOT test number

264338705565

Result

✓ Passed

Advice

Clutch slave leaking

Advice

Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice

Nearside Rear Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)

**MOT #13**

2018-04-27 08:21

MOT test number

537130544798

Result

✗ Failed

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Fail** Offside Front Anti-roll bar linkage has excessive play in a pin/bush (2.4.G.2)
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Power steering ram(s) leaking from a failed component (2.3.3b)
- Advice** Nearside Rear Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)
- Advice** Clutch slave leaking
- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Fail** Offside Rear rear brake binding (3.7.B.1)
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #12

2017-05-02 14:38

MOT test number

909760120721

Result

✓ Passed

- Advice** Offside Front Inner Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Inner Tyre worn close to the legal limit (4.1.E.1)

MOT #11

2016-12-21 12:16

MOT test number

988046758290

Result

✓ Passed

MOT #10

2016-12-21 11:39

MOT test number

293850268355

Result

✗ Failed

- Fail** Nearside Rear Braking system leaking (3.6.A.1)

**MOT #9**

2016-01-15 14:15

MOT test number

825911321161

Result

✓ Passed

- Advice** Engine noisy at idle
- Advice** Clutch pipe excessively corroded on bulk head
- Advice** Offside Front Anti-roll bar has slight play in a pin/bush D bush (2.4.G.2)
- Advice** Offside Front Brake pipe slightly corroded to flexi (3.6.B.2c)

MOT #8

2016-01-06 11:00

MOT test number

948185939334

Result

✗ Failed

- Fail** Nearside Rear Brake pipe excessively corroded on axle to flexi (3.6.B.2c)
- Fail** Nearside Rear Anti-roll bar has excessive play in a pin/bush D bush (2.4.G.2)
- Advice** Offside Front Anti-roll bar has slight play in a pin/bush D bush (2.4.G.2)
- Advice** Clutch pipe excessively corroded on bulk head
- Fail** Offside Front Upper Suspension arm has excessive play in a ball joint (2.4.G.2)
- Fail** Brake pipe excessively corroded both front to rear brake pipes near fuel tank (3.6.B.2c)
- Advice** Offside Front Brake pipe slightly corroded to flexi (3.6.B.2c)
- Advice** Offside Rear Anti-roll bar has slight play in a pin/bush D bush (2.4.G.2)
- Fail** Offside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)
- Advice** Engine noisy at idle

MOT #7

2014-12-23 11:43

MOT test number

256277154391

Result

✓ Passed

**MOT #6** 2014-12-22 15:56**MOT test number** 198536454326**Result** ✗ Failed**Fail** Offside Rear Brake pipe excessively corroded (3.6.B.2c)**Fail** Nearside Front Brake pipe excessively corroded (3.6.B.2c)**MOT #5** 2014-01-16 12:38**MOT test number** 799496414056**Result** ✓ Passed**MOT #4** 2013-01-17 16:04**MOT test number** 948887413017**Result** ✓ Passed**Advice** Offside Suspension arm has slight play in a ball joint (2.4.G.2)**Notice** Travel on handbrake**Advice** Nearside Suspension arm has slight play in a ball joint (2.4.G.2)**MOT #3** 2013-01-17 16:04**MOT test number** 208267713035**Result** ✗ Failed**Advice** Offside Suspension arm has slight play in a ball joint (2.4.G.2)**Advice** Nearside Suspension arm has slight play in a ball joint (2.4.G.2)**Notice** Travel on handbrake**Pass with rectification** Offside Registration plate lamp not illuminating the registration plate (1.1.C.1e)**MOT #2** 2010-02-16 11:05**MOT test number** 172647540095**Result** ✓ Passed



MOT #1	2009-02-17 11:44
MOT test number	114418149412
Result	✓ Passed
Advice	Nearside Rear Anti-roll bar has slight play in a pin/bush (2.4.G.2)
Advice	Nearside Power steering component(s) has slight seepage from a seal (2.3.3b)
Advice	Offside Rear Anti-roll bar has slight play in a pin/bush (2.4.G.2)



Tax & MOT check

X

Untaxed

Tax expired:
11 January 2021

X

MOT

Expired:
1 November 2021

Tax status	Expired at 11 January 2021
Days left	1203 days too late
MOT expiry date	1 November 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2024-03-29
Current registration	*****
Plate since	2024-03-29

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2006-02-22
Last registration	2020-10-23
Complete history	See info



Registration #1	2006-02-22	25 mi
Registration #2	2009-02-17	26.506 mi
Registration #3	2010-02-16	45.224 mi
Registration #4	2013-01-17	75.358 mi
Registration #5	2014-01-16	88.217 mi
Registration #6	2014-12-22	103.696 mi
Registration #7	2014-12-23	103.696 mi
Registration #8	2016-01-06	116.097 mi
Registration #9	2016-01-15	116.452 mi
Registration #10	2016-01-22	116.452 mi
Registration #11	2016-01-22	116.452 mi
Registration #12	2016-01-22	116.452 mi
Registration #13	2016-01-22	116.452 mi
Registration #14	2016-01-22	116.452 mi
Registration #15	2016-01-22	116.452 mi
Registration #16	2016-01-22	116.452 mi
Registration #17	2016-01-22	116.452 mi
Registration #18	2016-01-22	116.452 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1884 mm
Height	1804 mm
Length	4567 mm
Wheel base	2710 mm
Kerb weight	2079 kg
Max. allowed weight	2600 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D4CB5856510