



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	EOS GTI EDITION30 T 230
Colour	Black
Year of manufacture	2007
Top speed	150 mph
0 - 60 mph	6.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	227 BHP
Max. torque	300 Nm at 2.200 rpm
Engine capacity	1.984 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.0 mpg
Consumption extra urban	44.1 mpg
Consumption combined	34.4 mpg
CO2 emission	194 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-02-06
Pictures	0
Listing price	View report

source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2024-07-27
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	30
Total items failed	9

MOT #12	2023-07-28 14:22
MOT test number	886336070230
Result	✓ Passed
Next expiry date	2024-07-27
Advice	Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))
Advice	Front shock absorbers corroded - both

MOT #11	2023-07-25 16:05
MOT test number	741429038970
Result	✗ Failed
Fail	Rear Tyre tread depth below requirements of 1.6mm both- inner shoulder wear (5.2.3 (e))
Advice	Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))
Advice	Front shock absorbers corroded - both

**MOT #10**

2022-06-08 12:50

MOT test number

789554905956

Result

✓ Passed

- Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))

MOT #9

2019-04-04 08:30

MOT test number

798712467555

Result

✓ Passed

- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))

MOT #8

2018-03-08 12:43

MOT test number

809852176161

Result

✓ Passed

- Advice** Nearside Rear tyre worn on inside edge
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front Lower Anti-roll bar linkage ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)

**MOT #7** 2017-03-08 13:19**MOT test number** 830044040832**Result** ✓ Passed**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #6** 2017-03-06 14:54**MOT test number** 269612473444**Result** ✗ Failed**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Offside Rear Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Rear brakes release unevenly (3.7.B.4)**MOT #5** 2016-04-04 14:01**MOT test number** 473321706164**Result** ✓ Passed**MOT #4** 2016-04-04 14:01**MOT test number** 451392431336**Result** ✗ Failed**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)

**MOT #3** 2015-03-02 10:11**MOT test number** 977181565001**Result** ✓ Passed**MOT #2** 2014-03-24 10:03**MOT test number** 897113884023**Result** ✓ Passed**MOT #1** 2013-06-21 11:26**MOT test number** 268172673417**Result** ✗ Failed**Fail** Fuel cap/sealing device does not fasten securely maintaining the sealing arrangement (7.2.4b)**Notice** Air bag light on dash**Notice** Steering warning light on dash**Fail** Rear fog lamp switch faulty (1.3.1a)**Fail** Offside Rear Seat belt locking mechanism does not secure or release (5.2.5a)**Notice** Drivers door handle insecure**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Too much oil in engine**Fail** Windscreen wiper does not clear the windscreen effectively (8.2.2)



Tax & MOT check

X

Untaxed

Tax expired:
1 July 2023

✓

MOT

Expires:
27 July 2024

Tax status	Expired at 1 July 2023
Days left	302 days too late
MOT expiry date	27 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 GJ57PXD
Plate since	2024-03-28
Current registration	 GJ57PXD
Plate since	2024-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2007-09-19
Last registration	2023-07-28
Complete history	See info



Registration #1	2007-09-19	12 mi
Registration #2	2013-06-21	26.483 mi
Registration #3	2014-03-24	26.662 mi
Registration #4	2015-03-02	29.356 mi
Registration #5	2016-04-04	39.572 mi
Registration #6	2016-04-04	39.572 mi
Registration #7	2017-03-06	52.397 mi
Registration #8	2019-05-29	55.277 mi
Registration #9	2019-05-29	55.277 mi
Registration #10	2019-05-29	55.277 mi
Registration #11	2019-05-29	55.277 mi
Registration #12	2019-05-29	55.277 mi
Registration #13	2019-05-29	55.277 mi
Registration #14	2019-05-29	55.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1759 mm
Height	1469 mm
Length	4216 mm
Wheel base	2578 mm
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles

2

Engine number

NOT KNOWN