





report date: 2024-03-28

## General information

Maka	DELICEOT
Make	PEUGEOT
Model	207 HDI MILLESIM
Colour	Grey
Year of manufacture	2010
Top speed	103 mph
0 - 60 mph	16.9 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	68 BHP
Max. torque	160 Nm at 1.750 rpm
Engine capacity	1.398 сс
Cylinders	4
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	76.4 mpg
Consumption combined	67.3 mpg
CO2 emission	114 g/km
CO2 label	С



CarCheck.co.uk page 1/15



report date: 2024-03-28

## Internet history

## Entry 1

Date 2021-05-26

Pictures 30

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/15



report date: 2024-03-28

	_				
11/1/	TC	n		$\overline{}$	r\/
IVIL	, ,		51	LU.	ıv
					. ,

MOT expiry date	2025-05-11
MOT pass rate	70 %
MOT passed	14
Failed MOT tests	6
Total advice items	29
Total items failed	22

MOT #20	2024-04-16 09:11
MOT test number	767461797642
Result	✓ Passed
Next expiry date	2025-05-11

MOT #19		2024-04-16 09:11
MOT test number		686770654133
Result		<b>X</b> Failed
Pass with rectification	Nearside Stop lamp(s) not working (4.3.1 (a) (ii))	
Pass with rectification	Offside Stop lamp(s) not working (4.3.1 (a) (ii))	

MOT #18	2023-05-12 09:30
MOT test	number 729501257233
Result	✓ Passed
Advice	Heat sheild loose
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

CarCheck.co.uk page 3/15



report date: 2024-03-28

**MOT #17** 2023-05-04 10:29 **MOT** test number 755499728288 Result × Failed Fail Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i)) Fail Nearside Rear Direction indicator incorrect colour (4.4.3 (a)) **Advice** Oil leak, but not excessive (8.4.1 (a) (i)) Advice Heat sheild loose Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i)) Fail Nearside Windscreen washer provides insufficient washer liquid (3.5 (a)) **Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) **Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) Offside Front Macpherson strut attachment bracket/mounting likely to become detached (5.3.3 (a) Fail (ii))

MOT #16		2022-02-07 14:27
MOT test	number	564730370645
Result		✓ Passed
Advice	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Advice Rear Tyre worn close to legal limit/worn on edge both (5.2.3 (e))		

MOT #15	2021-05-29 09:39
MOT test number	956595862739
Result	<b>✓</b> Passed

CarCheck.co.uk page 4/15



report date: 2024-03-28

MOT test number

242983560568

Result

Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail Windscreen washer provides insufficient washer liquid (3.5 (a))

Fail Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))

Fail Rear Engine mounting bracket excessively loose (6.1.8 (a) (ii))

MOT #13

MOT test number

Result

Advice Front exhaust hanger snapped (secure)

Advice Rear heatshield insecure (slight)

MOT #12 2020-01-20 12:00

MOT test number 394046338536

Result ✓ Passed

**MOT #11** 2019-12-30 14:40 **MOT** test number 266766101883 Result Passed **Advice** Tyre worn close to legal limit/worn on edge both front (5.2.3 (e)) **Advice** Tyre slightly damaged/cracking or perishing both rear (5.2.3 (d) (ii)) Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt Advice Brake disc worn, pitted or scored, but not seriously weakened both front (1.1.14 (a) (ii)) Nearside Rear Direction indicator slightly discoloured (4.4.3 (a)) **Advice** 

CarCheck.co.uk page 5/15



report date: 2024-03-28

**MOT #10** 2019-12-30 11:21

**MOT test number** 955462814008

Result X Failed

**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

**Fail** Nearside Windscreen washer not working (3.5 (a))

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Tyre worn close to legal limit/worn on edge both front (5.2.3 (e))

**Fail** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**Advice** Tyre slightly damaged/cracking or perishing both rear (5.2.3 (d) (ii))

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt

Fail Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

**Fail** Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Brake disc worn, pitted or scored, but not seriously weakened both front (1.1.14 (a) (ii))

MOT #9 2018-12-29 10:09

**MOT test number** 695948407543

Result \( \sqrt{Passed} \)

Advice Tyre worn close to legal limit/worn on edge both front (5.2.3 (e))

**MOT #8** 2017-12-20 12:42

**MOT test number** 147539686542

**Result** 
✓ Passed

CarCheck.co.uk page 6/15



report date: 2024-03-28

MOT #7 2017-12-16 10:11

**MOT test number** 720469068039

**Result** X Failed

**Fail** Nearside Front Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

Fail Offside Front Front position lamp(s) not working (1.1.A.3b)

**Fail** Nearside Front Anti-roll bar has excessive play in a ball joint (2.4.G.2)

Fail Windscreen washer provides insufficient washer liquid (8.2.3)

**Fail** Exhaust system not adequately supported (7.1.1)

MOT #6 2016-12-28 14:19

**MOT test number** 932525114697

Result 

Passed

MOT #5 2016-12-23 16:35

MOT test number 864828471934

Result X Failed

**Fail** Nearside Front Lower Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)

MOT #4 2016-07-23 09:34

**MOT test number** 739371460262

**Result** ✓ Passed

MOT #3 2015-07-18 11:11

**MOT test number** 618589195110

Result 

Passed

CarCheck.co.uk page 7/15



report date: 2024-03-28

MOT #2

MOT test number

837400904227

Result

Notice Both rear tyres cracking up

MOT #1 2013-07-03 16:31 **MOT test number** 379304483153 Result ✓ Passed **Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g) Notice Both rear tyres starting to crack up Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Advice Offside Front Brake pad(s) wearing thin (3.5.1g) Notice Nearside front tyre cracking up

CarCheck.co.uk page 8/15



report date: 2024-03-28

## Tax & MOT check



Tax status	Valid until 1 August
Days left	94
MOT expiry date	11 May 2025
Full MOT history	See MOT history

### Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 9/15



report date: 2024-03-28

### Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/15



report date: 2024-03-28

### Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 11/15



report date: 2024-03-28

_	
Owner	history
OWITCE	ilistoi y

For how long did the current and previous owner(s) have this PEUGEOT? How many own have? Check it in the premium report and see all owner registrations. Download the full	
HARMAN CO. C.	
************	
***************************************	
	More info >
	More into /
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	
Current registration	SIE UK
	UK C
Plate since	
Current registration	NK UK
Plate since	m.o.o
	More info >

CarCheck.co.uk page 12/15



report date: 2024-03-28

Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

**Contact info** 

More info >

CarCheck.co.uk page 13/15



report date: 2024-03-28

## Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2010-07-30
Last registration	2024-04-16
Complete history	See info



Registration #1	2010-07-30	15 mi
Registration #2	2013-07-03	22.577 mi
Registration #3	2014-07-19	31.530 mi
Registration #4	2015-07-18	38.799 mi
Registration #5	2016-07-23	47.784 mi
Registration #6	2016-12-23	50.969 mi
Registration #7	2016-12-28	50.969 mi
Registration #8	2017-12-16	64.438 mi
Registration #9	2017-12-20	64.439 mi
Registration #10	2018-12-29	76.660 mi
Registration #11	2019-12-30	91.348 mi
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.177 mi
Registration #18		11.117 es
Registration #19		11.177 es
Registration #20		11.177 es
Registration #21		11.777 es
Registration #22		0.00 44

More info >

CarCheck.co.uk page 14/15




report date: 2024-03-28

## Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Video	see crash video



## Dimensions & weight

Width	1972 mm
Height	1502 mm
Length	4030 mm
Wheel base	2540 mm
Kerb weight	1243 kg
Max. allowed weight	1620 kg

## Additional information

Fuel tank capacity	50
Fuel delivery	Direct Injection
Number of doors	3
Number of seats CarCheck.co.uk	5 page 15/1

Number of axles 2

**Engine number** FDAZ2812965