




report date: 2024-03-28

General information

Make	LAND ROVER
Model	RANGE ROVER TDV8 VOGUE SE
Colour	Black
Year of manufacture	2011
Top speed	130 mph
0 - 100 km/h	7.8 seconds
0 - 60 mph	7.5 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	230 kW / 313 HP / 313 BHP
Max. torque	700 Nm at 1.500 rpm
Engine capacity	4.367 cc
Cylinders	8
Fuel type	Diesel
Consumption city	24.6 mpg
Consumption extra urban	34.5 mpg
Consumption combined	30.1 mpg
CO2 emission	253 g/km
CO2 label	L





Internet history

Entry 2


Date	2021-06-25
Pictures	12
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-06-24
Pictures	24
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-04-23
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	31
Total items failed	2

MOT #15 2024-04-19 14:10

MOT test number 454097228702

Result ✓ Passed

Next expiry date 2025-04-23

Advice Brake pipe corroded, covered in grease or other material all greased (1.1.11 (c))

Advice Shock absorbers has light misting of oil both rear (5.3.2 (b))

Advice Suspension arm pin or bush worn but not resulting in excessive movement both front arm, rear bushes cracking (5.3.4 (a) (i))

MOT #14 2024-04-18 10:06

MOT test number 748687049696

Result ✗ Failed

Advice Suspension arm pin or bush worn but not resulting in excessive movement both front arm, rear bushes cracking (5.3.4 (a) (i))

MAJOR Offside Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Shock absorbers has light misting of oil both rear (5.3.2 (b))

Advice Brake pipe corroded, covered in grease or other material all greased (1.1.11 (c))

**MOT #13**

2023-04-24 10:12

MOT test number

976485280643

Result

✓ Passed

Advice Offside Rear Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge outer edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge outer edge (5.2.3 (e))**MOT #12**

2023-04-14 09:45

MOT test number

606304128781

Result

✗ Failed

Advice Nearside Front Tyre worn close to legal limit/worn on edge outer edge (5.2.3 (e))**MAJOR** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))**MAJOR** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**Advice** Offside Front Tyre worn close to legal limit/worn on edge outer edge (5.2.3 (e))**MOT #11**

2023-03-28 09:40

MOT test number

998762142154

Result

✗ Failed

Advice Nearside Front Tyre worn close to legal limit/worn on edge worn on edge - 255/50r20 (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge worn on edge and perishing/cracking on outer shoulder (5.2.3 (e))**MAJOR** Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn on edge (5.2.3 (e))**MAJOR** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing cracking or perishing on outer shoulder (5.2.3 (d) (ii))



MOT #10	2022-04-20 13:39
----------------	------------------

MOT test number	561970116493
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #9	2021-03-24 10:54
---------------	------------------

MOT test number	400127723039
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #8	2020-03-28 09:56
---------------	------------------

MOT test number	536531038297
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #7	2019-04-13 08:46
---------------	------------------

MOT test number	578187432500
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #6	2018-03-24 11:39
---------------	------------------

MOT test number	779197752262
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #5	2017-03-25 10:06
---------------	------------------

MOT test number	600897211208
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2016-03-24 11:02
---------------	------------------

MOT test number	193505991329
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice	Oil leak from engine.
---------------	-----------------------

Advice	Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
---------------	---

Advice	Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
---------------	--

**MOT #3** 2015-04-23 11:05**MOT test number** 617093015136**Result** ✓ Passed**Advice** Offside Rear Upper Suspension arm has slight play in a pin/bush (2.4.G.2)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #2** 2014-03-12 12:27**MOT test number** 868521674072**Result** ✓ Passed**Notice** Advise damage to nearside front tyre sidewall.**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #1** 2014-03-12 11:54**MOT test number** 728981574069**Result** ✗ Failed**Fail** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Advise damage to nearside front tyre sidewall.**Fail** Offside Rear Tyre has ply or cords exposed (4.1.D.1b)**Notice** Child seat fitted not allowing full inspection of adult belt



Tax & MOT check

✓
Taxed
Tax due:
1 May 2024

✓
MOT
Expires:
23 April 2025

Tax status	Valid until 1 May
Days left	3
MOT expiry date	23 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-



Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this LAND ROVER? How many owners did this LAND ROVER have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this LAND ROVER had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this LAND ROVER is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2011-03-23
Last registration	2024-04-19
Complete history	See info



Registration #1	2011-03-23	26 mi
Registration #2	2014-03-12	33.285 mi
Registration #3	2014-03-12	33.285 mi
Registration #4	2015-04-23	44.667 mi
Registration #5	2016-03-24	50.601 mi
Registration #6	2017-03-25	55.404 mi
Registration #7	2018-03-24	59.868 mi
Registration #8	2019-04-13	63.354 mi
Registration #9	2020-03-28	66.018 mi
Registration #10	2020-03-28	66.018 mi
Registration #11	2020-03-28	66.018 mi
Registration #12	2020-03-28	66.018 mi
Registration #13	2020-03-28	66.018 mi
Registration #14	2020-03-28	66.018 mi
Registration #15	2020-03-28	66.018 mi
Registration #16	2020-03-28	66.018 mi
Registration #17	2020-03-28	66.018 mi
Registration #18	2020-03-28	66.018 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2216 mm
Height	1865 mm
Length	4967 mm
Wheel base	2880 mm
Kerb weight	2710 kg

Additional information

Fuel tank capacity	100 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	0005543448DT