



TOYOTA



report date: 2024-03-28

General information

Make	TOYOTA
Model	PRIUS VVT-I T3
Colour	Silver
Year of manufacture	2006
Top speed	106 mph
0 - 60 mph	10.9 seconds
Gearbox	4 speed CVT

Engine & fuel consumption

Power	76 BHP
Max. torque	115 Nm at 4.000 rpm
Engine capacity	1.497 cc
Cylinders	4
Fuel type	Hybrid / Electric
Consumption city	56.5 mpg
Consumption extra urban	67.3 mpg
Consumption combined	65.7 mpg
CO2 emission	104 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-02-05
Pictures	5
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](#)



## MOT history

MOT expiry date	2024-04-24
MOT pass rate	64 %
MOT passed	14
Failed MOT tests	8
Total advice items	27
Total items failed	14

MOT #22 2023-04-25 07:33

MOT test number 209765191855

Result ✓ Passed

Next expiry date 2024-04-24

**Advice** Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

**Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #21 2023-04-25 07:33

MOT test number 379067281957

Result ✗ Failed

**Pass with rectification** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

**Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**Advice** Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

MOT #20 2022-01-24 10:56

MOT test number 348729478611

Result ✓ Passed

MOT #19 2021-02-22 18:03

MOT test number 379193483324

Result ✓ Passed

**MOT #18** 2020-02-26 08:47**MOT test number** 225885132675**Result** ✓ Passed**Advice** Some under body surface corrosion throughout vehicle but all appears sound**Advice** Under body covers fitted**MOT #17** 2020-02-26 08:47**MOT test number** 498557852243**Result** ✗ Failed**Advice** Some under body surface corrosion throughout vehicle but all appears sound**Pass with rectification** Offside Front Position lamp not working 501 (4.2.1 (a) (ii))**Advice** Under body covers fitted**MOT #16** 2019-04-15 15:42**MOT test number** 149819179926**Result** ✓ Passed**Advice** Items removed from driver's view prior to test accessory holder on centre windscreen.**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #15** 2019-04-05 13:51**MOT test number** 850021703596**Result** ✗ Failed**Advice** Items removed from driver's view prior to test accessory holder on centre windscreen.**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Fail** Front Service brake lagging in operation not releasing at the same rate. (1.2.1 (d))**Minor** Nearside Windscreen wiper blade defective split (3.4 (b) (i))**Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #14** 2018-04-09 07:46**MOT test number** 342111806811**Result** ✓ Passed**MOT #13** 2018-03-29 14:13**MOT test number** 726960738484**Result** ✗ Failed**Pass with rectification** Nearside Rear Rear position lamp(s) not working (1.1.A.3b)**Fail** Exhaust noise is clearly in excess of that emitted by a similar vehicle fitted with a standard silencer in average condition (7.1.4)**Pass with rectification** Nearside Front Front position lamp(s) not working (1.1.A.3b)**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively split (8.2.2)**Fail** Exhaust has a major leak of exhaust gases (7.1.2)**MOT #12** 2017-03-29 14:46**MOT test number** 138910832962**Result** ✓ Passed**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #11** 2016-04-22 16:24**MOT test number** 704625556378**Result** ✓ Passed**MOT #10** 2016-04-21 10:14**MOT test number** 620048924759**Result** ✗ Failed**Fail** Offside Rear coil spring broken (2.4.C.1a)

**MOT #9** 2014-08-29 10:59**MOT test number** 349461444472**Result** ✓ Passed**MOT #8** 2013-08-23 15:29**MOT test number** 948615833234**Result** ✓ Passed**MOT #7** 2013-08-23 14:41**MOT test number** 967605933288**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Notice** O/s/r tyre low tread/perishing**MOT #6** 2012-04-02 14:11**MOT test number** 437333392078**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Front brake juddering slightly (3.7.A.2b)**Notice** Front brake discs worn,corroded and lipped

**MOT #5** 2012-04-02 12:31**MOT test number** 905273692081**Result** ✗ Failed**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Front brake juddering slightly (3.7.A.2b)**Notice** Front brake discs worn, corroded and lipped**Fail** Brakes imbalanced across an axle (3.7.B.5b)**Notice** Items removed from driver's view prior to test**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2011-03-30 11:14**MOT test number** 915859681040**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Front brake discs corroded**MOT #3** 2010-09-09 15:01**MOT test number** 152682050227**Result** ✓ Passed**MOT #2** 2009-09-03 13:03**MOT test number** 933386349273**Result** ✓ Passed



MOT #1	2009-09-03 13:03
MOT test number	314156649481
Result	<div>✖ Failed</div>
<div>Pass with rectification</div>	Nearside Headlamp aim too high (1.8)
<div>Pass with rectification</div>	Offside Headlamp aim too high (1.8)





Tax & MOT check

✓

Taxed

Tax due:  
1 May 2024

✗

MOT

Expired:  
24 April 2024

Tax status	Valid until 1 May
Days left	3
MOT expiry date	24 April 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	59
Band	B
Single payment (12 months)	£ 10,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 10,50,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	FY56KVK
Plate since	2019-03-28
Current registration	FY56KVK
Plate since	2019-03-28

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2006-09-20
Last registration	2023-04-25
Complete history	<a href="#">See info</a>



Registration #1	2006-09-20	28 mi
Registration #2	2009-09-03	31.620 mi
Registration #3	2010-09-09	41.577 mi
Registration #4	2011-03-30	45.710 mi
Registration #5	2012-04-02	52.991 mi
Registration #6	2012-04-02	52.991 mi
Registration #7	2013-08-23	64.225 mi
Registration #8	2013-08-23	64.225 mi
Registration #9	2014-08-29	72.519 mi
Registration #10	2016-04-21	88.895 mi
Registration #11	2016-04-22	88.939 mi
Registration #12	2017-03-29	96.765 mi
Registration #13	2018-03-29	105.599 mi
Registration #14	2018-03-29	105.599 mi
Registration #15	2018-03-29	105.599 mi
Registration #16	2018-03-29	105.599 mi
Registration #17	2018-03-29	105.599 mi
Registration #18	2018-03-29	105.599 mi
Registration #19	2018-03-29	105.599 mi
Registration #20	2018-03-29	105.599 mi
Registration #21	2018-03-29	105.599 mi
Registration #22	2018-03-29	105.599 mi
Registration #23	2018-03-29	105.599 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1725 mm
Height	1490 mm
Length	4450 mm
Wheel base	2700 mm
Kerb weight	1325 kg
Max. allowed weight	1725 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1NZ4201111