



report date: 2024-03-28

General information

Make	MAZDA
Model	MX-5 I ROADSTER SE
Colour	Blue
Year of manufacture	2010
Top speed	121 mph
0 - 60 mph	9.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	124 BHP
Max. torque	167 Nm at 4.500 rpm
Engine capacity	1.798 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.8 mpg
Consumption extra urban	50.4 mpg
Consumption combined	39.8 mpg
CO2 emission	167 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-06-04
Pictures	21
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-03-12
MOT pass rate	92 %
MOT passed	11
Failed MOT tests	1
Total advice items	21
Total items failed	2

MOT #12	2024-03-13 17:07
MOT test number	625007668594
Result	✓ Passed
Next expiry date	2025-03-12
Advice	Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
Advice	General surface corrosion
Advice	Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

MOT #11	2023-01-04 13:32
MOT test number	975847452236
Result	✓ Passed
Advice	Rear Sub-frame corroded but not seriously weakened surface corrosion (5.3.3 (b) (i))
Advice	Front Sub-frame corroded but not seriously weakened surface corrosion (5.3.3 (b) (i))
Advice	Nearside Front Service brake binding but not excessively (1.2.1 (f))

**MOT #10** 2021-11-10 14:26**MOT test number** 440246109316**Result** ✓ Passed

Advice Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement
large rear bush (5.3.4 (a) (i))

Advice Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Advice Nearside Front Service brake binding but not excessively (1.2.1 (f))

Advice Offside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement
large rear bush (5.3.4 (a) (i))

MOT #9 2021-11-09 09:26**MOT test number** 524636254106**Result** ✗ Failed

Fail Offside Rear Upper Coil spring fractured or broken (5.3.1 (b) (i))

Fail Nearside Front Lower Coil spring fractured or broken (5.3.1 (b) (i))

Advice Nearside Front Service brake binding but not excessively (1.2.1 (f))

MOT #8 2020-10-30 14:26**MOT test number** 975238888701**Result** ✓ Passed**MOT #7** 2019-04-20 09:52**MOT test number** 396156284121**Result** ✓ Passed**MOT #6** 2018-04-07 09:51**MOT test number** 773143749203**Result** ✓ Passed

**MOT #5** 2017-04-22 10:32**MOT test number** 189651058827**Result** ✓ Passed**MOT #4** 2016-04-29 13:54**MOT test number** 175637483916**Result** ✓ Passed**MOT #3** 2015-04-23 11:52**MOT test number** 206223915402**Result** ✓ Passed**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** All 4 tyres cracked on side walls**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #2** 2014-04-28 12:18**MOT test number** 216568914130**Result** ✓ Passed**Notice** Nearside rear tyre slightly cracked on side wall**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**MOT #1** 2013-04-17 11:52**MOT test number** 779507903146**Result** ✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 June 2024

✓
MOT

Expires:
12 March 2025

Tax status	Valid until 1 June
Days left	33
MOT expiry date	12 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2020-01-01
Current registration	XXXXXX
Plate since	2020-01-01

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2010-04-28
Last registration	2024-03-13
Complete history	See info



Registration #1	2010-04-28	6 mi
Registration #2	2013-04-17	9.780 mi
Registration #3	2014-04-28	13.189 mi
Registration #4	2015-04-23	16.574 mi
Registration #5	2016-04-29	19.696 mi
Registration #6	2017-04-22	21.889 mi
Registration #7	2018-04-07	24.347 mi
Registration #8	2019-04-28	26.277 mi
Registration #9	2020-04-28	28.277 mi
Registration #10	2021-04-28	30.277 mi
Registration #11	2022-04-28	32.277 mi
Registration #12	2023-04-28	34.277 mi
Registration #13	2024-03-13	36.277 mi
Registration #14	2024-03-13	38.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1720 mm
Height	1245 mm
Length	4020 mm
Wheel base	2330 mm
Kerb weight	1155 kg
Max. allowed weight	1375 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	L8 10209175