





report date: 2024-03-28

General information

Make	MERCEDES-BENZ
Model	CLA CLA220 CDI AMG SPORT
Colour	Grey
Year of manufacture	2015
Top speed	143 mph
0 - 100 km/h	8.2 seconds
0 - 60 mph	8.2 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	130 kW / 177 HP / 170 BHP
Max. torque	350 Nm at 1.400 rpm
Engine capacity	2.143 cc
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	76.4 mpg
Consumption combined	67.3 mpg
CO2 emission	111 g/km
CO2 label	С



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-10-01

Pictures 24

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2025-04-04
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	14
Total items failed	4

MOT #10	2024-04-03 13:31
MOT test number	987152551566
Result	✓ Passed
Next expiry date	2025-04-04
Advice Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))	

MOT #9	2024-04-03 07:07
MOT test number	777459608595
Result	X Failed
Fail Tyre has a bulge, caused by separation or partial failure of its structure also split or cords (5.2.3 (d) (ii))	n inner side wall to
Fail Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))	
Advice Nearside Rear Tyre worn close to legal limit/worn on edge Bald on inside edge (5.2.3 (e))	
Fail Nearside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))	
Advice Rear exhaust heat shield insecure	
Advice Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))	

CarCheck.co.uk page 3/12



MOT #8 2023-04-05 12:34

MOT test number 958352090270

Result ✓ Passed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge Cracking and punctured (5.2.3 (e))

Minor Nearside Front Upper Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #7 2023-04-05 11:15

MOT test number 603077085718

Result X Failed

Minor Nearside Front Upper Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Fail Nearside Front Tyre has a tear, caused by separation or partial failure of its structure Inner side wall (5.2.3 (d) (ii))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge Cracking and punctured (5.2.3 (e))

MOT #6 2022-06-28 07:48

MOT test number 570296228924

Result

Passed

Advice Nearside Front Inner Road wheel slightly distorted (5.2.2 (c) (i))

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #5 2021-07-05 15:16

MOT test number 792010182244

Result
✓ Passed

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

CarCheck.co.uk page 4/12



MOT #4		2020-07-09 10:10
MOT test	number	524904647159
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
MOT #3	2019-04-12 08:46	
MOT test number	855318844651	
Result	✓ Passed	
MOT #2	2018-11-26 16:02	
MOT test number	962740860950	
Result	✓ Passed	
MOT #1	2017-12-01 12:21	
MOT test number	492826396508	
Result	✓ Passed	

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 October
Days left	156
MOT expiry date	4 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report here for the results.

Damage 1


Date
Category
Type

Damage 2

Date

Category

Type



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How ma MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. I report here .	

Plate changes	More info >
See in this check if this MERCEDES-BENZ had different number plates.	
Number of plates	,
Current registration	OK SIE
Plate since	
Current registration	NK SIK
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES-BENZ is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-03-02
Last registration	2024-04-03
Complete history	See info



Registration #1	2015-03-02	7 mi
Registration #2	2017-12-01	31.200 mi
Registration #3	2018-11-26	48.160 mi
Registration #4	2019-04-12	50.788 mi
Registration #5	2020-07-09	55.397 mi
Registration #6	2021-07-05	57.321 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		H.777 es

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	93%
Children	81%
Pedestrian	67%
Safety systems	86%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	2032 mm
Height	1432 mm
Length	4630 mm
Wheel base	2699 mm
Kerb weight	1525 kg
Max. allowed weight	2005 kg

Additional information

Fuel tank capacity	50 I
Fuel delivery	Direct Injection
Number of doors	4
CarChack so uk	nago 12/1:

CarCheck.co.uk page 12/12

Number of seats	5
Number of axles	2
Engine number	65193032710771