



report date: 2024-03-29

## General information

Make	NISSAN
Model	NOTE VISIA
Colour	Grey
Year of manufacture	2014
Top speed	104 mph
0 - 60 mph	13.3 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	80 BHP
Max. torque	110 Nm at 4.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	49.6 mpg
Consumption extra urban	68.9 mpg
Consumption combined	60.1 mpg
CO2 emission	109 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-02-03
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](http://autoonline.co.uk)



MOT history

MOT expiry date	2025-04-12
MOT pass rate	60 %
MOT passed	9
Failed MOT tests	6
Total advice items	29
Total items failed	5

MOT #15	2024-04-04 09:52
MOT test number	613506799228
Result	✓ Passed
Next expiry date	2025-04-12
Advice	Nearside Front Oil leak, but not excessive gearbox end cover (8.4.1 (a) (i))
Advice	Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #14	2023-04-12 09:58
MOT test number	708150567498
Result	✓ Passed

**MOT #13**

2023-04-11 08:38

**MOT test number**

945012046748

**Result****✗ Failed**

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Nearside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- DANGEROUS** Nearside Front Steering rack has excessive free play detected at the steering wheel to the extent that safe steering is affected (steering rack fitted) (2.3 (a) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #12**

2022-04-08 10:21

**MOT test number**

814093952913

**Result****✓ Passed**

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #11**

2022-04-08 10:21

**MOT test number**

828591192414

**Result****✗ Failed**

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))



<b>MOT #10</b>	2021-04-13 08:35
<b>MOT test number</b>	767557139136
<b>Result</b>	✓ Passed
<b>Advice</b>	Engine and under covers fitted

<b>MOT #9</b>	2021-04-12 11:19
<b>MOT test number</b>	512769963570
<b>Result</b>	✗ Failed
<b>Advice</b>	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
<b>MAJOR</b>	Offside Stop lamp(s) not working (4.3.1 (a) (ii))
<b>Advice</b>	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Advice</b>	Engine and under covers fitted
<b>Advice</b>	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
<b>MAJOR</b>	Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

<b>MOT #8</b>	2021-03-24 12:30
<b>MOT test number</b>	825317772541
<b>Result</b>	✓ Passed
<b>Advice</b>	Both front and rear exhaust joints corroded

<b>MOT #7</b>	2021-03-23 16:10
<b>MOT test number</b>	803701449895
<b>Result</b>	✗ Failed
<b>MAJOR</b>	Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
<b>Advice</b>	Both front and rear exhaust joints corroded
<b>Pass with rectification</b>	Offside Headlamp aim too high (4.1.2 (a))
<b>Pass with rectification</b>	Nearside Headlamp aim too high (4.1.2 (a))

**MOT #6** 2021-03-03 10:23**MOT test number** 853761984120**Result** ✗ Failed**MAJOR** Offside Front Anti-roll bar ball joint excessively worn lower ball joint worn (5.3.4 (a) (i))**MAJOR** Boot lid cannot be secured in the closed position boot handle broken (6.2.1 (e))**MAJOR** Offside Front Suspension arm pin or bush excessively worn rear bush worn (5.3.4 (a) (i))**MOT #5** 2019-12-21 09:48**MOT test number** 273132471547**Result** ✓ Passed**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Front bush debonding (5.3.4 (a) (i))**MOT #4** 2019-01-07 11:10**MOT test number** 716037765929**Result** ✓ Passed**MOT #3** 2018-01-09 11:02**MOT test number** 675957069855**Result** ✓ Passed**MOT #2** 2017-01-04 11:15**MOT test number** 435800475268**Result** ✓ Passed**MOT #1** 2017-01-04 10:02**MOT test number** 771306296669**Result** ✗ Failed**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)



Tax & MOT check

X

Untaxed

Tax expired:  
1 April 2024

✓

MOT

Expires:  
12 April 2025

Tax status	Expired at 1 April 2024
Days left	29 days too late
MOT expiry date	12 April 2025
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2020-01-01
Current registration	<b>XXXXXX</b>
Plate since	2020-01-01

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2014-01-13
Last registration	2024-04-04
Complete history	<a href="#">See info</a>



Registration #1	2014-01-13	13 mi
Registration #2	2017-01-04	37.713 mi
Registration #3	2017-01-04	37.713 mi
Registration #4	2018-01-09	49.391 mi
Registration #5	2019-01-07	58.527 mi
Registration #6	2019-12-21	68.207 mi
Registration #7	2020-03-20	70.277 mi
Registration #8	2021-03-03	71.751 mi
Registration #9	2021-03-23	71.764 mi
Registration #10	2022-03-20	75.277 mi
Registration #11	2022-03-20	75.277 mi
Registration #12	2023-03-20	75.277 mi
Registration #13	2023-03-20	75.277 mi
Registration #14	2023-03-20	75.277 mi
Registration #15	2023-03-20	75.277 mi
Registration #16	2023-03-20	75.277 mi
Registration #17	2024-03-20	75.277 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	86%
Children	82%
Pedestrian	58%
Safety systems	70%
Overall rating	78%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1695 mm
Height	1530 mm
Length	4100 mm
Wheel base	2600 mm
Kerb weight	1036 kg
Max. allowed weight	1510 kg

Additional information

Fuel tank capacity	41 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	065236R