



report date: 2024-03-28

General information

|                     |                        |
|---------------------|------------------------|
| Make                | VOLKSWAGEN             |
| Model               | SHARAN SE TDI (115BHP) |
| Colour              | Green                  |
| Year of manufacture | -                      |
| Top speed           | 112 mph                |
| 0 - 60 mph          | 13.7 seconds           |
| Gearbox             | 6 speed Manual         |

Engine & fuel consumption

|                         |                     |
|-------------------------|---------------------|
| Power                   | 115 BHP             |
| Max. torque             | 310 Nm at 1.900 rpm |
| Cylinders               | 4                   |
| Fuel type               | Diesel              |
| Consumption city        | 32.8 mpg            |
| Consumption extra urban | 51.4 mpg            |
| Consumption combined    | 42.8 mpg            |



LABEL UNKNOWN



Internet history

Entry 1

|               |                             |
|---------------|-----------------------------|
| Date          | 2021-06-29                  |
| Pictures      | 12                          |
| Listing price | <a href="#">View report</a> |



source: autotrader.co.uk



## MOT history

|                  |   |
|------------------|---|
| MOT #23          | 2021-02-27 10:37  |
| MOT test number  | 550782935459  |
| Result           | ✓ Passed  |
| Next expiry date | 2022-02-28  |
| Advice           | Front both sides front chassis area covered in underseal    |
| Advice           | Rear Brake pad(s) wearing thin both sides (1.1.13 (a) (ii)) |

|                 |  |
|-----------------|--|
| MOT #22         | 2020-02-27 13:36                                       |
| MOT test number | 244025205842   |
| Result          | ✓ Passed   |
| Advice          | Both sides front chassis areas covered with under seal |

|                 |  |
|-----------------|--|
| MOT #21         | 2020-02-25 13:09   |
| MOT test number | 721920983711   |
| Result          | ✗ Failed   |
| Fail            | Nearside Front Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced jacking point (6.1.1 (c) (i)) |
| Fail            | Nearside Front Macpherson strut top bush or bearing has excessive wear or free play (5.3.4 (a) (i))  |
| Fail            | Offside Front Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced jacking point (6.1.1 (c) (i))  |

|                 |  |
|-----------------|--|
| MOT #20         | 2019-02-14 15:02   |
| MOT test number | 513129560330   |
| Result          | ✓ Passed   |
| Advice          | Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a)) |

|                 |                  |
|-----------------|------------------|
| MOT #19         | 2018-02-15 16:30 |
| MOT test number | 713349037777     |
| Result          | ✓ Passed         |

**Advice**  
(2.5.B.1b)

Nearside Front Macpherson strut has slight movement in the upper support bearing assembly

**MOT #18** 2018-02-15 11:51**MOT test number** 546824774366**Result** ✗ Failed**Advice** Nearside Front Macpherson strut has slight movement in the upper support bearing assembly (2.5.B.1b)**Fail** Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)**Fail** Front Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #17** 2017-02-17 16:27**MOT test number** 774492928390**Result** ✓ Passed**MOT #16** 2017-02-16 15:17**MOT test number** 910501353474**Result** ✗ Failed**Fail** Offside Front Body or chassis has excessive corrosion, seriously affecting its strength within 30cm of the body mountings (6.1.B.2)**Fail** Nearside Front Body or chassis has excessive corrosion, seriously affecting its strength within 30cm of the body mountings (6.1.B.2)**Fail** Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)**MOT #15** 2016-02-11 12:22**MOT test number** 357353250717**Result** ✓ Passed**MOT #14** 2016-02-11 12:22**MOT test number** 859419821502**Result** ✗ Failed**Pass with rectification** Rear Registration plate lamp not working (1.1.C.1d)

**MOT #13** 2015-02-12 12:02**MOT test number** 526533945033**Result** ✓ Passed**Advice** Offside Inner Front Vehicle structure has slight corrosion (6.1.B.2)**Advice** Nearside Inner Front Vehicle structure has slight corrosion (6.1.B.2)**MOT #12** 2014-03-01 11:28**MOT test number** 535450464060**Result** ✓ Passed**MOT #11** 2012-09-20 10:19**MOT test number** 717254962238**Result** ✓ Passed**MOT #10** 2011-10-03 12:48**MOT test number** 149996471208**Result** ✓ Passed**Notice** Surface rust on brake pipes**Notice** Front tyres near 1.6 mm limit**MOT #9** 2010-12-20 14:09**MOT test number** 171454150370**Result** ✓ Passed**Advice** Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Nearside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)

**MOT #8** 2010-12-15 15:29**MOT test number** 852139540348**Result** ✗ Failed**Fail** Offside Rear coil spring incomplete (2.4.C.1a)**Advice** Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Nearside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)**MOT #7** 2009-08-20 15:13**MOT test number** 933012739227**Result** ✓ Passed**Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)**Advice** Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2009-02-19 15:48**MOT test number** 491000059068**Result** ✓ Passed**Advice** Brake pipe slightly corroded (3.6.B.2c)**MOT #5** 2009-02-19 13:57**MOT test number** 992640759041**Result** ✗ Failed**Advice** Brake pipe slightly corroded (3.6.B.2c)**Fail** Brake pipe excessively corroded (3.6.B.2c)

**MOT #4** 2008-02-29 10:53**MOT test number** 382310368053**Result** ✓ Passed**Advice** Front Macpherson strut has slight movement in the upper support bearing assembly (2.5.B.1b)**Advice** Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**MOT #3** 2006-12-05 14:37**MOT test number** 364359436331**Result** ✓ Passed**MOT #2** 2006-12-04 14:57**MOT test number** 790388936324**Result** ✗ Failed**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #1** 2005-12-12 15:46**MOT test number** 772646645386**Result** ✓ Passed





Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |

Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 19,999 |
| Auction value               | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |              |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

|                      |  |
|----------------------|--|
| Number of plates     | 1  |
| Current registration |  <b>YL51DWN</b> |
| Plate since          | 2019-09-29   |
| Current registration |  <b>YL51DWN</b> |
| Plate since          | 2019-09-29   |

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

|                   |          |      |
|-------------------|----------|------|
| Finance company   | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type    | XXXXXXXX | XXXX |
| Agreement term    | XXXXXXXX | XXXX |
| Agreement number  | XXXXXXXX | XXXX |
| Contact info      | XXXXXXXX | XXXX |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 25                       |
| First mileage registration | 2001-12-13               |
| Last registration          | 2021-02-27               |
| Complete history           | <a href="#">See info</a> |



|                  |            |            |
|------------------|------------|------------|
| Registration #1  | 2001-12-13 | 9 mi       |
| Registration #2  | 2005-12-12 | 44.485 mi  |
| Registration #3  | 2006-12-04 | 59.613 mi  |
| Registration #4  | 2006-12-05 | 59.613 mi  |
| Registration #5  | 2008-02-29 | 77.839 mi  |
| Registration #6  | 2009-02-19 | 92.623 mi  |
| Registration #7  | 2009-02-19 | 92.623 mi  |
| Registration #8  | 2009-08-20 | 100.159 mi |
| Registration #9  | 2010-12-15 | 115.216 mi |
| Registration #10 | 2010-12-20 | 115.321 mi |
| Registration #11 | 2011-10-03 | 127.051 mi |
| Registration #12 | 2012-09-20 | 134.629 mi |
| Registration #13 | 2014-03-01 | 139.008 mi |
| Registration #14 | 2015-03-01 | 151.337 mi |
| Registration #15 | 2015-03-01 | 151.337 mi |
| Registration #16 | 2015-03-01 | 151.337 mi |
| Registration #17 | 2015-03-01 | 151.337 mi |
| Registration #18 | 2015-03-01 | 151.337 mi |
| Registration #19 | 2015-03-01 | 151.337 mi |
| Registration #20 | 2015-03-01 | 151.337 mi |
| Registration #21 | 2015-03-01 | 151.337 mi |
| Registration #22 | 2015-03-01 | 151.337 mi |
| Registration #23 | 2015-03-01 | 151.337 mi |
| Registration #24 | 2015-03-01 | 151.337 mi |
| Registration #25 | 2015-03-01 | 151.337 mi |



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

|       |                  |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

|            |         |
|------------|---------|
| Width      | 1810 mm |
| Height     | 1730 mm |
| Length     | 4634 mm |
| Wheel base | 2841 mm |

Additional information

|                    |                  |
|--------------------|------------------|
| Fuel tank capacity | 70 l             |
| Fuel delivery      | Direct Injection |
| Number of doors    | 5                |
| Number of axles    | 2                |
| Engine number      | AUY042518        |