





report date: 2024-03-29

General information

Make	FORD
Model	FUSION FUSION +
Colour	Blue
Year of manufacture	2009
Top speed	103 mph
0 - 60 mph	14.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	79 BHP
Max. torque	124 Nm at 3.500 rpm
Engine capacity	1.388 сс
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	49.6 mpg
Consumption combined	41.5 mpg
CO2 emission	149 g/km
CO2 label	F



CarCheck.co.uk page 1/13



report date: 2024-03-29

Internet history

Entry 1

Date 2021-12-30

Pictures 2

Listing price <u>View report</u>





source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

MOT history	M	OT	history
-------------	---	----	---------

MOT expiry date	2025-02-14
MOT pass rate	79 %
MOT passed	15
Failed MOT tests	4
Total advice items	2
Total items failed	8

MOT #19	2024-01-29 17:06
MOT test number	243344278786
Result	✓ Passed
Next expiry date	2025-02-14

MOT #18	2024-01-29 17:06
MOT test number	342187802432
Result	★ Failed
Pass with rectification	Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #17		2023-01-21 13:02
MOT test number		795694606802
Result		✓ Passed
MOT #16		2023-01-21 13:02
MOT test number		475387515113
Result		X Failed
Pass with rectification	Nearside Headlamp aim too high (4.1.2 (a))	
Pass with rectification	Nearside Stop lamp(s) not working (4.3.1 (a) (ii))	
Pass with rectification	Offside Headlamp aim too high (4.1.2 (a))	

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT #15 2022-02-15 15:37

MOT test number 770605548158

Result ✓ Passed

MOT #14 2022-02-15 09:55

MOT test number 723157394744

Result X Failed

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Fail Service brake efficiency below requirements (1.2.2 (a) (i))

Fail Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

Fail Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))

MOT #13 2021-12-08 15:56

MOT test number 421632287094

Result ✓ Passed

Advice Nearside Rear Tyre slightly damaged/cracking or perishing cracking between treads (5.2.3 (d) (ii))

MOT #12 2021-01-25 11:11

MOT test number 497853767596

MOT #11 2021-01-25 11:11

MOT test number 264286207924

Result × Failed

Pass with rectification Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #10 2020-01-16 10:40

MOT test number 534782564716

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT test number Result MOT #8 2018-01-18 0	1484 assed
·	issed
MOT #8 2018-01-18 (
MOT #8 2018-01-18 0	
	8:59
MOT test number 75231549	7564
Result	assed
MOT #7 2017-01-09 1	L2:45
MOT test number 59675522	1552
Result VPa	assed
MOT #6 2016-01-20 1	
MOT test number 43361092	2165
Result VP	assed
MOT #5 2015-01-26 1	
MOT test number 13778622	
Result	assed
MOT #4 2014-09-04 1	12:00
MOT test number 27715704	
Result J Pa	assed
MOT #3 2013-09-06 1	L2:26
MOT test number 35688984	3280
	3280 assed
	assed
Result VPa	assed 15:31

CarCheck.co.uk page 5/13



MOT #1

AG09EGU

report date: 2024-03-29

2012-06-28 09:05

MOT test number 138060182157

CarCheck.co.uk page 6/13



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 February
Days left	277
MOT expiry date	14 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-29

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	



Extra FORD salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

AG09EGU

report date: 2024-03-29

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report here. More info >

More info >

CarCheck.co.uk page 10/13



report date: 2024-03-29

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2009-08-01
Last registration	2024-01-29
Complete history	See info



Registration #1	2009-08-01	22 mi
Registration #2	2012-06-28	16.535 mi
Registration #3	2012-09-19	17.689 mi
Registration #4	2013-09-06	21.817 mi
Registration #5	2014-09-04	25.081 mi
Registration #6	2015-01-26	26.179 mi
Registration #7	2016-01-20	30.570 mi
Registration #8	2017-01-09	33.892 mi
Registration #9	2018-01-18	36.951 mi
Registration #10	2019-01-15	39.314 mi
Registration #11	2020-01-16	42.498 mi
Registration #12		71.777 es
Registration #13		71.777 es
Registration #14		71.777 es
Registration #15		11.777 es
Registration #16		71.777 es
Registration #17		11.777 es
Registration #18		71.777 es
Registration #19		11.777 es
Registration #20		71.777 es
Registration #21		11.777 esi

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-29

Car features

50225	Air conditioning
50295	
50482	
60501	
50566	
60567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1952 mm
Height	1534 mm
Length	4020 mm
Wheel base	2485 mm
Kerb weight	1200 kg
Max. allowed weight	1605 kg

Additional information

Fuel tank capacity	45 I	
Fuel delivery	Multi-Point Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 13/13