





report date: 2024-03-28

#### General information

Make	FORD
Model	C-MAX ZETEC 100
Colour	Blue
Year of manufacture	2009
Top speed	107 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	100 BHP
Max. torque	145 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.7 mpg
Consumption extra urban	49.6 mpg
Consumption combined	40.9 mpg
CO2 emission	164 g/km
CO2 label	G



CarCheck.co.uk page 1/12



report date: 2024-03-28

## Internet history

#### Entry 2

Date 2021-01-29

Pictures 1

Listing price <u>View report</u>




#### source: autoonline.co.uk

#### Entry 1


Date	2021-01-21
Pictures	51

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/12



report date: 2024-03-28

## **MOT** history

MOT expiry date	2024-06-05
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	9
Total items failed	6

MOT #15	2023-06-06 09:45
MOT test number	552140420481
Result	✓ Passed
Next expiry date	2024-06-05
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (i	i))

MOT #14	2022-11-25 17:42
MOT test number	254230611873
Result	✓ Passed

MOT #13	2022-11-25 17:42

**MOT test number** 349529632708

**Result** X Failed

**Pass with rectification** Nearside Rear Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))

**Pass with rectification** Offside Rear Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #12		2022-01-12 13:09
MOT test	number	656766856803
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #11	2021-02-04 12:53
MOT test number	218885352918
Result	✓ Passed
MOT #10	2021-02-04 09:01
MOT test number	937885633659
Result	<b>X</b> Failed
Fail Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))	

MOT #9	2019-12-14 09:42
MOT test number	980706848332
Result	✓ Passed
MOT #8	2018-12-21 14:17
MOT test number	328371692595
Result	<b>✓</b> Passed
Advice Brake pad(s) wearing thin both rear sets. (1.1.13 (a) (ii))	

MOT #7	2017-12-19 11:18
MOT test number	895310998046
Result	<b>✓</b> Passed

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #6

MOT test number

588465307699

Result

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT test number

Result

Pass with rectification

Nearside Front Headlamp aim too low (1.8)

Advice

Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Pass with rectification

Offside Rear Stop lamp not working (1.2.1b)

Pass with rectification

Offside Front Wheel nut(s) missing (4.2.A.1e)

MOT #4

MOT test number

474993133407

Result

Advice Brake hydraulic reservoir fluid close to minimum level (3.6.G.1b)

2014-12-20 14:03 **MOT** #3 **MOT** test number 946404654334 Result ✓ Passed **MOT** #2 2013-12-16 14:03 **MOT** test number 259730653394 Result ✓ Passed **MOT #1** 2012-12-20 13:56 **MOT** test number 765935952342 Result ✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 October
Days left	155
MOT expiry date	5 June 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

#### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

# Owner history

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report	
***************************************	
********	
***************************************	
	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	
Current registration	NK NY
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

#### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

## Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-12-22
Last registration	2023-06-06
Complete history	See info



Registration #1	2009-12-22	20 mi
Registration #2	2012-12-20	12.320 mi
Registration #3	2013-12-16	19.698 mi
Registration #4	2014-12-20	26.804 mi
Registration #5	2015-12-12	31.552 mi
Registration #6	2016-12-06	38.034 mi
Registration #7	2016-12-06	38.034 mi
Registration #8	2017-12-19	44.501 mi
Registration #9	2018-12-21	50.044 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 au

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

## Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	2022 mm
Height	1595 mm
Length	4333 mm
Wheel base	2640 mm
Kerb weight	1372 kg
Max. allowed weight	1855 kg

#### Additional information

Fuel tank capacity	53 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/12

Number of axles 2

**Engine number** 9G49373